

ASS. REC. BY:

REF:

CS/E0119022074/USF301

Special Instruction:

Surveyor: MARCUS

ASSIGNMENT (Office)

From (Person): Jacelyn Foo

of

EG1

Date/Time:

13/12/19 @ 5-30h

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To inspect Vehicle No:

G6J 5745A

Insured:

YP 4750M

at Workshop m/s

Liu's Brother

Tel:

67411730

of

No. 1 Kaki Bukit Ave 6 #01-01 Auto Bay @ K.

Policy No:

Claim No:

CDMCA19007355

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

12/12/19

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

16/12/19

Person Contacted:

Susan

Vehicle:

IN/OUT

Date/Time	Action/Instruction
	G6J 5745A - X
	YP 4750M - X

ASSIGNMENT

From: Date: Vch No: 63J 5745A Yr Regn: 6, 19
 Estimated Cost: Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 OD TP WS / TP RES / OD RES / EVA / INV / MV Truck / Trailer or Car /
 To Inspect Vehicle No: 63J 5745A Make: FIAT DO 610 C.C. 1598
 at Workshop m/s 11-3 40 Colour: white / blue A/C: Insured / Std / NI / NA
 of Sp. Reading 9907 T/Radio: Insured / Std / NI / NA
 Insured: Eng/No:
 Policy No: C/No: ZFA26300006N 23163
 Claims No: Gen. Cond: Good / Fair / Poor / Burnt
 Sum Insured: Excess: Steering: In order / Jammed / Leaked / Burnt or
 (Client's Record) Brake: In order / Jammed / Leaked / Burnt or
 Make of Veh: Modi: Nil / S/Rim / STD A/Rim or

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 18
 IDAC Accident Rpt: Consistent? : Yes or No
 GIA / PR Seen: Consistent? : Yes or No
 Est. Repairs: 24 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS LT A24208
 Date: Person Contacted: Vehicle: IN / OUT

Tyre Size: F: 195/60 R16
 R:
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or
 Front 6 mm Rear 6 mm
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. D.O.I. 13/12/19
 Survey held at 16/12/19
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
 Rear 6.4
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

net 33792

21/2/20 1/5 \$27,000 conf. ind with Susan.
 CF 52,974.40 Red - 66%

RECEIVED 21 FEB 2020

Date/Time, File Pass to?

21/02/20

1) Typist

Date/Time, File Return to?

2)



Prel. Report



Final Report

Days Of Repair: 24

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Add Fee:



Site Insp (\$

) S + RS SI



Interview (\$

) Photos



Tech. Invs (\$

) Others



Weekend (\$

)

Report Format :

Lump Sum / I.B.I: (\$ 21,000 - 415)

TOTAL

361

Summer Lee (LKK Auto)

From: Jacelyn Foo <jacelyn.foo@ergo.com.sg>
Sent: Friday, 13 December, 2019 5:30 PM
To: admin-d@lkkauto.com; admin-a@lkkauto.com; Meikwan@lkkauto.com
Cc: Susan Low; Ivy Yong; Pauline Soh
Subject: RE: ERGO Claims Ref: CDMCG19002355 | Request for 3rd party claims survey
GBJ5745A Claims against YP4250M
Attachments: GBJ5745A Serach.pdf; GBJ5745A191212.pdf

Data Classification: Confidential, C3

Hi LKK,

Please conduct this survey request.

(Note: Survey vehicle only, LOD will be handled by Ergo)

Kindly inform us if you are not able to attend it.

***** NOTE:** Please assist to quote our claims ref no. as the subject matter, when forwarding the Preliminary Reports / Survey Reports.

Thank you.

Warmest Regards,
Jacelyn Foo
ERGO Insurance Pte. Ltd.

5 Temasek Boulevard, #04-05 Suntec Tower Five
Singapore 038985
DID: +65 6829 9258
jacelyn.foo@ergo.com.sg

ERGO

www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

EMAIL DISCLAIMER

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message. Any views expressed in this email communication are those of the individual sender. ERGO Insurance Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference. ERGO Insurance Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.



Disclaimer: This message and its attachments are confidential, intended only for the named addressee, and may be privileged. If you are not the intended recipient, you should not disclose, distribute, copy or use this communication. If you are not the intended recipient, please notify the sender by return email and delete this message. By opening any attachment to this message, you agree to accept the risk that it may contain a virus or damaging code, and you agree that ERGO Insurance Pte Ltd. will not be liable for any loss or damage thereby caused.

From: Susan Low [mailto:liusbro@gmail.com]
Sent: Friday, December 13, 2019 5:26 PM
To: Jacelyn Foo

Subject: Re: ERGO Claims Ref: CDMCG19002355 | Request for 3rd party claims survey GBJ5745A Claims against YP4250M

We did liked to chose as follow

LKK Auto Consultants Pte Ltd

Kindly arrange

Thank.

Best Regards,

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 67411730 Fax: 67445746

On Friday, 13 December 2019, 5:16:28 pm SGT, Jacelyn Foo <jacelyn.foo@ergo.com.sg> wrote:

Data Classification: Confidential, C3

Dear Susan,

Please refer to our list of surveyors :

1	AIS	Automobile Inspection Services Pte Ltd
2	FTA	FormTeam Consultancy Pte Ltd
3	IAS	Infiniti Appraisal Service
4	JPK	JP Knights Pte Ltd
5	LBS	L.B.S Auto Consultants Pte Ltd
6	LKK	LKK Auto Consultants Pte Ltd
7	PS	Priority Services
8	VAC	Vicom Ltd
9	AJAX	AJAX Inspection Services Pte Ltd
10	QRM	Quantum Risk Management (S) Pte Ltd
11	AA	Appraisal Associate

Accident on 12/12/2019 Along TPE (PIE)

Involving GBJ5745A and YP4250M

We refer to the above accident and 3rd party claims.

We hereby write to request of 3rd party claims pre-repair inspection for our client's vehicle.

Please let us have your single joint expert motor surveyors list (SJE) to conduct a pre-repair survey of the damage to our client's vehicle jointly with our client/our motor workshop at No. 1 Kaki Bukit Avenue 6 #01-01 AutoBay @ Kaki Bukit Singapore 417883 as soon as possible.

Kindly arrange.

Thank you.

Best Regard!

Susan Low
M/s Liu's Brother Auto Engineering Workshop
No. 1 Kaki Bukit Avenue 6 #01-01
AutoBay @ Kaki Bukit
Singapore 417883
Tel: 6741 1730
Fax: 6744 5746

Date of Survey:- _____

Name of Authorise Surveyor:- _____

Surveyor Email: _____

Remark :- _____

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 12/12/2019 10:38
 Date Of Accident 12/12/2019 07:30
 Exact Location Of Accident ALONG TPE (PIE)
 Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number GBJ5745A
Insured/Policyholder
 Name Of Registered Owner GOLDBELL LEASING PTE LTD
 Co Reg No 199001196N
 Email Address NOEMAIL
 Mobile Phone No
 Alternative Phone No OFFICE-64942833

Vehicle Particulars

Manufacturer FIAT
 Model DOBLO SX 1.6MJ E6 GLAZED

Exact Purpose for which vehicle was being used at time of accident

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY
 Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company MS FIRST CAPITAL INSURANCE LTD
 Type Of Coverage THIRD PARTY
 Fleet Policy YES
 Policy Number D-19093298MFCV
 Cover Note Number

Driver

Name of Driver SHANMUGAM MURUGAP ANDIYAN
 Passport No/FIN G8260435P
 Date Of Birth 23/04/1988
 Occupation OUTDOOR
 Date Of Driving Pass 24/05/2016
 Driving Experience 3 YEARS AND 6 MONTHS
 Gender MALE
 Mobile Number (LOCAL) +65-91363695
 Fax Number
 Contact Number
 Email Address NOEMAIL

Address	NIL
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - LESSEE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	CHAIN COLLISION
Weather Conditions	CLEAR
Road Surface	WET

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles (including own vehicle) involved in the accident	8
Was any body injured in the Accident?	YES
Was any injured conveyed to hospital by ambulance?	YES
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	YES
If Yes, Please state which Police Station	
Police Station Name	HOUGANG NEIGHBOURHOOD POLICE CENTRE
Police Station Address	ROAD: 60 HOUGANG AVE 9 , POSTCODE: 538775 , COUNTRY: SINGAPORE
Police Station Contact	TEL NO: 1800-4890999 - FAX NO: 63128989
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO POLICE REPORT NO. T/20191212/2140

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	SD CARD WITH TRAFFIC POLICE
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLV7037R
Vehicle Make/Model/Colour	
Details Of Properties	
Vehicle Category	PRIVATE CAR
Name of Driver	CHRISTOPHER
NRIC/Passport Number	
Contact Number	97671903
Address	
Postcode	
Insurance Company Name	

Nature Of Damage

No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SLJ5849R
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver HATHAN
NRIC/Passport Number
Contact Number 96736144
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 3

Vehicle Registration Number GY3652J
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver LING
NRIC/Passport Number
Contact Number 88215280
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number SGX4895Z
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver CHUA KOON TIONG
NRIC/Passport Number
Contact Number 96681094
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 5

Vehicle Registration Number SJS6305M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver TERENCE
NRIC/Passport Number
Contact Number 96392461

Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 6

Vehicle Registration Number SKQ5830T
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver KHAIRUL
NRIC/Passport Number
Contact Number 91822949
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 7

Vehicle Registration Number YP4250M
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category COMMERCIAL VEHICLE
Name of Driver TAN KIM POH
NRIC/Passport Number
Contact Number 96302311
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

DETAILS OF INJURED PERSON 1

Name UNKNOWN
Approximate Age
Injuries Sustain
Injured person in which vehicle?
Were seat belts worn?
Was this injured conveyed to hospital by ambulance?
Address
Postcode

SKETCH PLAN**IMPORTANT NOTICE**

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **rescind policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation**.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes").
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes;
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims;
- (e) the information so collected under (a) above may be shared / disclosed
 - (i) to all Insurers and, or any other third parties that assist in evaluating, investigating, controlling, or managing fraud, regulations, law enforcement and government agencies as reasonably required for the purposes stated; or
 - (ii) for complying with requirements under any regulations, laws or court orders.


Policyholder's Signature
(Date & Time)

Insurer's Signature
(If driver is not the policyholder)
(Date & Time)

Reporting Centre Personnel's Signature
Name
NRIC/ID No.

Sketch Plan #2

SKETCH PLAN



- A SLV 7037R
B SLJ 5849R
C GY 3652J
D SGX 4895Z
E SJS 6305M
F SKQ 5830T
G GBJ 5745A
H YP 4250M

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

REFER TO POLICE REPORT NO. T/20191212/2140

DECLARATION

I/We declare the foregoing particulars are true in every respect

 Date & Time

Driver's Signature
(If driver is not the policyholder)
Date & Time

Reporting Centre Personnel's Signature
Name _____
idno_706_40

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	196N
Vehicle Details	
Vehicle No.:	GBJ5745A
Vehicle to be Exported:	No
Intended Deregistration Date:	26 Dec 2019
Vehicle Make:	FIAT
Vehicle Model:	NEW DOBLO SX 1.6MJ E6 GLAZED
Primary Colour:	White
Manufacturing Year:	2019
Engine No.:	263A80008745950
Chassis No.:	ZFA26300006N23163
Maximum Power Output:	-
Open Market Value:	\$19,739.00
Original Registration Date:	07 Jun 2019
First Registration Date:	07 Jun 2019
Transfer Count:	0
Actual ARF Paid:	\$987.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Expiry Date:	06 Jun 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
PQP Paid:	\$25,626.00
COE Rebate Amount:	\$24,208.00
Total Rebate Amount:	\$24,208.00

The information contained herein is correct as at 26 Dec 2019

OK

New Cars

Used Cars

Rental Cars

Sell My Car

Directory

Products

Insurance

Articles

For



Here is a car loan that's got
our green light!

Post an Advertisement

Sell it yourself! Advertise it at just

\$58 until it's SOLD!

[Post an Ad](#)
[Advertiser Login](#)
[Ways of Selling](#)

Mercedes-Benz CLA180 Shooting Brake Urban On Sales.



3 Years Or 100,000 Km
Warranty, Fully Maintained By
C&C. High Trade-In.
Speedo Motoring StarAd.

HIN LUNG AUTO
Ho Bee Group

One Stop Car Hub
Finance, Insurance, Works!
New and Used Cars

[Browse by Category](#)
[Sort by Date Posted](#)

1 vehicles

[Advanced Search](#)

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
Search Selection	fiat doblo		Any	Any	2019	Any	Any	Any
	Fiat Doblo	1.6M Multijet Glaze	\$61,800	\$6,490 /yr	01-Jul-2019	1,598 cc	-	Van
	Fuel Type: Diesel 5 Years/160000 Warranty. 3 Times Servicing With Parts And Labour Included. Powerful Engine And Economical Model. Good Fuel Efficiency. Call Us Now And Find Out More On Our Package.							
	Ezy-1 Pte Ltd							
	Posted: 20-Dec-2019 Tags: 2019 Fiat Doblo, 2019 fiat doblo, Fiat Doblo, fiat doblo, Fiat, Doblo, doblo, Used Fiat							

Save this search criteria, to get email alerts whenever a match is found.

Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type
------	-------	-------	--------------	----------	---------	---------	----------

For old advertisements, view [Expired ads](#)

[Home](#) | [New Cars](#) | [Used Cars](#) | [Sell My Car](#) | [Directory](#) | [Products](#) | [Insurance](#) | [Article](#) | [Forum](#) | [Resources](#)

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car br insurance. Find buy used fiat doblo, fiat doblo Singapore, used fiat doblo Singapore, used fiat doblo, used vehicles Singapore or even buy used fiat doblo Singapore. We comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partn for Singapore jobs, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE re

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but ne that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of thi

Follow sgCarMart.com

[About Us](#) | [Careers](#) | [Contact Us](#) | [Sitemap](#) | [Terms of Service](#) | [Privacy Policy](#) | [Personal Data Protection Statement](#)

©2004-2019 sgCarMart. All rights reserved.

Compare

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBJ5745A191212

Estimate

Customer

Page 04 - 01

Name: ERGO Insurance Pte Ltd

Date: 13-12-19

Address: Motor Claims Department

Vehicle No: GBJ5745A

5 Temasek Boulevard #04-01

Model/Make: Fiat New Doblo

Suntec Tower Five

Singapore 038985

SX 1.6 MJE 6 Glazed

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Bumper <i>Dis</i>	\$ 627.00	✓
2	Bumper Clips 1 set <i>rec</i>	\$ 65.00	✓
3	Bumper Reflector 02 pcs (@ \$598.60) <i>N/S 1/5</i>	\$ 197.20	1 pc
4	Bumper Reinforcement <i>bet</i>	\$ 475.30	✓
5	End Panel Outer <i>Body</i>	\$ 430.00	✓
6	End Panel Inner <i>Body</i>	\$ 295.00	✓
7	End Panel Top Garnish <i>Delene</i> 35.00	\$ 347.70	✓
8	End Panel Top Garnish Clips 1 set <i>11</i>	\$ 58.00	X
9	Bumper Reverse Sensor 1 set <i>shut</i>	\$ 220.00	SN 2005.2
10	Bumper <i>retains</i> 2 pcs (@ \$5283.70) <i>N/S bet 1/5</i>	\$ 567.40	1 pc
11	Spare Tyre Carrier <i>11</i>	\$ 590.00	X
12	Floor Panel <i>examined/suc</i> 2350.00	\$ 2,450.00	✓
13	Floor Panel <i>Top mat</i> <i>Dis</i>	\$ 179.80	✓
14	Tail Lamp 02 pcs (@ \$462.70) <i>N/S 2/20 0/5 crn</i>	\$ 925.40	✓
15	Rear Rh Tailgate <i>Body</i>	\$ 1,895.90	✓
16	Tailgate Weatherstrip <i>To in</i>	\$ 237.00	✓
17	Tailgate Inner Trim Board <i>ac/cut</i>	\$ 297.80	✓
18	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 127.20	X
19	Tailgate Lock Top <i>11</i>	\$ 189.30	X
20	Tailgate Lock <i>bottom</i> <i>SM</i>	\$ 192.90	✓
21	Tailgate Hinge 02 pcs (@ 166.30) <i>11</i>	\$ 332.60	X
22	Tailgate Outer Garnish <i>crn</i>	\$ 279.00	✓
23	Tailgate Inner Handle <i>11</i>	\$ 189.40	X
24	Tailgate "Fiat Logo" Emblem <i>NE</i>	\$ 87.80	X
25	Tailgate "Professional" Emblem <i>NE</i>	\$ 163.50	X
26	Tailgate "6 PAX" Sticker <i>rec</i>	\$ 12.00	SN 10 S.N
27	Tailgate Glass Sealant <i>rec</i>	\$ 80.00	SN 40 S.N
28	Tailgate "70 KM/H" Sticker <i>rec</i> 605.00 ✓ <i>Rear w. ad screen RH</i> <i>shut</i>	\$ 15.00	SN 10 S.N
29	Rear Lh Tailgate <i>Body</i>	\$ 2,156.30	✓
30	Tailgate Weatherstrip <i>To in</i>	\$ 279.00	✓
31	Tailgate Inner Trim Board <i>To in</i>	\$ 384.90	✓
32	Tailgate Inner Trim Board Clips 1 set <i>11</i>	\$ 164.50	SN X
33	Tailgate Lock <i>Top LHM</i>	\$ 331.00	✓
34	Tailgate Hinge 02 pcs (@ 166.30) <i>inner bet</i>	\$ 332.60	1 pc
35	Tailgate Outer Handle <i>crn</i> 488.20	\$ 556.40	✓
C/F Balance -->		\$ 15,731.90	

not allowed
2/5
27,000
24.12.19



M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBJ5745A191212

Estimate

Customer	Page 04 - 02
Name: ERGO Insurance Pte Ltd	Date: 13-12-19
Address: Motor Claims Department	Vehicle No: GBJ5745A
5 Temasek Boulevard #04-01	Model/Make: Fiat New Doblo
Suntec Tower Five Singapore 038985	SX 1.6 MJE 6 Glazed

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance -->	\$ 15,731.90	
36	Rear Lh Tailgate Outer Handle Garnish <i>C/R</i>	\$ 369.80	
37	Tailgate Inner Handle <i>11</i>	\$ 189.40	X
38	Tailgate Number Plate Outer Garnish <i>11</i>	\$ 310.60	X
39	Tailgate Number Plate Lamp 02 pcs (@\$51.50) <i>11</i>	\$ 103.00	X
40	Tailgate Number Plate & Base <i>bet</i>	\$ 48.00	SN 40 S.N
41	Tailgate Windscreen Glass <i>shotted 681.20</i>	\$ 841.50	
42	Tailgate Glass Sealant <i>new</i>	\$ 80.00	SN 40 S.N
43	Tailgate Wiper Motor <i>C/R/3m</i>	\$ 428.00	
44	Tailgate Wiper arm <i>bet</i>	\$ 165.30	
45	Tailgate Wiper Blade <i>7m</i>	\$ 98.00	
46	Tail Lamp Panel <i>body no</i>	\$ 989.30	
47	Fender (Body Panel) <i>body no / 3m</i>	\$ 2,350.00	
48	Fender Cowling <i>2011 266.40</i>	\$ 316.00	
	"Corporate" Advertisement Sticker	\$ 1,200.00	
	To check all wiring & electrical component for proper function	\$ 180.00	
	Remove and refix rear 2 tailgate components & wiper mechanism	\$ 180.00	
	Remove and refix rear bumper reverse sensor	\$ 100.00	
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 2,500.00	
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	
	Remove & reinstall Tailgate 2 Glass to facilitate repairs	\$ 280.00	
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 180.00	
49	Front Bonnet <i>983.43</i>	\$ 1,170.00	
50	Bonnet Hinges 02 Pcs (@\$135.00) <i>3m</i>	\$ 270.00	X
51	Bonnet Insulator <i>11</i>	\$ 97.30	X
52	Bonnet Insulator Clips (1 set) <i>11</i>	\$ 50.00	X
53	Bonnet Rubber Beading 02 pcs (@ \$98.40) <i>11</i>	\$ 196.80	X
54	Bonnet Inner Lock <i>1w1</i>	\$ 145.00	X
55	Bonnet Sponge <i>NS</i>	\$ 241.80	X
56	Bonnet Sponge Clips 1 set <i>NS</i>	\$ 80.00	SN X
57	Fender 02 pcs (@ \$5780.00) <i>2</i>	\$ 1,560.00	X
58	Fender Cowling 02 pcs (@ \$5466.00) <i>11</i>	\$ 932.00	X
59	Fender Cowling Clips Lh & Rh 2 sets (@ \$560.00 SN) <i>11</i>	\$ 120.00	X
60	Fender Cover "Black" 02 pcs (@ \$5640.00) <i>11</i>	\$ 1,280.00	X
	C/F Balance -->	\$ 34,583.70	



M/s Liu's Brother Auto Engrg Wks

19064.83

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917931 . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbros@gmail.com

Invoice/Ref No: GBJ5745A191212

Estimate

Customer

Page 04 - 03

Name: ERGO Insurance Pte Ltd

Date: 13-12-19

Address: Motor Claims Department

Vehicle No: GBJ5745A

5 Temasek Boulevard #04-01

Model/Make: Fiat New Doblo

Suntec Tower Five

Singapore 038985

SX 1.6 MJE 6 Glazed

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance -->	\$ 34,583.70	
61	Front Head Lamp 02 pcs (@ \$5862.40)	\$ 1,724.80	
62	Head Lamp Panel 02 pcs (@ \$988.70)	\$ 1,977.40	
63	Support Panel Centre 665.00	\$ 790.00	
64	Bumper 1092.00	\$ 1,245.50	
65	Bumper Clips 1 set	\$ 58.00	
66	Bumper Reinforcement 715.00	\$ 752.00	
67	Bumper Lower Grille 766	\$ 685.00	
68	Bumper Lower Grille Clips 1 set	\$ 65.00	
69	Bumper retainers 02 pcs (@ \$171.80) 139.X2=278	\$ 343.60	
70	Bumper Fog Lamp Cover 02 pcs (@ \$197.60)	\$ 395.20	
71	Bumper Sponge	\$ 117.60	
72	Bumper Towing Cover 45	\$ 105.00	
73	Grille	\$ 484.70	
74	Grille "Fiat Logo" Motif	\$ 142.10	
75	Diesel Pump	\$ 1,370.00	
76	"Corporate" Advertisement & Artwork	\$ 300.00	
77	Wiper Tank	\$ 280.00	
78	Inter Cooler 1850	\$ 3,640.00	
79	Inter Cooler Cowling	\$ 435.00	
80	Inter Cooler Clips 1 set	\$ 35.00	
81	Aircon Condenser	\$ 1,278.00	
82	Air Con Condensor Cowling	\$ 285.00	
83	Radiator	\$ 854.30	
84	Radiator Fan Motor	\$	
85	Radiator Fan Cowling Completed > complete-1033	\$ 1,175.00	
86	Radiator Top Hose	\$ 2,017.80	
87	Radiator Spare Tank	\$ 773.50	
88	Radiator Hose Top	\$ 142.80	
89	Radiator Hose Lower	\$ 195.70	
90	Radiator Coolant 1 bottle 102	\$ 45.00	
91	ABS Master Pump	\$ 4,270.00	
92	TURBO	\$ 4,856.30	
93	Engine Lower Cover	\$ 975.00	
94	Engine Mounting 1 set	\$ 1,790.00	
95	Engine Top Cover	\$ 890.00	
	C/F Balance -->	\$69,456.60	

p-29945.23

102
2695070

M/s Liu's Brother Auto Engrg Wks

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 53291793J . Tel: 6741-1730 / 731 . Fax: 6744-5746. Email: liusbro@gmail.com

Invoice/Ref No: GBJ5745A191212

Estimate

Customer

Page 04 - 04

Name: ERGO Insurance Pte Ltd

Date: 13-12-19

Address: Motor Claims Department

Vehicle No: GBJ5745A

5 Temasek Boulevard #04-01

Model/Make: Fiat New Doblo

Suntec Tower Five Singapore 038985

SX 1.6 MJE 6 Glazed

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
	B/F Balance -->	\$69,456.60	
96	Number Plate Garnish	\$ 387.00	605.00
97	Number Plate and Base	\$ 48.00	405.00
98	Exhaust Sensor	\$ 610.00	X
99	Exhaust Heat Shield	\$ 365.80	X
100	Exhaust Heater	\$ 317.20	X
101	Battery	\$ 280.00	X
102	Battery Base	\$ 385.00	X
103	Air Cleaner Completed	\$ 955.90	X
104	Air Cleaner Hose	\$ 361.80	X
105	Horn Unit	\$ 182.10	X
	"Corporate" Advertisement Sticker	\$ 800.00	X
	To check all wiring & electrical component for proper function	\$ 180.00	-
	Remove and refix rear 2 tailgate components & wiper mechanism	\$ 180.00	X
	Remove and replace condenser including refill gas	\$ 100.00	-
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc.	\$ 2,500.00	-
	To putty & spray painting & including touch up paint on accident affected	\$ 1,800.00	-
	Remove & reinstall Tailgate 2 Glass to facilitate repairs	\$ 280.00	X
	To apply Rust Proofing, reseal tuff-coating treatment on accident area	\$ 180.00	-

Total Parts & Labour of estimate for damaged vehicle

\$ 79,369.40

79,974.40

Total amount in Lump Sum Basis for repaired vehicle

SDLS:



M/s Liu's Brother Auto Engrg Wks

79596.40

LOS Auto Consultants hence notify the Repairer of the following:

- To return before/after spray painting
- To replace damaged part(s) during repairs
- Parts used are subject to confirmation
- This quotation is on a "Without Prejudice" basis
- No legal action is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-26950.70
 S.W-1570.00
 L-5560.00
 34080.7
 27264.50

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	21 Feb 2020 15:25 Edit Reg		13 Dec 2019 00:00 Edit Adj Rpt	S\$27,000.00 Edit Estimates	S\$27,000.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured: -, Co. Reg. No.: -									
Main Claimant: GOLDBELL LEASING PTE LTD , Co. Reg. No.: 199001196N									
Vehicle Reg. No.: GBJ5745A		Date of Loss: 12/12/2019 07:00 - :59 [6 Months and 5 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP		Policy/Cover Note No.:							
Vehicle Reg. No. (Insured): YP4250M		Policy No. (Claimant):							
		Excess:							
Repairer: Liu's Brother Auto Engineering Workshop (HQ) BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO BAY @ KAKI BUKIT, 417883 Kaki Bukit - Tel:									
Handling Insurer: ERGO Insurance Pte. Ltd. (HQ) - Tel: 6829 9199									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 26/12/2019]									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBJ5745A
 [YP4250M]
 TP
 GOLDBELL LEASING PTE LTD
 Dec 12 2019 7:00AM
 [-]
 Liu's Brother Auto Engineering Workshop

Upload Documents		Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images						3 per page			
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)					Thumbnail	Print	
1	21/02/20 15:33	General View					Load JPG		
2	21/02/20 15:33	General View					Load JPG		
3	21/02/20 15:33	General View					Load JPG		
4	21/02/20 15:33	General View					Load JPG		
5	21/02/20 15:33	General View					Load JPG		
6	21/02/20 15:33	General View					Load JPG		
7	21/02/20 15:33	General View					Load JPG		
8	21/02/20 15:33	General View					Load JPG		
9	21/02/20 15:33	General View					Load JPG		
10	21/02/20 15:33	General View					Load JPG		
11	21/02/20 15:33	General View					Load JPG		
12	21/02/20 15:33	General View					Load JPG		
13	21/02/20 15:33	General View					Load JPG		
14	21/02/20 15:33	General View					Load JPG		
15	21/02/20 15:33	General View					Load JPG		
16	21/02/20 15:33	General View					Load JPG		
17	21/02/20 15:33	General View					Load JPG		
18	21/02/20 15:33	General View					Load JPG		
19	21/02/20 15:33	General View					Load JPG		
20	21/02/20 15:33	General View					Load JPG		
21	21/02/20 15:33	General View					Load JPG		
22	21/02/20 15:33	General View					Load JPG		
23	21/02/20 15:33	General View					Load JPG		
24	21/02/20 15:33	General View					Load JPG		
25	21/02/20 15:33	General View					Load JPG		
26	21/02/20 15:33	General View					Load JPG		
27	21/02/20 15:33	General View					Load JPG		
28	21/02/20 15:33	General View					Load JPG		
29	21/02/20 15:33	General View					Load JPG		
30	21/02/20 15:33	General View					Load JPG		
31	21/02/20 15:33	General View					Load JPG		
32	21/02/20 15:33	General View					Load JPG		
33	21/02/20 15:33	General View					Load JPG		
34	21/02/20 15:33	General View					Load JPG		
35	21/02/20 15:33	General View					Load JPG		
36	21/02/20 15:33	General View					Load JPG		
37	21/02/20 15:33	General View					Load JPG		

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	21/02/20 15:33	General View	 Load JPG	☒
39	21/02/20 15:33	General View	 Load JPG	☒
40	21/02/20 15:33	General View	 Load JPG	☒
41	21/02/20 15:33	General View	 Load JPG	☒
42	21/02/20 15:33	General View	 Load JPG	☒
43	21/02/20 15:33	General View	 Load JPG	☒
44	21/02/20 15:33	General View	 Load JPG	☒
45	21/02/20 15:33	General View	 Load JPG	☒
46	21/02/20 15:33	General View	 Load JPG	☒
47	21/02/20 15:33	General View	 Load JPG	☒
48	21/02/20 15:33	General View	 Load JPG	☒
49	21/02/20 15:33	General View	 Load JPG	☒
50	21/02/20 15:33	General View	 Load JPG	☒
51	21/02/20 15:33	General View	 Load JPG	☒
52	21/02/20 15:33	General View	 Load JPG	☒
53	21/02/20 15:33	General View	 Load JPG	☒
54	21/02/20 15:33	General View	 Load JPG	☒
55	21/02/20 15:33	General View	 Load JPG	☒
56	21/02/20 15:33	General View	 Load JPG	☒
57	21/02/20 15:33	General View	 Load JPG	☒
58	21/02/20 15:33	General View	 Load JPG	☒
59	21/02/20 15:33	General View	 Load JPG	☒
60	21/02/20 15:33	General View	 Load JPG	☒
61	21/02/20 15:33	General View	 Load JPG	☒
62	21/02/20 15:33	General View	 Load JPG	☒
63	21/02/20 15:33	General View	 Load JPG	☒
64	21/02/20 15:33	General View	 Load JPG	☒
65	21/02/20 15:33	General View	 Load JPG	☒
66	21/02/20 15:33	General View	 Load JPG	☒
67	21/02/20 15:33	General View	 Load JPG	☒
68	21/02/20 15:33	General View	 Load JPG	☒
69	21/02/20 15:33	General View	 Load JPG	☒
70	21/02/20 15:33	General View	 Load JPG	☒
71	21/02/20 15:33	General View	 Load JPG	☒
72	21/02/20 15:33	General View	 Load JPG	☒
73	21/02/20 15:33	General View	 Load JPG	☒
74	21/02/20 15:33	General View	 Load JPG	☒
75	21/02/20 15:33	General View	 Load JPG	☒
76	21/02/20 15:33	General View	 Load JPG	☒
77	21/02/20 15:33	General View	 Load JPG	☒
78	21/02/20 15:33	General View	 Load JPG	☒
79	21/02/20 15:33	General View	 Load JPG	☒
80	21/02/20 15:33	General View	 Load JPG	☒
81	21/02/20 15:33	General View	 Load JPG	☒
82	21/02/20 15:33	General View	 Load JPG	☒
83	21/02/20 15:33	General View	 Load JPG	☒
84	21/02/20 15:33	General View	 Load JPG	☒
85	21/02/20 15:33	General View	 Load JPG	☒
86	21/02/20 15:33	General View	 Load JPG	☒
87	21/02/20 15:33	General View	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
88	21/02/20 15:33	General View	 Load JPG	☒
89	21/02/20 15:33	General View	 Load JPG	☒
90	21/02/20 15:33	General View	 Load JPG	☒
91	21/02/20 15:33	General View	 Load JPG	☒
92	21/02/20 15:33	General View	 Load JPG	☒
93	21/02/20 15:33	General View	 Load JPG	☒
94	21/02/20 15:33	General View	 Load JPG	☒
95	21/02/20 15:33	General View	 Load JPG	☒
96	21/02/20 15:33	General View	 Load JPG	☒
97	21/02/20 15:33	General View	 Load JPG	☒
98	21/02/20 15:33	General View	 Load JPG	☒
99	21/02/20 15:33	General View	 Load JPG	☒
100	21/02/20 15:33	General View	 Load JPG	☒
101	21/02/20 15:33	General View	 Load JPG	☒
102	21/02/20 15:33	General View	 Load JPG	☒
103	21/02/20 15:33	General View	 Load JPG	☒
104	21/02/20 15:33	General View	 Load JPG	☒
105	21/02/20 15:33	General View	 Load JPG	☒
106	21/02/20 15:33	General View	 Load JPG	☒
107	21/02/20 15:33	General View	 Load JPG	☒
108	21/02/20 15:33	General View	 Load JPG	☒
109	21/02/20 15:33	General View	 Load JPG	☒
110	21/02/20 15:33	General View	 Load JPG	☒
111	21/02/20 15:33	General View	 Load JPG	☒
112	21/02/20 15:33	General View	 Load JPG	☒
113	21/02/20 15:33	General View	 Load JPG	☒
114	21/02/20 15:33	General View	 Load JPG	☒
115	21/02/20 15:33	General View	 Load JPG	☒
116	21/02/20 15:33	General View	 Load JPG	☒
117	21/02/20 15:33	General View	 Load JPG	☒
118	21/02/20 15:33	General View	 Load JPG	☒
119	21/02/20 15:33	General View	 Load JPG	☒
120	21/02/20 15:33	General View	 Load JPG	☒
121	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
122	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
123	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
124	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
125	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
126	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
127	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
128	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
129	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
130	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
131	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
132	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
133	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
134	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
135	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
136	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
137	21/02/20 15:38	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
138	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
139	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
140	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
141	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
142	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
143	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
144	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
145	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
146	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
147	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
148	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
149	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
150	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
151	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
152	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
153	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
154	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
155	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
156	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
157	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
158	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
159	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
160	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
161	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
162	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
163	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
164	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
165	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
166	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
167	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
168	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
169	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
170	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
171	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
172	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
173	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
174	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
175	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
176	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
177	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
178	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
179	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
180	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
181	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
182	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
183	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
184	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
185	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
186	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
187	21/02/20 15:38	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
188	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
189	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
190	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
191	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
192	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
193	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
194	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
195	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
196	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
197	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
198	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
199	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
200	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
201	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
202	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
203	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
204	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
205	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
206	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
207	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
208	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
209	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
210	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
211	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
212	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
213	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
214	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
215	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
216	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
217	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
218	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
219	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
220	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
221	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
222	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
223	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
224	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
225	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
226	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
227	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
228	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
229	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
230	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
231	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
232	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
233	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
234	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
235	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
236	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
237	21/02/20 15:38	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
238	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
239	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
240	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
241	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
242	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
243	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
244	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
245	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
246	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
247	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
248	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
249	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
250	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
251	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
252	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
253	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
254	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
255	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
256	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
257	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
258	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
259	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
260	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
261	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
262	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
263	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
264	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
265	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
266	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
267	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
268	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
269	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
270	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
271	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
272	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
273	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
274	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
275	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
276	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
277	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
278	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
279	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
280	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
281	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
282	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
283	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
284	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
285	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
286	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
287	21/02/20 15:38	Reinspection Photo	 Load JPG	☒

Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
288	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
289	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
290	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
291	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
292	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
293	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
294	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
295	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
296	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
297	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
298	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
299	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
300	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
301	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
302	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
303	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
304	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
305	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
306	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
307	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
308	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
309	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
310	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
311	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
312	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
313	21/02/20 15:38	Reinspection Photo	 Load JPG	☒
314	21/02/20 15:39	Reinspection Photo	 Load JPG	☒
315	21/02/20 15:39	Reinspection Photo	 Load JPG	☒
316	21/02/20 15:39	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST		Reset	Save	Print
There are no document checklists configured.				
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)				
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.				

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/EGI19022074/USF3E2

Date: 25/02/2020

REFERENCE

Handling Insurer: ERGO Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No: GBJ5745A

Insured Vehicle No: YP4250M

Date of Loss: 12/12/2019

Nature of Claim: TP

Claim No: CDMCG19002355

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBJ5745A

Make & Model: FIAT NEW DOBLO SX, 1.6 MJ E6 GLA (A)

Engine No: 263A80008745950

Reg. Date: 07/06/2019 (Man. Year: 2019)

Chassis No: ZFA26300006N23163

Colour: White/Blue

Odometer: 9901 km

Engine Capacity: 1598 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/60 R16

Rear Tyre Size:

195/60 R16

Front Left Side: Goodyear 6 mm

Rear Left Side:

Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side:

Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	69,156.40	29,065.21	40,091.19	57.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	10,440.00	5,560.00	4,880.00	46.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	79,596.40	34,625.21	44,971.19	56.50
Approved Total (Overridden) (\$\$)		27,000.00		
(\$\$)	79,596.40	27,000.00	52,596.40	66.08
+ GST 7.00/7.00% (\$\$)	5,571.75	1,890.00	3,681.75	66.08
Nett Amount (\$\$)	85,168.15	28,890.00	56,278.15	66.08

INSPECTION

Date of Assignment: 13/12/2019

Date Inspected: 18/12/2019 Inspected At:

Liu's Brother Auto Engineering Workshop (HQ)

BLK 1 KAKI BUKIT AVE 6, #01-01 AUTO

BAY @ KAKI BUKIT

Singapore 417883

Estimated Period of Repair: 24.0 days

Adjuster: MARCUS CHUA**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	(Last Synchronised: 25 Feb 2020)	
Parts:	N/A	FIAT NEW DOBLO SX 1.6 MJ E6 GLA (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBJ5745A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	627.00 F	*627.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	65.00 F	*65.00 FL
3	1		*REAR BUMPER REFLECTOR	N/S Broken	197.20 F	*98.60 FL
4	1		*REAR BUMPER REINFORCEMENT	Bent	475.30 F	*475.30 FL
5	1		*REAR END PANEL OUTER	Badly Dented	430.00 F	*430.00 FL
6	1		*REAR END PANEL INNER	Badly Dented	295.00 F	*295.00 FL
7	1		*REAR END PANEL TOP GARNISH	Deformed / Cracked	347.70 F	*315.00 FL
8	1		*SET REAR END PANEL TOP GARNISH CLIPS	Not Necessary	58.00 F	*- FL
9	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	220.00 FS	*200.00 FS
10	1		*REAR BUMPER RETAINERS	N/S Bent	567.40 F	*115.00 FL
11	1		*REAR SPARE TYRE CARRIER	Not Necessary	590.00 F	*- FL
12	1		*REAR FLOOR PANEL	Crumpled / Buckled	2,450.00 F	*2,350.00 FL
13	1		*REAR FLOOR PANEL TOP MAT	Distorted	179.80 F	*179.80 FL
14	2		*REAR TAIL LAMP	N/S Broken / O/S Cracked	925.40 F	*925.40 FL
15	1		*REAR RH TAILGATE	Badly Dented	1,895.90 F	*1,895.90 FL
16	1		*REAR RH TAILGATE WEATHERSTRIP	Torn	237.00 F	*237.00 FL
17	1		*REAR RH TAILGATE INNER TRIM BOARD	Deformed / Cut	297.80 F	*297.80 FL
18	1		*SET REAR RH TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	127.20 F	*- FL
19	1		*REAR RH TAILGATE LOCK TOP	Not Necessary	189.30 F	*- FL
20	1		*REAR RH TAILGATE LOCK BOTTOM	Jammed	192.90 F	*192.90 FL
21	2		*REAR RH TAILGATE HINGE	Not Necessary	332.60 F	*- FL
22	1		*REAR RH TAILGATE OUTER GARNISH	Cracked	279.00 F	*279.00 FL
23	1		*REAR RH TAILGATE INNER HANDLE	Not Necessary	189.40 F	*- FL
24	1		*REAR RH TAILGATE FIAT LOGO EMBLEM	Not fitted	87.80 F	*- FL
25	1		*REAR RH TAILGATE PROFESSIONAL EMBLEM	Not fitted	163.50 F	*- FL
26	1		*REAR RH TAILGATE 6 PAX STICKER	Necessary	12.00 FS	*10.00 FS
27	1		*REAR RH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
28	1		*REAR TAILGATE 70 KM/H STICKER	Necessary	15.00 FS	*10.00 FS
29	1		*REAR WINDSCREEN RH	Shattered	605.00 F	*605.00 FL
30	1		*REAR LH TAILGATE	Badly Dented	2,156.30 F	*2,156.30 FL
31	1		*REAR LH TAILGATE WEATHERSTRIP	Torn	279.00 F	*279.00 FL
32	1		*REAR LH TAILGATE INNER TRIM BOARD	Torn	384.90 F	*384.90 FL
33	1		*SET REAR LH TAILGATE INNER TRIM BOARD CLIPS	Not Necessary	164.50 FS	*- FS
34	1		*REAR LH TAILGATE LOCK	Twisted / Jammed	331.00 F	*331.00 FL
35	1		*REAR LH TAILGATE HINGE	Lower Bent	332.60 F	*166.30 FL
36	1		*REAR LH TAILGATE OUTER HANDLE	Cracked	556.40 F	*488.20 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
37	1		*REAR LH TAILGATE OUTER HANDLE GARNISH	Cracked	369.80 F	*369.80 FL
38	1		*REAR LH TAILGATE INNER HANDLE	Not Necessary	189.40 F	*- FL
39	1		*REAR LH TAILGATE NUMBER PLATE OUTER GARNISH	Not Necessary	310.60 F	*- FL
40	2		*REAR LH TAILGATE NUMBER PLATE LAMP	Not Necessary	103.00 F	*- FL
41	1		*REAR LH TAILGATE NUMBER PLATE & BASE	Bent	48.00 FS	*40.00 FS
42	1		*REAR LH TAILGATE WINDSCREEN GLASS	Shattered	841.50 F	*685.20 FL
43	1		*REAR LH TAILGATE GLASS SEALANT	Necessary	80.00 FS	*40.00 FS
44	1		*REAR LH TAILGATE WIPER MOTOR	Cracked / Jammed	428.00 F	*428.00 FL
45	1		*REAR LH TAILGATE WIPER ARM	Bent	165.30 F	*165.30 FL
46	1		*REAR LH TAILGATE WIPER BLADE	Twisted	98.00 F	*98.00 FL
47	1		*REAR LH TAIL LAMP PANEL	Badly Dented	989.30 F	*989.30 FL
48	1		*REAR LH FENDER (BODY PANEL)	Badly Dented / Twisted	2,350.00 F	*2,350.00 FL
49	1		*REAR LH FENDER COWLING	Torn	316.00 F	*266.40 FL
50	1		*CORPORATE ADVERTISEMENT STICKER	Necessary	2,000.00 FS	*800.00 FS
51	1		*FRONT BONNET	Buckled	1,170.00 F	*983.43 FL
52	2		*FRONT BONNET HINGES	Serviceable	270.00 F	*- FL
53	1		*FRONT BONNET INSULATOR	Not Necessary	97.30 F	*- FL
54	1		*SET FRONT BONNET INSULATOR CLIPS	Not Necessary	50.00 F	*- FL
55	2		*FRONT BONNET RUBBER BEADING	Not Necessary	196.80 F	*- FL
56	1		*FRONT BONNET INNER LOCK	Twisted	145.00 F	*145.00 FL
57	1		*FRONT BONNET SPONGE	No such part	241.80 F	*- FL
58	1		*SET FRONT BONNET SPONGE CLIPS	No such part	80.00 FS	*- FS
59	2		*FRONT FENDER	Repair	1,560.00 F	*- FL
60	2		*FRONT FENDER COWLING	Not Necessary	932.00 F	*- FL
61	2		*SETS FRONT FENDER COWLING CLIPS LH & RH	Not Necessary	120.00 F	*- FL
62	2		*FRONT FENDER COVER BLACK	Not Necessary	1,280.00 F	*- FL
63	2		*FRONT HEAD LAMP	Cracked	1,724.80 F	*1,724.80 FL
64	2		*FRONT HEAD LAMP PANEL	Repair	1,977.40 F	*- FL
65	1		*FRONT SUPPORT PANEL CENTRE	Bent	790.00 F	*665.00 FL
66	1		*FRONT BUMPER	Distorted	1,245.50 F	*1,092.00 FL
67	1		*SET FRONT BUMPER CLIPS	Necessary	58.00 F	*58.00 FL
68	1		*FRONT BUMPER REINFORCEMENT	Bent	752.00 F	*715.00 FL
69	1		*FRONT BUMPER LOWER GRILLE	Torn	685.00 F	*685.00 FL
70	1		*SET FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	65.00 F	*- FL
71	2		*FRONT BUMPER RETAINERS	Bent	343.80 F	*278.00 FL
72	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	395.20 F	*- FL
73	1		*FRONT BUMPER SPONGE	Torn	117.60 F	*117.60 FL
74	1		*FRONT BUMPER TOWING COVER	Torn	105.00 F	*45.00 FL
75	1		*FRONT GRILLE	Cracked	484.70 F	*484.70 FL
76	1		*FRONT GRILLE FIAT LOGO MOTIF	Not Necessary	142.10 F	*- FL
77	1		*FRONT DIESEL PUMP	Not Necessary	1,370.00 F	*- FL
78	1		*FRONT CORPORATE ADVERTISEMENT & ARTWORK	Necessary	300.00 FS	*300.00 FS
79	1		*FRONT WIPER TANK	Not Necessary	280.00 F	*- FL
80	1		*FRONT INTER COOLER	Cut	3,640.00 F	*1,850.00 FL
81	1		*FRONT INTER COOLER COWLING	Not Necessary	435.00 F	*- FL
82	1		*SET FRONT INTER COOLER CLIPS	Not Necessary	35.00 FS	*- FS
83	1		*FRONT AIRCON CONDENSER	Bent / Punctured	1,278.00 F	*1,278.00 FL
84	1		*FRONT AIR CON CONDENSOR COWLING	No such part	285.00 F	*- FL
85	1		*FRONT RADIATOR	Bent / Cracked	854.30 F	*854.30 FL
86	1		*FRONT RADIATOR TOP HOSE	Not Necessary	2,017.80 F	*- FL
87	1		*FRONT RADIATOR SPARE TANK	Not Necessary	773.50 F	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
88	1		*FRONT RADIATOR HOSE TOP	Not Necessary	142.80 F	*- FL
89	1		*FRONT RADIATOR HOSE LOWER	Not Necessary	195.70 F	*- FL
90	1		*FRONT RADIATOR COOLANT 1 BOTTLE	Necessary	45.00 FS	*30.00 FS
91	1		*FRONT ABS MASTER PUMP	Not Necessary	4,270.00 F	*- FL
92	1		*FRONT TURBO	Not Necessary	4,856.30 F	*- FL
93	1		*FRONT ENGINE LOWER COVER	Not Necessary	975.00 F	*- FL
94	1		*SET FRONT ENGINE MOUNTING	Not Necessary	1,790.00 F	*- FL
95	1		*FRONT ENGINE TOP COVER	Not Necessary	890.00 F	*- FL
96	1		*FRONT NUMBER PLATE GARNISH	Distorted	387.00 FS	*60.00 FS
97	1		*FRONT NUMBER PLATE AND BASE	Bent	48.00 FS	*40.00 FS
98	1		*FRONT EXHAUST SENSOR	Not Necessary	610.00 F	*- FL
99	1		*FRONT EXHAUST HEAT SHIELD	Not Necessary	365.80 F	*- FL
100	1		*FRONT EXHAUST HEATER	Not Necessary	317.20 F	*- FL
101	1		*FRONT BATTERY	Not Necessary	280.00 F	*- FL
102	1		*FRONT BATTERY BASE	Not Necessary	385.00 F	*- FL
103	1		*FRONT AIR CLEANER COMPLETED	Not Necessary	955.90 F	*- FL
104	1		*FRONT AIR CLEANER HOSE	Not Necessary	361.80 F	*- FL
105	1		*FRONT HORN UNIT	Not Necessary	182.10 F	*- FL
106	1		*FRONT RADIATOR FAN MOTOR }	Cracked / Jammed	1,175.60 F	*1,033.00 FL
107	1		*FRONT RADIATOR FAN COWLING COMPLETED }		0.00 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	69,156.40	32,120.23
- List Item Discount on L Items 0.00/10.00% (\$\$)	0.00	3,055.02

Total Parts (\$\$)	69,156.40	29,065.21
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK ALL WIRING & ELECTRICAL COMPONENT FOR PROPER FUNCTION	New	360.00	40.00
2	REMOVE AND REFIX REAR 2 TAILGATE COMPONENTS & WIPER MECHANISM	New	360.00	100.00
3	REMOVE AND REFIX REAR BUMPER REVERSE SENSOR	New	100.00	50.00
4	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS (REAR)	New	2,500.00	2,400.00
5	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED (REAR)	New	1,800.00	1,200.00
6	REMOVE & REINSTALL TAILGATE 2 GLASS TO FACILITATE REPAIRS	New	560.00	200.00
7	TO APPLY RUST PROOFING, RESEAL TUFF-COATING TREATMENT ON ACCIDENT AREA	New	360.00	170.00
8	REMOVE AND REPLACING CONDENSER INCLUDING REFILL GAS	New	100.00	100.00
9	LABOR FOR PANEL BEATING, CUT, WELD, STRAIGHTEN & REPLACING PARTS ETCS (FRONT)	New	2,500.00	700.00
10	TO PUTTY & SPRAY PAINTING & INCLUDING TOUCH UP PAINT ON ACCIDENT AFFECTED (FRONT)	New	1,800.00	600.00
Gross Labour Cost (S\$)			10,440.00	5,560.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >