

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/III19022083/EPS3Q2

**Date:** 29/04/2020

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
<b>Claimant</b>		
<b>Vehicle No :</b> SLA6325B	<b>Insured Vehicle No :</b>	SHD4335S
Date of Loss: 13/12/2019	Nature of Claim: TP	Claim No: MCT19120325

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLA6325B</b>		
Make & Model:	HONDA CITY, 1.5 (A)	Engine No:	L15Z12720058
Reg. Date:	09/03/2016 (Man. Year: 2016)	Chassis No:	MRHGM6660GP000466
Colour:	Blue	Odometer:	48369 km
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Dunlop 5 mm	Rear Left Side:	Dunlop 5 mm
Front Right Side:	Dunlop 5 mm	Rear Right Side:	Dunlop 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	2,662.28	1,279.58	1,382.70	51.94
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,170.00	8,640.00	2,530.00	22.65
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (\$\$)</b>	<b>13,832.28</b>	<b>9,919.58</b>	<b>3,912.70</b>	<b>28.29</b>
<b>+ GST 7.00/7.00% (\$\$)</b>	968.26	694.37	273.89	28.29
<b>Nett Amount (\$\$)</b>	<b>14,800.54</b>	<b>10,613.95</b>	<b>4,186.59</b>	<b>28.29</b>
<b>+ Car Rental (15.0 x S\$100.00/day + 7.00% GST) (\$\$)</b>		1,605.00		
		<b>12,218.95</b>		

### INSPECTION

Date of Assignment:	16/12/2019	
Date Inspected:	23/12/2019 Inspected At:	Kah Motor Co Sdn Bhd (alexandra) (HQ) 255 Alexandra Road Singapore 159937
Estimated Period of Repair:	13.0 days	

**Adjuster:** CHEN TSUE YEE

**Manager:** CHEW HSIAO TONG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 12 Feb 2020)
<b>Parts:</b>	143	HONDA CITY 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLA6325B)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LID COMPTRUNK	Repair	375.15 FS	*- FS
2	1		*EMBLEM H	Necessary	9.22 FS	*9.22 FS
3	1		*EMBLEMRR .CITY	Necessary	9.52 FS	*9.52 FS
4	1		*EMBLEMRR.I-VTEC	Necessary	9.97 FS	*9.97 FS
5	2		*CLIP TUBULAR	Necessary	3.60 FS	*3.60 FS
6	1		*LOCK ASSYTRUNK	Not Necessary	75.82 FS	*- FS
7	1		*WEATHERSTRIPTRUNK LID	Not Necessary	60.45 FS	*- FS
8	1		*PANEL COMPRR	Dented	273.37 FS	*273.37 FS
9	1		*LINING ASSYRR.PANEL	Crushed	49.95 FS	*49.95 FS
10	1		*FACERR.BUMPER	Dented	347.77 FS	*347.77 FS
11	1		*REFLECTOR ASSY R.RR	Not Necessary	12.45 FS	*- FS
12	1		*REFLECTOR ASSY L.RR	Not Necessary	12.45 FS	*- FS
13	1		*SPACER R.RR BUMPER SIDE	Broken	8.62 FS	*8.62 FS
14	1		*SPACER L.RR BUMPER SIDE	Broken	8.62 FS	*8.62 FS
15	1		*CLIP.BUMPER (4 PCS)	Necessary	6.90 FS	*6.90 FS
16	1		*TAILLLIGHT ASSYR	Not Necessary	154.27 FS	*- FS
17	1		*TAILLLIGHT ASSYL	Not Necessary	154.27 FS	*- FS
18	1		*LIGHT ASSY,R.LID	Not Necessary	61.42 FS	*- FS
19	1		*LIGHT ASSY,L.LID	Not Necessary	61.42 FS	*- FS
20	1		*ACR RR SENSOR	Not Necessary	320.00 FS	*- FS
21	1		*NUMBER PLATE WITH CASING -L	Not Necessary	45.00 FS	*- FS
22	1		*SUNDRIES	Necessary	100.00 FS	*50.00 FS
23	1		*PANEL SETRR.FLOOR	Dented	345.00 FS	*345.00 FS
24	1		*STIFFENERRR.JACK UP	Dented	78.60 FS	*78.60 FS
25	1		*OILSHEET	Necessary	31.27 FS	*31.27 FS
26	1		*BUZZER ASSYSMART	Broken	47.17 FS	*47.17 FS

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)** **2,662.28** **1,279.58**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	INSPECT RR LIGHTING MECHANISMS PERFORM WATER	New	180.00	180.00
2	REMOVE & INSTALL REAR COMPARTMENT LININGS	New	560.00	560.00
3	BODY JOINT SEALANT END PANEL	New	150.00	120.00
4	BODY UNDERSIDE COATING	New	280.00	250.00
5	RESET VEHICLE SMART ENTRY SYSTEM	New	480.00	450.00
6	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	New	480.00	0.00
7	REMOVE & RENEW REVERSE SENSORS	New	180.00	180.00
8	CUT OFF & RENEW RR PANELAND REPLACE DAMAGE PARTS	New	3,920.00	1,960.00
9	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS	New	2,250.00	2,250.00
10	CUT & RENEW RR FLOOR PANEL	New	2,240.00	2,240.00
11	SPRAY PAINTING ON FLOOR PANEL	New	450.00	450.00
<b>Gross Labour Cost (S\$)</b>			<b>11,170.00</b>	<b>8,640.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >