

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORTChina Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909**Our File No:** CS/CT119022107/T1TF32E**Date:** 07/04/2020REFERENCE

Insured/Claimant: SMTECH HOLDINGS PTE LTD Policy No: DMPCSN30752319000

Date of Loss: 11/12/2019

Nature of Claim: OD

Claim No: SNM19D205945C01

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SKW1221X**

Make & Model: PORSCHE MACAN, 2.0 PDK (A)

Engine No: 018254

Reg. Date: 05/03/2015 (Man. Year: 2014)

Chassis No: WP1ZZZ95ZFLB67036

Colour: White

Odometer: 91207 km

Engine Capacity: 2997 cc

Market Value/New Car Price: S\$184,000.00

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 295/45 R20

Rear Tyre Size: 295/45 R20

Front Left Side: Michelin 6 mm

Rear Left Side: Michelin 6 mm

Front Right Side: Michelin 6 mm

Rear Right Side: Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,823.00	6,652.00	1,171.00	14.97
Miscellaneous Items	0.00	0.00	0.00	
Labour	8,080.00	6,320.00	1,760.00	21.78
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	15,903.00	12,972.00	2,931.00	18.43
- Excess (S\$)	2,500.00	2,500.00	0.00	0.00
(S\$)	13,403.00	10,472.00	2,931.00	21.87
+ GST 7.00/7.00% (S\$)	938.21	733.04	205.17	21.87
Nett Amount (S\$)	14,341.21	11,205.04	3,136.17	21.87

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 17/12/2019

Inspected At:

Stuttgart Auto Pte Ltd
27A Tanjong Penjuru
Singapore 609042

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 07 Apr 2020)
Parts: M1-SUV	PORSCHE MACAN 2.0 PDK (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKW1221X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*PORCHE CREST	Necessary	248.60 FS	*248.60 FS
2	1		*DESK PAD CREST	Necessary	14.40 FS	*14.40 FS
3	2		*HOOD BADGE NUT	Necessary	3.00 FS	*3.00 FS
4	1		*TOP PANEL COVER	Cracked	68.30 FS	*68.30 FS
5	1		*BONNET	Bent	3,225.60 FS	*3,225.60 FS
6	2		*BONNET SEAL	Necessary	14.80 FS	*14.80 FS
7	1		*FRONT BUMPER	Deformed	1,084.90 FS	*1,084.90 FS
8	1		*FRONT BUMPER CENTER GRILLE	Deformed	329.10 FS	*329.10 FS
9	1		*TOW COVER	Deformed	47.50 FS	*47.50 FS
10	1		*FRONT SPOILER	Deformed	215.80 FS	*215.80 FS
11	1		*LICENSE PLATE BRACKET	Deformed	86.40 FS	*86.40 FS
12	1		*REINFORCEMENT	Not Necessary	378.40 FS	*- FS
13	1		*PLASTIC FOAM STRIP	Cracked	65.80 FS	*65.80 FS
14	1		*BUMPER LOWER SUPPORT	Cracked	216.60 FS	*216.60 FS
15	1		*RADIATOR AIR FLAP	Not Necessary	362.70 FS	*- FS
16	1		*AIR GUIDE CENTER	Cracked	145.50 FS	*145.50 FS
17	1		*SIDE LOWER AIR DUCT LH	Cracked	62.30 FS	*62.30 FS
18	1		*SIDE LOWER AIR DUCT RH	Cracked	62.30 FS	*62.30 FS
19	1		*SIDE UPPER AIR DUCT LH	Cracked	41.80 FS	*41.80 FS
20	1		*SIDE UPPER AIR DUCT RH	Cracked	41.80 FS	*41.80 FS
21	1		*RADIATOR AIR DUCT REAR	Deformed	169.60 FS	*169.60 FS
22	1		*P7PP-010-714-R-/(WB35) WARNING SIGN STICKER	Necessary	5.90 FS	*5.90 FS
23	1		*MOBIL 1 STICKER	Necessary	6.30 FS	*6.30 FS
24	1		*AIR CON STICKER	Necessary	16.40 FS	*16.40 FS
25	1		*INDICATION STICKER	Necessary	8.90 FS	*8.90 FS
26	1		*UNDERBODY COVER CENTER	Not Necessary	409.90 FS	*- FS
27	1		*MUDFLAP LH	Deformed	110.20 FS	*110.20 FS
28	1		*MUDFLAP RH	Deformed	110.20 FS	*110.20 FS
29	1		*CHASSIS STICKER	Necessary	150.00 FS	*150.00 FS
30	1		*NUMBER PLATE WITH CASING	Cracked	70.00 FS	*70.00 FS
31	1		*SUNDRIES	Necessary	50.00 FS	*30.00 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 7,823.00 6,652.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BONNET, FRONT BUMPER & TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT	New	4,680.00	3,120.00
2	TO RESPRAY BONNET & FRONT BUMPER	New	2,600.00	2,400.00
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	New	200.00	200.00
4	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS	New	600.00	600.00
			Gross Labour Cost (\$\$)	8,080.00
				6,320.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >