

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19022140/AKA3Q2

Date: 13/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 0999994065

Claimant
Vehicle No : SLP2586L **Insured Vehicle No :** SLK4366T

Date of Loss: 15/12/2019 Nature of Claim: TP Claim No: 1021436262SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLP2586L		
Make & Model:	MAZDA 3, 2.0 SEDAN SPORTS A/T 2WD S/R (A)	Engine No:	PE20829399
Reg. Date:	30/05/2017 (Man. Year: 2016)	Chassis No:	JM6BN2278H0115829
Colour:	White	Odometer:	68829 km
Engine Capacity:	1998 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45 R18	Rear Tyre Size:	215/45 R18
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	10,680.40	5,832.80	4,847.60	45.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,430.00	3,100.00	1,330.00	30.02
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	15,110.40	8,932.80	6,177.60	40.88
Approved Total (Overridden) (\$\$)		7,150.00		
(\$\$)	15,110.40	7,150.00	7,960.40	52.68
+ GST 7.00/7.00% (\$\$)	1,057.73	500.50	557.23	52.68
Nett Amount (\$\$)	16,168.13	7,650.50	8,517.63	52.68
+ Car Rental (9.0 x S\$120.00/day) (\$\$)		1,080.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		8,737.95		
Global Sum Settlement (\$\$)		8,450.00		

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 18/12/2019 Inspected At:

Modern Automotive Pte Ltd (HQ)
Blk 3023A Ubi Road 1, #01-61 & #01-58
Singapore 408717

Estimated Period of Repair: 8.0 days

Adjuster: ADRIAN LING**Manager:** Khanchna Pothuraj

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,075.00 FL	*1,075.00 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	30.00 FL	*30.00 FL
3	2		*REAR BUMPER SIDE HOLDER -LH & RH	Necessary	110.00 FL	*110.00 FL
4	2		*REAR BUMPER TOWING COVER	Missing	68.00 FL	*68.00 FL
5	1		*REAR BUMPER REINFORCEMENT	Bent	538.00 FL	*538.00 FL
6	2		*REAR BUMPER REFLECTOR -LH & RH	Not Necessary	230.00 FL	*- FL
7	1		*REAR END PANEL	Distorted	530.00 FL	*530.00 FL
8	1		*REAR END PANEL TOP GARNISH	Deformed	185.00 FL	*185.00 FL
9	2		*TAILLAMP -LH & RH	Cracked	1,170.00 FL	*1,170.00 FL
10	2		*TAILLAMP PANEL-LH & RH	Repair	702.00 FL	*- FL
11	1		*BOOTLID	Distorted	1,005.00 FL	*1,005.00 FL
12	1		*BOOTLID LOCK	Damaged	198.00 FL	*198.00 FL
13	1		*BOOTLID WEATHERSTRIPE	Cut	135.00 FL	*135.00 FL
14	2		*BOOTLID REFLECTOR -LH & RH	Cracked	590.00 FL	*590.00 FL
15	1		*BOOTLID INNER TRIM	Not Necessary	195.00 FL	*- FL
16	1		*BOOTLID INNER TRIM CLIPS	Necessary	30.00 FL	*30.00 FL
17	2		*BOOTLID HINGES -LH & RH	Bent	292.00 FL	*292.00 FL
18	2		*BOOTLID HINGES COVER-LH & RH	Not Necessary	68.00 FL	*- FL
19	1		*MAZDA LOGO	Necessary	56.00 FL	*56.00 FL
20	1		*MAZDA 3 WORDING	Necessary	65.00 FL	*65.00 FL
21	1		*SKY ACTIV EMBLEM	Necessary	69.00 FL	*69.00 FL
22	2		*REAR FENDER -LH & RH	Repair	2,370.00 FL	*- FL
23	2		*REAR FENDER INNER TRIM -LH & RH	Not Necessary	472.00 FL	*- FL
24	1		*REAR FENDER INNER TRIM CLIPS	Necessary	60.00 FL	*60.00 FL
25	1		*SPARE TYRE PANEL TOP COVER	Deformed	308.00 FL	*308.00 FL
26	1		*SPARE TYRE PANEL TOP SPONGE TRAY	Deformed	252.00 FL	*252.00 FL
27	1		*REAR WINDSCREEN MOULDING	Not Necessary	168.00 FL	*- FL
28	1		*REAR EXHAUST PIPE	Not Necessary	1,075.00 FL	*- FL
29	1		*REAR EXHAUST MOUNTING	Not Necessary	42.00 FL	*- FL
30	1		*REAR NUMBER PLATE	Bent	30.00 FS	*30.00 FS
31	1		*REAR NUMBER PLATE HOLDER	Deformed	30.00 FS	*30.00 FS
32	4		*REVERSE SENSOR	Damaged	350.00 FS	*300.00 FS
33	1		*REAR END PANEL SEALANT	Necessary	60.00 FS	*60.00 FS
34	1		*REAR CAMERA	Not Necessary	480.00 FS	*- FS
35	1		*REAR WINDSCREEN SEALANT	Not Necessary	60.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	13,098.00	7,186.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	2,417.60	1,353.20
Total Parts (\$\$)	10,680.40	5,832.80

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO KNOCKING & PULL OUT REAR PORTION & RENEW ABOVE PARTS	New	1,800.00	1,400.00
2	TO PUTTY & SPRAY UP PAINT WORKS	New	1,600.00	1,400.00
3	TO CHECK WIRING	New	50.00	30.00
4	TO REMOVE REVERSE SENSOR	New	100.00	60.00
5	TO REMOVE UPHOLSTERY	New	150.00	80.00
6	TO REMOVE REAR CAMERA	New	100.00	50.00
7	TO TRANSFER BOOTLID FITTINGS	New	150.00	80.00
8	TO REMOVE FUEL TANK	New	150.00	0.00
9	TO REMOVE EXHAUST PIPE	New	150.00	0.00
10	TO REMOVE REAR WINDSCREEN	New	180.00	0.00
Gross Labour Cost (\$)			4,430.00	3,100.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >