

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19022157/AEA3Q2

Date: 28/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800151219

Claimant
Vehicle No : SGK1313A **Insured Vehicle No :** SLV6222D

Date of Loss: 09/12/2019 Nature of Claim: TP Claim No: 7471832895SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGK1313A		
Make & Model:	HONDA STREAM, 1.8 (A)	Engine No:	R18A1754894
Reg. Date:	07/12/2007 (Man. Year: 2007)	Chassis No:	RN61049220
Colour:	Black	Odometer:	205012 km
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/50 R17	Rear Tyre Size:	215/50 R17
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,172.96	1,036.64	1,136.32	52.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,750.00	1,000.00	750.00	42.86
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	3,922.96	2,036.64	1,886.32	48.08
Approved Total (Overridden) (S\$)		1,600.00		
(S\$)	3,922.96	1,600.00	2,322.96	59.21
+ GST 7.00/7.00% (S\$)	274.61	112.00	162.61	59.21
Nett Amount (S\$)	4,197.57	1,712.00	2,485.57	59.21
+ Loss of Use (5.0 x S\$80.00/day) (S\$)		400.00		
Nett Liability (S\$)		2,112.00		

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 16/12/2019 Inspected At:

Success United Pte Ltd (HQ)
2 Kaki Bukit Ave 2 #01-33, Kaki Bukit
AutoHub
Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	688.90 FL	*688.90 FL
2	8		*REAR BUMPER CLIPS	Necessary	44.00 FL	*44.00 FL
3	1		*REAR BUMPER SIDE HOLDER RH	Necessary	37.90 FL	*37.90 FL
4	1		*REAR BUMPER INNER SIDE SHIELD RH	Not Necessary	61.80 FL	*- FL
5	1		*REAR FENDER RH	Repair	858.30 FL	*- FL
6	1		*SIDE ROCKER SKIRT RH	Repair	500.30 FL	*- FL
7	1		*REAR SPORT RIM RH	Cut	420.00 FS	*420.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	2,611.20	1,190.80
- List Item Discount on L Items 20.00/20.00% (\$)	438.24	154.16
Total Parts (\$)	2,172.96	1,036.64

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE,REPAIR AND REPLACED DAMAGED BODYPARTS ,REALIGN BODYWORKS & WHERE CONSISTENT TO THE ACCIDENT	New	900.00	400.00
2	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREA	New	850.00	600.00
Gross Labour Cost (\$\$)			1,750.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >