

INS. CASE OWNER:

CC 3 /AIG190

2109, Q dls

LKK
IDAC

Surveyor:

Sunpin

DOI:

ASSIGNMENT

16/1/19

Date / Time:

16/1/19

Registered in Merimen:

12/1/19

Pre-assign / CCU / FTE



Insured Vehicle No.:

SLA 37264

Name of Insured:

Wong Wai Sen

Insured Tel No.:

HP:

Claim No.:

20040492-06

Policy No.:

WISSAW

Make / Model:

Place of Accident:

PIE TMS TMS

Excess Sec II :\$5

D.O.A.:

14/1/19

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

Huang Bro'w Edwin

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability:

%

Final ? Yes / No

SKY 4180E

UNKNOWN

SLA 37264

SHB54074



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT

T1

Date/ Time

SHB54074-1

SLA 37264-1

STAGE

DATE / PIC

Non-Reporting hr (1st):

Non-Reporting hr (2nd):

Non-Reporting hr (Final):

Notification hr (if non-pickup):

Call OI:

After call hr to OI:

Documentation Check List: Handler Typist

Notification hr (if non-pickup)

After call hr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA :

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$5

(days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time: 28/3/2020

Confirm with: Tom Lee Goh

Email

Cal

Final Liability:

%

100

(Agreed / Assessed) BOLA S/N No. : 28

If NO or B 28, Ass. Lta : 02

Repair Cost:

\$5 1350.00

4 veh C.C., 02 was 2nd

Loss of Rental (LOR):

\$5 322.62

(

3

days)

x \$107.54

Loss of Use (LOU):

\$5 -

(5

x

days)

Loss of Income (LOI):

\$5 150.00

(5

50

x

3

days)

LOR only

LOU only

LOR + LOU

LOR + LO

[Tick only one]

GIA/LTA Search

\$5 7.00

Medical:

\$5 -

Disbursement:

\$5 -

(e.g. Tow/ Independent)

Legal Cost

\$5 -

1) Claim status: Notify/Reject/Private Settle

2) Report Format:

3) Survey fee: \$520

Total:

\$5 1829.62

Global Sum \$5:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Cal

Payee 1:

\$5 1829.62

Name 1:

SMRT Taxis Pte Ltd

Payee 2: (Strike if N.A.)

\$5

Name 2:

Payee 3: (Strike if N.A.)

\$5

Name 3:

COPY SENT
3/3/2020

Section A - Accident Details

Registration Number	SHB5407Y
Case Reference Number	TAX/12/19/2067
Registration Date	8/4/2016
Company Type	SMRT Taxis Pte Ltd
Make	TOYOTA
Model	PRIUS
Name of Driver	WONG CHEE WAI
Type of Accident	Head to Rear
Accident Date and Time	14/12/2019 12:15 AM
Accident Reported Date and Time	14/12/2019 11:57 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle Issued?	No
Job Card Number	24104874
Special Instruction to ARC, if any	TP
Prepared Date and Time	14/12/2019 4:04 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$338.00	\$200.00
Total Spray Cost	\$558.00	\$200.00
Total Spare Part Cost	\$1,984.69	\$650.22
Total Other Cost	\$658.88	\$316.88
TOTAL COST	\$3,537.57	\$1,367.10
Lump Sum Total	\$3,550.00	\$1,350.00 (L/S)
Number of Repair Days	4.0	2.0
Prepared / Adjusted By	Ang Bang Kien	Sun Pin (LKK) / AIG
ARC / Surveyor Sign Off Date	17/12/2019 9:14 AM	16/12/2019 4:22 PM
Signature		
Remarks	Lump sum repair, Take after spray photo.	

Section C - Quotation and Accident Invoice Details

Quotation Number	GN-2001-0209	Invoice Number	
Quotation Date	14.01.2020	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	\$338.00	\$200.00
Total Labour	\$338.00	\$200.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$375.00	\$200.00
TO RESPRAY BUMPER BEAM	\$180.00	\$0.00
Total Spray Painting & Panel Beating	\$555.00	\$200.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$20.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	\$0.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	\$296.88	\$296.88
Total Other Costs	\$656.88	\$316.88

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved	
		52159-47905	BUMPER REAR	1.00	\$458.60	25.00	\$343.95	Replace	Replace	DD
		90467-07211	BUMPER CLIPS	10.00	\$2.10	25.00	\$15.75	Replace	Replace	NEC
			PIXEL STICKER	2.00	\$60.00	0.00	\$120.00	Replace	Replace	NEC
		52023-12240	BUMPER REINFORCEMENT REAR	0.00	\$205.70	0.00	\$0.00	Replace	Check	X
		52015-47050	ARM SUB-ASSY. RR BUMPER RH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		52016-47030	ARM SUB-ASSY. RR BUMPER LH	0.00	\$139.60	0.00	\$0.00	Replace	Check	X
		89997-30070	ANTENNA, ELECTRICAL LOWER REAR SENSOR REVERSE	0.00	\$157.40	0.00	\$0.00	Replace	Check	X
		52576-47020	BUMPER SIDE RETAINER RR/LH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
		52575-47020	BUMPER SIDE RETAINER RR/RH	0.00	\$94.80	0.00	\$0.00	Replace	Not Given	X
		52592-47021	BUMPER SEAL, RR LH	0.00	\$88.90	0.00	\$0.00	Replace	Not Given	X
		52591-47021	BUMPER SEAL, RR RH	0.00	\$65.70	0.00	\$0.00	Replace	Not Given	X
		76086-47020	BUMPER LIP COVER RR/LH	0.00	\$72.20	0.00	\$0.00	Replace	Not Given	X
		76087-47020	BUMPER LIP COVER RR/RH	0.00	\$116.10	0.00	\$0.00	Replace	Not Given	X
		76091-47020	BUMPER LIP REAR	0.00	\$228.90	0.00	\$0.00	Replace	Not Given	X

	58308-47011	UNDER COVER SUB-ASSY, RR FLOOR	0.00	\$514.50	0.00	\$0.00	Replace	Not Given	X
	51442-12210	UNDER COVER RR SHIELD	0.00	\$63.90	0.00	\$0.00	Replace	Not Given	X
	89350-47030	TAILGATE DOOR LOCK	1.00	\$444.10	25.00	\$333.08	Replace	Replace	
Total				\$3,128.90		\$812.78			

su
su
Jam

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

812.78 (Parts)

- 202

650.22

+ 200.00

+ 516.88 } Labour

1367.10

4s \$1350/-

2 days



Case Details

Case Reference Number : TAX/12/15/2067
 Type of Repair : Accident Repair
 Vehicle Registration Number : SH85407Y

Company Type : SMRT Taxicab Pte Ltd
 Estimation ID : EST-9742-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 13/12/2019 04:15 PM
 Vehicle Age(in Months) : 44

Documents / Photographs

View Documents / Photographs

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

BOM Type	Coating Type	Portion	Material Number	Part Name	SMRT Recommendation					Repair Replace	Surveyor Approval			Remarks
					Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)		Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	
One Time Key In	Main			BUMPER REAR	1	458.80	458.80	25.00	343.95	Replace	1	343.95	Replace	✓ DP
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace	✓ NAC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace	✓ NAC
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check	✗ SVC
One Time Key In	Main			ARM SUB-ASSY, RH BUMPER RH	1	139.80	139.80	25.00	104.70	Replace	0	0	Check	✗ SVC
One Time Key In	Main			ARM SUB-ASSY, RH BUMPER LH	1	139.80	139.80	25.00	104.70	Replace	0	0	Check	✗ SVC
One Time Key In	Main			ANTENNA,ELECTRICAL LOWER REAR	1	157.40	157.40	25.00	118.05	Replace	0	0	Check	✗ SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✗ SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give	✗ SVC

Total Spare Part Cost 2,488.88

Surveyor Total 812.78

Lump Sum Discount (%) 25.00

Lump Sum Dis (%) 25

Final Spare Part Cost 1,864.89

Final Sur Total 602.22

SMRT Recommendation											Surveyor Approval			
BOM Type	Coating Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace	Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	88.70	88.70	25.00	66.53	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER R/LH	1	72.30	72.30	25.00	54.13	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP COVER R/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.90	514.90	25.00	386.18	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	83.90	83.90	25.00	62.93	Replace	0	0	Not Give	* X SVC
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.08	Replace	* / Jam

Total Spare Part Cost 2,480.98

Surveyor Total 812.78

Lump Sum Discount (%) 25.00

Lump Sum Dis (%) 25

Final Spare Part Cost 1,864.69

Final Sur Total 600.22

Labour's Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Coating Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

12/16/2019

https://vacswb.smrt.com.sg/Estimation.aspx

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	60.00	0	
4	Main	TO WASH AND VACUUM	80.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
Total:			656.88	316.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,584.88	660.22
Total Labour Cost	0.00	200.00
Total Spray Painting	0.00	200.00
Other	0.00	316.88
Overall Total	1,584.88	1,367.10
Lump Sum Repair Option		
Lump Sum Total	2,000.00	1,350.00
Surveyor Approved Amount		1,350.00
No of Repair Days*	4	2
Remarks		Lump sum repair. Take after spray photo.
Surveyor Name		Ben Pin (LKK)
Signature		

Save

Clear

Survey Date

16/12/2019

Repair day - 2 days.
4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Oi Sun Pin (LKK Auto)

From: Oi Sun Pin (LKK Auto)
Sent: Friday, 31 January, 2020 1:22 PM
To: 'Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)'
Subject: RE: SHB5407Y

Dear Poh Suan,

Confirm the finalize amount \$1,350. Repair day 2 days under lump sum repair.

Thank you.

Best Regards,
Oi Sun Pin | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 6256 3561 | Email: Sunpin@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis) [<mailto:YeoPohsuan@smrt.com.sg>]
Sent: Saturday, 18 January, 2020 11:31 AM
To: Oi Sun Pin (LKK Auto)
Cc: SUR; CS A Team
Subject: SHB5407Y

Hi Sun Pin,

Attached herewith the repair estimate of SHB 5407Y having Case No: TAX/12/19/2067.

There is no change to the approved amount of \$1,350 @ 2 working days under lump sum repair.

Cost of Repair invoice will be generated as approved.

Please finalize with me within 7 working day, thanks.

Thanks & Regards
Poh Suan

-----Original Message-----

From: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Sent: Saturday, 18 January 2020 11:23 AM
To: Yeo Poh Suan (Auto Svcs/ARC/ARC/Taxis)
Subject: Scan Data from FX-D421D6

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	369K
Vehicle Details	
Vehicle No.:	SHB5407Y
Vehicle to be Exported:	No
Intended Deregistration Date:	16 Dec 2019
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS TAXI (SMRT)
Primary Colour:	Maroon
Manufacturing Year:	2015
Engine No.:	2ZR1675601
Chassis No.:	JTDKN36U905767869
Maximum Power Output:	100.0 kW (134 bhp)
Open Market Value:	\$29,508.00
Original Registration Date:	08 Apr 2016
First Registration Date:	08 Apr 2016
Transfer Count:	0
Actual ARF Paid:	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	07 Apr 2024
PARF Rebate Amount:	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date:	07 Apr 2024
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$36,862.00
COE Rebate Amount:	\$19,858.00
Total Rebate Amount:	\$23,608.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 16 Dec 2019

OK



Case Details

Case Reference Number : TAX/12/19/2067
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB5407Y

Company Type : SMRT Taxis Pte Ltd
 Estimation ID : EST-9742-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : AIG Asia Pacific Insurance Pte Ltd
 Accident Date and Time : 13/12/2019 04:15 PM
 Vehicle Age(In Months) : 44

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 1

Estimation Details

Spare Part's Cost Detail

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER REAR	1	458.60	458.60	25.00	343.95	Replace	1	343.95	Replace * / PD
One Time Key In	Main			BUMPER CLIPS	10	2.10	21.00	25.00	15.75	Replace	10	15.75	Replace * / NEC
One Time Key In	Main			PIXEL STICKER	2	60.00	120.00	0.00	120.00	Replace	2	120.00	Replace * / NEE
One Time Key In	Main			BUMPER REINFORCEMENT REAR	1	205.70	205.70	25.00	154.27	Replace	0	0	Check * X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER RH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * X SVC
One Time Key In	Main			ARM SUB-ASSY. RR BUMPER LH	1	139.60	139.60	25.00	104.70	Replace	0	0	Check * X SVC
One Time Key In	Main			ANTENNA ELECTRICAL LOWER REAR	1	157.40	157.40	25.00	118.05	Replace	0	0	Check * X SVC
One Time Key In	Main			SENSOR REVERSE	1	180.00	180.00	0.00	180.00	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/LH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER SIDE RETAINER RR/RH	1	94.80	94.80	25.00	71.10	Replace	0	0	Not Give * X SVC

Total Spare Part Cost 2,480.86

Surveyor Total 812.78

Lump Sum Discount (%) 20.00

Lump Sum Dis (%) 20

Final Spare Part Cost 1,984.69

Final Sur Total 650.22

SMRT Recommendation											Surveyor Approval		
BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	List Price Per Unit(\$)	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity	Surveyor Final Price(\$)	Repair/Replace Remarks
One Time Key In	Main			BUMPER SEAL, RR LH	1	88.90	88.90	25.00	66.68	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER SEAL, RR RH	1	65.70	65.70	25.00	49.28	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP COVER RR/LH	1	72.20	72.20	25.00	54.15	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP COVER RR/RH	1	118.10	118.10	25.00	88.57	Replace	0	0	Not Give * X SVC
One Time Key In	Main			BUMPER LIP REAR	1	228.90	228.90	25.00	171.68	Replace	0	0	Not Give * X SVC
One Time Key In	Main			UNDER COVER SUB-ASSY, RR FLOOR	1	514.90	514.90	25.00	385.88	Replace	0	0	Not Give * X SVC
One Time Key In	Main			UNDER COVER RR SHIELD	1	83.90	83.90	25.00	47.92	Replace	0	0	Not Give * X SVC
One Time Key In	Main			TAILGATE DOOR LOCK	1	444.10	444.10	25.00	333.08	Replace	1	333.08	Replace * / Jam
Total Spare Part Cost									2,480.88	Surveyor Total 812.78			
Lump Sum Discount (%)									20.00	Lump Sum Dis (%) 20			
Final Spare Part Cost									1,984.60	Final Sur Total 650.22			

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION	338.00	200	✓
Total:			338.00	200.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	378.00	200	✓
2	Main	TO RESPRAY BUMPER BEAM	180.00	0	
Total:			558.00	200.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
-------	--------------	-----------	-------------------------	-------------------------	---------

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	20	
2	Main	TO REPLACE SUNDRY PARTS	100.00	0	
3	Main	TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0	
4	Main	TO WASH AND VACUUM	60.00	0	
5	Main	TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER(NET)	296.88	296.88	
Total:			656.88	316.88	

Summary

	Estimator Assessment(\$)	Surveyor Assessment(\$)
Total Spare Part Detail	1,984.89	650.22
Total Labour Cost	0.00	200.00
Total Spray Painting	0.00	200.00
Other	0.00	316.88
Overall Total	1,984.89	1,367.10
Lump Sum Repair Option		✓
Lump Sum Total	2,000.00	1,350.00
Surveyor Approved Amount		1,350.00
No of Repair Days*	4	2
Remarks		Lump sum repair. Take after spray photo.
Surveyor Name		Sun Pin (LKK)

Signature




Save

Clear

Survey Date

16/12/2019

Repair day - 2 days.

4/5

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	17 Dec 2019 Edit Reg		16 Dec 2019 00:00 Edit Adj Rpt	S\$1,350.00 Edit Estimates	S\$1,350.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	WONG YUEN SEN , ID: 51277800G								
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K								
Vehicle Reg. No.:	SHB5407Y	Date of Loss:	14/12/2019 00:00 - :59 44 Months and 6 Days From LTA Reg Date (Man Yr)						
Claim Type:	TP / 6962829042SG	Policy/Cover Note No.:	2100454592 (Comprehensive)						
Vehicle Reg. No. (Insured):	SLA3726Y	Policy No. (Claimant):	D-19093197MFSH						
	Excess:								
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628								
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Syed-Yusoff, Saliha] Saliha.Syed-Yusoff@aig.com								
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by OI SUN PIN] ... [Final Rpt due 27/12/2019]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
• AIG_SG_EXPRESS (14/02/2020): Alert - Adj Mandate Approved (S\$1829.62) - SHB5407Y - Claim Handler: Syed-Yusoff...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHB5407Y (6962829042SG)
[SLA3726Y]

TP

SMRT TAXIS PTE LTD

Dec 14 2019 12:00AM

[WONG YUEN SEN]

SMRT Automotive Services Pte Ltd

Upload Documents		Upload Photos	Compose New Letter	Upload Video	Upload Audio	View View in Browser v
Letters/Correspondences						1 per page v ☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown				Edit
Assessment Reports						1 per page v ☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	11/02/20 08:57	Adjuster Immediate Advice				Load HTM
Photos/Images						3 per page v ☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)			Thumbnail	Print
1	19/12/19 09:02	Chassis Number				Load JPG ☒
2	19/12/19 09:02	Odometer Reading				Load JPG ☒
3	19/12/19 09:02	General View				Load JPG ☒
4	19/12/19 09:02	General View				Load JPG ☒
5	19/12/19 09:02	General View				Load JPG ☒
6	19/12/19 09:02	General View				Load JPG ☒
7	19/12/19 09:02	General View				Load JPG ☒
8	19/12/19 09:02	General View				Load JPG ☒
9	19/12/19 09:02	General View				Load JPG ☒
10	19/12/19 09:02	General View				Load JPG ☒
11	19/12/19 09:02	General View				Load JPG ☒
12	19/12/19 09:02	General View				Load JPG ☒
13	19/12/19 09:02	General View				Load JPG ☒
14	19/12/19 09:02	General View				Load JPG ☒
15	19/12/19 09:02	General View				Load JPG ☒
16	19/12/19 09:02	General View				Load JPG ☒
17	19/12/19 09:02	General View				Load JPG ☒
18	19/12/19 09:02	General View				Load JPG ☒
19	19/12/19 09:02	General View				Load JPG ☒
20	19/12/19 09:02	General View				Load JPG ☒
21	19/12/19 09:02	General View				Load JPG ☒
22	19/12/19 09:03	General View				Load JPG ☒
23	19/12/19 09:03	General View				Load JPG ☒
24	19/12/19 09:03	General View				Load JPG ☒
25	19/12/19 09:03	General View				Load JPG ☒
26	19/12/19 09:03	General View				Load JPG ☒
27	19/12/19 09:03	General View				Load JPG ☒
28	19/12/19 09:03	General View				Load JPG ☒
29	19/12/19 09:03	General View				Load JPG ☒
30	19/12/19 09:03	General View				Load JPG ☒
31	19/12/19 09:03	General View				Load JPG ☒
32	19/12/19 09:03	General View				Load JPG ☒
33	19/12/19 09:03	General View				Load JPG ☒
34	19/12/19 09:03	General View				Load JPG ☒
35	31/01/20 13:39	After Repair Photo				Load JPG ☒
36	31/01/20 13:39	After Repair Photo				Load JPG ☒

Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
37	31/01/20 13:39	After Repair Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	17/12/19 17:16	TP GIA REPORT.	 Load PDF	
2	17/12/19 17:17	TP ESTIMATE- MARKED	 Load PDF	
3	05/02/20 12:56	TP ESTIMATE - MARKED (FINAL)	 Load PDF	
4	10/02/20 17:51	LOD	 Load PDF	
5	11/02/20 08:39	RENTAL RECEIPT	 Load PDF	
6	11/02/20 08:39	LTA SEARCH FEE	 Load PDF	
7	04/03/20 10:15	WORKSHOP INVOICE	 Load PDF	
8	04/03/20 10:15	AUTHORISATION TO ACT FORM	 Load PDF	
9	04/03/20 10:15	Release Voucher	 Load PDF	
10	04/03/20 10:15	LETTER TO OI	 Load PDF	
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	19/12/19 15:17	OI GIA REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SLA3726Y (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHB5407Y (TP veh)		
Date of Accident:	14/12/2019		

Global Sum Settlement	:	☐ Yes	☒ No
Repair Estimate	:	\$	4,760.68
Final Repair Cost	:	\$	1,350.00
Loss of Use	:	\$	150.00
Rental (if any)	:	\$	322.62
LTA / GIA Search Fee	:	\$	7.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	1,829.62

3.00 days at \$50.00 per day
3 days

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability ____ 100 ____ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: ____

BOLA Liability: ____ (%) Assessed Liability (*): ____ 0 ____ (%)

* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks _____

Payment Instruction: Payee's Breakdown			
1)	SMRT Taxis Pte Ltd	:	\$ 1,829.62
2)		:	\$
3)		:	\$
4)		:	\$

JOANNE LEE KHANG MIN

04 Mar
2020

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022159/QDS3Q2

Date: 04/03/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100454592
 Claimant SHB5407Y Insured Vehicle No : SLA3726Y
 Vehicle No : SHB5407Y
 Date of Loss: 14/12/2019 Nature of Claim: TP Claim No: 6962829042SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHB5407Y
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZR1675601
 Reg. Date: 08/04/2016 (Man. Year: 2015) Chassis No: JTDKN36U905767869
 Colour: Maroon Odometer: 403103 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 195/65 R15 Rear Tyre Size: 195/65 R15
 Front Left Side: West Lake 5 mm Rear Left Side: West Lake 5 mm
 Front Right Side: West Lake 5 mm Rear Right Side: West Lake 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,504.68	1,109.66	2,395.02	68.34
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,256.00	420.00	836.00	66.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,760.68	1,529.66	3,231.02	67.87
Approved Total (Overridden) (S\$)		1,350.00		
Nett Amount (S\$)	4,760.68	1,350.00	3,410.68	71.64
+ Loss of Use (3.0 x S\$50.00/day) (S\$)		150.00		
+ Car Rental (3.0 x S\$107.54/day) (S\$)		322.62		
+ Doc/Search Fee (S\$)		7.00		
Nett Liability (S\$)		1,829.62		

INSPECTION

Date of Assignment: 16/12/2019
 Date Inspected: 16/12/2019 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705

Estimated Period of Repair: 2.0 days

Adjuster: OI SUN PIN**Manager:** CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*ADVERTISEMENT STICKER (SN)	Necessary	296.88 F	*296.88 F
2	2		*PIXEL STICKER (SN)	Necessary	120.00 F	*120.00 F
3	1		*BUMPER REAR (DISC 25%)	Dented	458.60 F	*343.95 F
4	1		*BUMPER CLIPS (DISC 25%) (10 PCS)	Necessary	21.00 F	*15.75 F
5	1		*TAILGATE DOOR LOCK (DISC 25%)	Jammed	444.10 F	*333.08 F
6	1		*BUMPER REINFORCEMENT REAR	Serviceable	205.70 F	*- F
7	1		*ARM SUB-ASSY ,RR BUMPER RH	Serviceable	139.60 F	*- F
8	1		*ARM SUB-ASSY ,RR BUMPER LH	Serviceable	139.60 F	*- F
9	1		*ANTENNA ELECTRICAL LOWER REAR	Serviceable	157.40 F	*- F
10	1		*SENSOR REVERSE	Serviceable	180.00 F	*- F
11	1		*BUMPER SIDE RETAINER RR/LH	Serviceable	94.80 F	*- F
12	1		*BUMPER SIDE RETAINER RR/RH	Serviceable	94.80 F	*- F
13	1		*BUMPER SEAL ,RR LH	Serviceable	88.90 F	*- F
14	1		*BUMPER SEAL ,RR RH	Serviceable	65.70 F	*- F
15	1		*BUMPER LIP COVER RR/LH	Serviceable	72.20 F	*- F
16	1		*BUMPER LIP COVER RR/RH	Serviceable	118.10 F	*- F
17	1		*BUMPER LIP REAR	Serviceable	228.90 F	*- F
18	1		*UNDER COVER SUB-ASSY ,RR FLOOR	Serviceable	514.50 F	*- F
19	1		*UNDER COVER RR SHIELD	Serviceable	63.90 F	*- F

F=Franchise part.

Total Parts (\$\$)	3,504.68	1,109.66
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PANEL BEATING & BODY WORK	New	338.00	200.00
2	SPRAY PAINT	New	558.00	200.00
3	TO TEST AND REFIX REVERSE SENSOR SYSTEM	New	120.00	20.00
4	TO REPLACE SUNDRY PARTS	New	100.00	0.00
5	TO CHECK WIRING AND SYSTEM FUNCTION	New	80.00	0.00
6	TO WASH AND VACUUM	New	60.00	0.00
Gross Labour Cost (\$\$)			1,256.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >