

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:**

CC4/AIG19022164/R1RS3Q2

Date:

16/11/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

1800079732

Claimant Vehicle No : SJV5707C**Insured Vehicle No :**

SKM6521A

Date of Loss: 09/12/2019

Nature of Claim:

TP

Claim No:

3787954654SG

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SJV5707C**

Make & Model: HONDA CIVIC, 1.3 HYBRID MX (A)

Engine No:

LDA24010285

Reg. Date: 29/01/2010 (Man. Year: 2008)

Chassis No:

JHMF36209S202237

Colour: Purple

Odometer:

230216 km

Engine Capacity: 1339 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:

Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65 R15

Rear Tyre Size:

195/65 R15

Front Left Side: Dunlop 6 mm

Rear Left Side:

Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side:

Dunlop 6 mm

*The above values represent the remaining tyre treads depth***COST OF CLAIMS**

	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 16/12/2019 Inspected At:

Gold Autoworks Pte Ltd (HQ)
48 TOH GUAN ROAD EAST, #01-119 ENTERPRISE HUB
Singapore 608586

Estimated Period of Repair: 8.0 days

Adjuster: MOHD RASUL

Manager: Jaslin Kok Chin Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

MARKET VALUE:\$23,000.00

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Torn	0.00 F	*- F
2	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
3	1		*FRT BUMPER SIDE RETAINER (RH)	Necessary	0.00 F	*- F
4	1		*FRT BUMPER GRILLE	Deformed	0.00 F	*- F
5	1		*FRT RH BUMPER FOG LAMP COVER	Missing	0.00 F	*- F
6	1		*FRT RH BUMPER FOG LAMP	Missing	0.00 F	*- F
7	1		*FRT GRILLE	Cracked	0.00 F	*- F
8	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
9	1		*FRT RH HEADLAMP ASSY	Broken	0.00 F	*- F
10	1		*BONNET	Bent	0.00 F	*- F
11	1		*WIPER WASHER TANK	Deformed	0.00 F	*- F
12	1		*FRT RH FENDER	Bent	0.00 F	*- F
13	1		*FRT WINDSCREEN GLASS	Cracked	0.00 F	*- F
14	1		*FRT WINDSCREEN MOULDING	Necessary	0.00 F	*- F
15	1		*STEERING WHEEL AIRBAG	Activated	0.00 F	*- F
16	1		*STEERING WHEEL AIRBAG SENSOR	Necessary	0.00 F	*- F
17	1		*DASHBOARD AIRBAG	Activated	0.00 F	*- F
18	1		*DASHBOARD AIRBAG SENSOR	Necessary	0.00 F	*- F
19	1		*AIRBAG CONTROL UNIT	Necessary	0.00 F	*- F
					Total Parts (\$\$)	0.00
						0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >