

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022167/BEA3Q2

Date: 16/07/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1800038335

Claimant
Vehicle No : SLU8749T **Insured Vehicle No :** SMA9777Z

Date of Loss: 13/12/2019 Nature of Claim: TP Claim No: 8166763115SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLU8749T	Engine No:	CAW007541
Make & Model:	VOLKSWAGEN TIGUAN, 2.0 (A)	Chassis No:	WVGZZZ5NZ9W011046
Reg. Date:	25/09/2008 (Man. Year: 2008)	Odometer:	156340 km
Colour:	White		
Engine Capacity:	1984 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	235/50 R18	Rear Tyre Size:	235/50 R18
Front Left Side:	Sumitomo 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Sumitomo 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	34,194.25	17,787.40	16,406.85	47.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,080.00	3,480.00	1,600.00	31.50
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	39,274.25	21,267.40	18,006.85	45.85
Approved Total (Overridden) (S\$)		17,000.00		
Nett Amount (S\$)	39,274.25	17,000.00	22,274.25	56.71
+ Loss of Use (14.0 x S\$90.00/day) (S\$)		1,260.00		
+ Doc/Search Fee (S\$)		36.45		
+ Other Costs (S\$)		90.00		
Nett Liability (S\$)		18,386.45		

INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 17/12/2019 Inspected At:

Team Autopro Pte Ltd (KAKI BUKIT)
No.8 Kaki Bukit Avenue 4, #06-21
Premier@ Kaki Bukit (Gate 2)
Singapore 415875

Estimated Period of Repair: 11.0 days

Adjuster: Lim Teow Guan

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BONNET	Dented	1,863.70 FL	*1,120.00 FL
2	1		*BONNET INSULATOR	Dislodged	237.00 FL	*237.00 FL
3	2		*BONNET HINGE	Bent	370.40 FL	*210.00 FL
4	1		*BONNET LOCK	Jammed	144.30 FL	*144.30 FL
5	1		*BONNET UPPER CATCH	Bent	146.30 FL	*146.30 FL
6	1		*FRONT GRILLE ASSY	Missing	893.40 FL	*780.50 FL
7	1		*FRONT GRILLE EMBLEM VOLKSWAGEN	Necessary	58.90 FL	*58.90 FL
8	1		*FRONT BUMPER	Broken	1,652.80 FL	*902.00 FL
9	2		*FRONT BUMPER SIDE RETAINER	Necessary	373.00 FL	*170.00 FL
10	2		*FRONT BUMPER BRACKET	No such part	253.40 FL	*- FL
11	1		*FRONT BUMPER TOW COVER	Missing	189.60 FL	*16.00 FL
12	1		*FRONT BUMPER LOWER GRILLE	Missing	523.10 FL	*325.00 FL
13	2		*FRONT BUMPER AIR GUIDE	Missing	175.20 FL	*91.40 FL
14	2		*FRONT FOG LAMP	Missing	590.60 FL	*236.00 FL
15	2		*FRONT FOG LAMP GARNISH	No such part	708.40 FL	*- FL
16	1		*FRONT BUMPER REINFORCEMENT	Broken	689.50 FL	*450.00 FL
17	1		*FRONT BUMPER INNER SPONGE	Broken	186.40 FL	*160.00 FL
18	1		*FRONT SUPPORT PANEL	Broken	1,769.20 FL	*1,008.00 FL
19	1		*FRONT FENDER LH	Dented	1,983.50 FL	*899.00 FL
20	1		*FRONT FENDER INNER COWLING LH	Broken	358.10 FL	*290.00 FL
21	1		*AIR FILTER BOX	Broken	753.40 FL	*753.40 FL
22	1		*AIR DUCT	Distorted	368.20 FL	*266.00 FL
23	1		*BATTERY	Broken	486.50 FL	*250.00 FL
24	1		*BATTERY BRACKET	Broken	328.50 FL	*46.72 FL
25	1		*WIPER WASHER TANK	Dented	623.40 FL	*331.90 FL
26	2		*WIPER WASHER TANK MOTOR	Not Damaged	507.60 FL	*- FL
27	1		*ENGINE LOWER COVER	Broken	843.60 FL	*175.45 FL
28	1		*ENGINE COVER	Not Damaged	553.10 FL	*- FL
29	1		*THROTTLEBODY	Broken	583.70 FL	*360.13 FL
30	1		*INTAKE MONIFOLD	Broken	1,653.20 FL	*1,653.20 FL
31	1		*A/C CONDENSER	Broken	804.00 FL	*615.00 FL
32	1		*A/C CONDENSER HIGH PRESSURE PIPE	Broken	483.10 FL	*216.20 FL
33	1		*A/C CONDENSER LOW PRESSURE PIPE	Broken	452.00 FL	*89.09 FL
34	1		*RADIATOR	Broken	985.30 FL	*585.00 FL
35	1		*RADIATOR TOP HOSE	Distorted	459.20 FL	*165.08 FL
36	1		*RADIATOR BOTTOM HOSE	Bent	587.30 FL	*180.00 FL
37	1		*FUSE BOX ASSY	Not Damaged	1,980.00 FL	*- FL
38	1		*INTER COOLER	Broken	1,065.90 FL	*647.00 FL
39	2		*INTER COOLER PIPE	Broken	1,307.60 FL	*453.60 FL
40	1		*RADIATOR FAN ASSY	Broken	986.20 FL	*729.00 FL
41	1		*A/CON FAN ASSY	Broken	528.15 FL	*351.00 FL
42	1		*SET GEAR BOX MOUNTING	Broken	543.20 FL	*480.00 FL
43	2		*HEADLAMP	Broken	3,687.00 FL	*2,647.20 FL
44	2		*HEADLAMP LOWER BRACKET	No such part	257.00 FL	*- FL
45	1		*SUNDRIES	Necessary	80.00 FS	*- FS
46	1		*BONNET INSULATOR CLIP	Necessary	60.00 FS	*30.00 FS
47	1		*FRONT GRILLE CLIP	Necessary	60.00 FS	*30.00 FS
48	1		*FRONT BUMPER CLIP	Necessary	60.00 FS	*30.00 FS
49	1		*FRONT BUMPER LOWER GRILLE CLIP	Necessary	60.00 FS	*30.00 FS
50	4		*FRONT BUMPER SENSOR	Damaged	1,000.00 FS	*200.00 FS
51	1		*COOLANT	Not Necessary	80.00 FS	*- FS
52	1		*FRONT FENDER SEALANT	Necessary	80.00 FS	*30.00 FS
53	1		*FRONT FENDER INNER COWLING CLIP LH	Necessary	60.00 FS	*30.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*A/C CONDENSER FLUID	Necessary	80.00 FS	*40.00 FS
55	1		*RADIATOR COOLANT	Necessary	80.00 FS	*40.00 FS
56	2		*HEADLAMP SEAL	Not Necessary	200.00 FS	*- FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
				Sub Total (\$\$)	35,893.95	18,699.37
				- List Item Discount on L Items 5.00/5.00% (\$\$)	1,699.70	911.97
				Total Parts (\$\$)	34,194.25	17,787.40

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	R&R RADIATOR	New	150.00	80.00
2	R&R A/C CONDENSER	New	150.00	80.00
3	R&R FRONT BUMPER SENSOR	New	100.00	60.00
4	R&R FUSE BOX	New	150.00	50.00
5	R&R INTAKE MONIFOLD	New	150.00	50.00
6	R&R GEAR BOX MOUNTING	New	150.00	50.00
7	DIAGNOSTIC & RESET FAULT CODES	New	300.00	100.00
8	PANEL BEAT	New	1,800.00	1,600.00
9	RUST PROOFING	New	100.00	60.00
10	SPRAY PAINTING	New	1,800.00	1,300.00
11	CHECK WIRING	New	150.00	50.00
12	CONDUCT WATER LEAKAGE TEST	New	80.00	0.00
Gross Labour Cost (\$\$)			5,080.00	3,480.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >