

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
AXA INSURANCE PTE LTD			Ref : CC4/ASM19022181/Aps3q2		
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811 ATTN:KIAN CHUAN			Date: 29-06-2020 Code: ASM		
1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SFW 7007T	Veh. Inspected	SKN 6377U	
	Policy No.	GA486610	Coverage (\$)	0.00	
	Claim No.	S9M02ABY	Excess (\$)	0.00	
	Assign From		Assign Date	17/12/2019	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA ODYSSEY	c.c	2356	
	Engine No.	HIDDEN	Year of Reg.	2014	
	Chassis No.	JHMRC1890EC202071	Colour	GREY	
	Odometer	-	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3. Conditions of Tyres					
		Size	Make	Balance	
	R/H Front Tyre	215/55 R17	PIRELLI	6 mm	
	L/H Front Tyre	215/55 R17	PIRELLI	6 mm	
	R/H Rear Tyre	215/55 R17	PIRELLI	6 mm	
	L/H Rear Tyre	215/55 R17	PIRELLI	6 mm	
4.					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	15/12/2019	Inspection Date	17/12/2019	
	Survey held at	HUA MENG SPRAY PAINTING WORKSHOP			
		1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883			
5a.	Remarks				
		A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days				