

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022198/KEA3Q2
Date: 30/10/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:
Claimant
Vehicle No : JSB3294 **Insured Vehicle No :** SLA4391Y
Date of Loss: 14/12/2019 Nature of Claim: TP Claim No: 2579255055SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **JSB3294**
Make & Model: TOYOTA VIOS, 1.5 E (A) Engine No: 2NR0N10018
Reg. Date: 28/03/2017 (Man. Year: 2017) Chassis No: PN153SYF103011872
Colour: Metallic Red Odometer: 43986 km
Engine Capacity: 1496 cc
Market Value/New Car Price: N/A
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition: Yes

CONDITION OF TYRES

Front Tyre Size: 185/60 R15 Rear Tyre Size: 185/60 R15
Front Left Side: Continental 8 mm Rear Left Side: Continental 8 mm
Front Right Side: Continental 8 mm Rear Right Side: Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	15,738.60	11,065.06	4,673.54	29.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,760.00	4,870.00	1,890.00	27.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	22,498.60	15,935.06	6,563.54	29.17
Approved Total (Overridden) (S\$)		12,200.00		
Nett Amount (S\$)	22,498.60	12,200.00	10,298.60	45.77
+ Loss of Use (21.0 x S\$30.00/day) (S\$)		630.00		
		12,830.00		

INSPECTION

Date of Assignment: 17/12/2019
Date Inspected: 17/12/2019 Inspected At: AE AUTP PTE LTD
160 Sin Ming Drive #06-01., Sin Ming
AutoCity
Singapore 575722
Estimated Period of Repair: 21.0 days

Adjuster: KENNETH KONG

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET ASSY	Bent	1,119.40 FL	*1,119.40 FL
2	1		*FRONT BONNET HINGES	Repair	121.10 FL	*- FL
3	1		*FRONT BONNET LOCK	Repair	167.80 FL	*- FL
4	1		*FRONT BONNET TOP INSULATOR	Serviceable	46.80 FL	*- FL
5	1		*FRONT HEADLAMP ASSY R & LH	N/S Cracked	1,873.40 FL	*936.70 FL
6	1		*FRONT GRILLE	Cracked	325.00 FL	*325.00 FL
7	1		*FRONT GRILLE LOGO	Necessary	38.00 FL	*38.00 FL
8	1		*FRONT GRILLE CHROME	Necessary	78.30 FL	*78.30 FL
9	1		*FRONT BUMPER	Bent	737.50 FL	*737.50 FL
10	1		*FRONT BUMPER BEAM	Serviceable	562.40 FL	*- FL
11	1		*FRONT BUMPER SIDE RETAINER	N/S Distorted	222.50 FL	*111.25 FL
12	2		*FRONT BUMPER BRACKET	Serviceable	208.70 FL	*- FL
13	1		*FRONT BUMPER CENTRE GRILLE	Cracked	296.60 FL	*296.60 FL
14	2		*FRONT BUMPER SIGNAL LAMP	Serviceable	84.80 FL	*- FL
15	2		*FRONT BUMPER SIGNAL LAMP GARNISH	Serviceable	149.20 FL	*- FL
16	2		*FRONT BUMPER SPORT LAMPS	Serviceable	289.30 FL	*- FL
17	1		*FRONT SUPPORT PANEL	Repair	885.00 FL	*- FL
18	1		*AIR CONDENSER SIDE AIR GARNISH	N/S Cracked	180.00 FL	*90.00 FL
19	1		*FRONT FENDER (NPA)	Repair	0.00 FL	*- FL
20	1		*BOOTLID	Bent	1,250.00 FL	*1,250.00 FL
21	1		*BOOTLID HINGES	N/S Bent	380.00 FL	*190.00 FL
22	1		*BOOTLID LOCK	Bent	220.00 FL	*220.00 FL
23	1		*BOOTLID OUTER MOULDING	Warped	180.00 FL	*180.00 FL
24	1		*BOOTLID WEATHERSTRIP	Distorted / Cut	80.00 FL	*80.00 FL
25	1		*BOOTLID CENTRE LOGO	Necessary	68.00 FL	*68.00 FL
26	1		*BOOTLID VIOS EMBLEM	Necessary	68.00 FL	*68.00 FL
27	1		*BOOTLID E EMBLEM	Necessary	55.00 FL	*55.00 FL
28	1		*BOOT CABLE	Serviceable	135.00 FL	*- FL
29	1		*BOOT LID TOP GARNISH	Distorted	265.00 FL	*265.00 FL
30	2		*TAILLAMP RH & LH	Cracked	1,520.00 FL	*1,520.00 FL
31	1		*TAILLAMP INNER PANEL RH & LH	Bent	680.00 FL	*680.00 FL
32	1		*REAR END PANEL (NPA)	Serviceable	0.00 FL	*- FL
33	1		*REAR SPARE TYRE SIDE SPONGE	Deformed	140.00 FL	*140.00 FL
34	1		*REAR END PANEL TOP GARNISH	Repeated	265.00 FL	*- FL
35	1		*REAR SPARE TYRE PANEL	Bent / Buckled	880.00 FL	*880.00 FL
36	1		*REAR SPARE CARDBOARD	Cracked	285.00 FL	*285.00 FL
37	1		*REAR SPARE TYRE CARDBOARD TOP GARNISH	Cracked	365.00 FL	*365.00 FL
38	1		*REAR BUMPER	Bent	1,150.00 FL	*1,150.00 FL
39	2		*REAR BUMPER SIDE RETAINER	Cracked	128.00 FL	*128.00 FL
40	2		*REAR BUMPER BRACKETS	Distorted	110.00 FL	*110.00 FL
41	2		*REAR BUMPER BEAM	Bent	325.00 FL	*325.00 FL
42	1		*REAR BUMPER REFLECTORS	N/S Cracked	680.00 FL	*340.00 FL
43	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
44	1		*SET REAR NO PLATE LAMP	Serviceable	285.00 FL	*- FL
45	1		*REAR FENDER -LH	Buckled	1,120.00 FL	*1,120.00 FL
46	2		*REAR FENDER INNER GARNISH	Deformed	710.00 FL	*710.00 FL
47	1		*REAR FENDER -RH (NPA)	Repair	0.00 FL	*- FL
48	1		*REAR W/SCREEN MOULDING MLDG	Necessary	185.00 FL	*185.00 FL
49	1		*REAR FENDER MUDFLAP	Cracked	135.00 FL	*135.00 FL
50	1		*SET REAR SPARE TYRE OPENER	Dented	145.00 FL	*145.00 FL
51	1		*REAR EXHAUST PIPE	Repair	750.00 FL	*- FL
52	1		*SET FRONT & REAR NO PLATE	Dented	120.00 FS	*90.00 FS
53	1		*SET REAR BUMPER SENSOR	Dented / Shorted	380.00 FS	*200.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
54	1		*REAR SPARE TYRE	Serviceable	250.00 FS	*- FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	20,734.80	14,656.75
					- List Item Discount on L Items 25.00/25.00% (\$\$)	4,996.20	3,591.69
					Total Parts (\$\$)	15,738.60	11,065.06

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	LABOUR CHARGE	New	800.00	500.00
2	SPRAY PAINTING ON AFFECTED AREA	New	800.00	600.00
3	ANTI-RUST	New	100.00	30.00
4	TO REMOVE AIR CON CONDENSER & TOP UP FEON GAS	New	120.00	0.00
5	TO CHECK WIRING SYSTEM FORCUS HEADLAMPS & ETC	New	130.00	20.00
6	LABOUR CHARGES	New	2,000.00	1,800.00
7	SPRAY PAINTING WHOLE EXTERIOR AND INTERIOR	New	1,500.00	1,200.00
8	TRANSFER OLD BOOT LID TO ANOTHER NEW BOOT	New	120.00	60.00
9	ANTI-RUST	New	120.00	120.00
10	TO CHECK WIRING & CHECK LEAKING	New	90.00	20.00
11	TO REPLACE REAR SENSOR	New	90.00	50.00
12	REPLACE REAR EXHAUST PIPE	New	180.00	60.00
13	TO REMOVE & REFIT BOOT GARNISH ,CARPER & SIDE TRIM	New	280.00	100.00
14	TO BODY CHASSIS ALIGNMNET	New	300.00	250.00
15	TO REMOVE & REFIT PETROL TANK	New	130.00	60.00
			Gross Labour Cost (\$)	4,870.00
				6,760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >