



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKF 9399D

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FACE ASSY ,RR.BUMPER (SN)	DEFORMED	462.90	462.90
1	BEAM COMPRR.BUMPER (SN)	NOT NECESSARY	135.00	-
8	CLIP.BUMPER (SN)	NECESSARY	13.80	13.80
1	GARNISH ,RR.BUMPER LOWER (SN)	DEFORMED	29.85	29.85
1	SPACERR.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	SPACERL.RR.BUMPER SIDE (SN)	NOT NECESSARY	8.62	-
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			708.79	526.55
	<u>LABOUR</u>			
	INSPECT RR LIGHTING MECHANISMS .PERFORM WATER.	NOT NECESSARY	180.00	-
	REMOVE & INSTALL REVERSE SENSORS.		180.00	130.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.		1,000.00	560.00
	SPRAY PAINTING ON REPAIRED OR RPELACED AREAS.		1,100.00	450.00
			2,460.00	1,140.00
GRAND TOTAL			3,168.79	1,666.55

RECOMMENDED COST OF REPAIRS			1,666.55
------------------------------------	--	--	-----------------

Report Ref No. CC4/FCI19022200/Aea3q2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.