

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III19022206/KPS3Q2

Date: 09/07/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLB2457A	Insured Vehicle No :	SHD3354T
Date of Loss: 13/12/2019	Nature of Claim: TP	Claim No: MCT19120298

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB2457A		
Make & Model:	NISSAN QASHQAI, 1.2 DIG-T CVT ABS 2WD 5DR (A)	Engine No:	HRA2237843A
Reg. Date:	31/03/2016 (Man. Year: 2015)	Chassis No:	SJNFEAJ11U1588915
Colour:	Metallic Black	Odometer:	85967 km
Engine Capacity:	1197 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R17	Rear Tyre Size:	215/60 R17
Front Left Side:	Continental 3 mm	Rear Left Side:	Continental 4 mm
Front Right Side:	Continental 3 mm	Rear Right Side:	Continental 4 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,424.58	3,914.56	510.02	11.53
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,420.00	1,870.00	550.00	22.73
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,844.58	5,784.56	1,060.02	15.49
Approved Total (Overridden) (S\$)		4,600.00		
(S\$)	6,844.58	4,600.00	2,244.58	32.79
+ GST 7.00/7.00% (S\$)	479.12	322.00	157.12	32.79
Nett Amount (S\$)	7,323.70	4,922.00	2,401.70	32.79
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		5,349.45		
Global Sum Settlement (S\$)		5,300.00		

INSPECTION

Date of Assignment:	19/12/2019	
Date Inspected:	19/12/2019	Inspected At: Optima Werkz Pte Ltd (HQ) 9A Serangoon North Ave 5 Singapore 554500
Estimated Period of Repair:	7.0 days	

Adjuster: KENNETH KONG**Manager:** CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 26 Jun 2020)
Parts:	M1-SUV	NISSAN QASHQAI 1.2 DIG-T CVT ABS 2WD 5DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB2457A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*REAR TAILGATE	Bent	2,867.50 FL	*2,867.50 FL
2	1	*REAR TAILGATE INNER LOCK	Dented	203.28 FL	*203.28 FL
3	1	*REAR TAILGATE QASHQAI EMBLEM	Necessary	105.75 FL	*105.75 FL
4	1	*REAR WINDSCREE MOULDING	Necessary	128.60 FL	*128.60 FL
5	8	*REAR TAILGATE INNER TRIM CLIPS	Not Necessary	52.00 FL	*- FL
6	1	*REAR END PANEL	Bent	703.50 FL	*650.40 FL
7	1	*REAR END PANEL UPPER TRIM COVERING	Distorted	129.25 FL	*129.25 FL
8	6	*REAR END PANEL UPPER TRIM COVERING CLIPS	Necessary	39.00 FL	*39.00 FL
9	1	*REAR BUMPER	Bent	1,240.50 FL	*717.00 FL
10	10	*REAR BUMPER CLIPS	Necessary	58.00 FL	*58.00 FL
11	1	*REAR BUMPER REFLECTOR LH	Distorted	87.50 FL	*87.50 FL
12	1	*REAR BUMPER SIDE BRACKET LH	Distorted	48.80 FL	*48.80 FL
13	1	*REAR SPARE TYRE PANEL (NPA)	Repair	0.00 FL	*- FL
14	1	*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
15	2	*REAR WINDSCREEN STOPPER	Serviceable	30.00 FS	*- FS
16	1	*REAR BUMPER REVERSE SENSOR	Dented	350.00 FS	*350.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,123.68	5,425.08
- List Item Discount on L Items 30.00/30.00% (\$\$)	1,699.10	1,510.52
Total Parts (\$\$)	4,424.58	3,914.56

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGES TO REMOVE,REPLACE ,REPAIR ,READJUST REAR ACCIDENT AREAS & ETC	New	800.00	750.00
2	LABOUR CHARGES TO REMOVE & REFIX ,REPLACE REAR WINDSCREEN GLASS ,REAR WINDSCREEN SEALANT ,REAR WINDSCREEN MOULDING & ETC	New	150.00	120.00
3	LABOUR CHARGES TO REMOVE & REINSTALLED REAR TAILGATE INNER MECHANISM & ETC	New	150.00	60.00
4	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR TAILGATE ,REAR END PANEL ,REAR BUMPER & ETC	New	900.00	800.00
5	LABOUR CHARGES TO DISCONNECT & RECONNECT REAR WIRING SYSTEMS & ETC	New	120.00	20.00
6	TO TUFF KOTE & UNDERSEAL MATERIALS	New	200.00	60.00
7	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC	New	100.00	60.00
Gross Labour Cost (\$\$)			2,420.00	1,870.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >