

LKK Auto Consultants Pte Ltd

LKK Auto Consultants Pte I
51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJR 1643A

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	DENTED	877.20	724.00
1	REAR BUMPER REFLECTOR (LEFT)	SERVICEABLE	38.00	-
1	REAR BUMPER SIDE RETAINER (LEFT)	BROKEN	30.00	30.00
1	REAR BUMPER BRACKET (LEFT)	SERVICEABLE	34.80	-
1	REAR BUMPER REVERSE SENSOR	SERVICEABLE	300.00	-
1	REAR BUMPER REINFORCEMENT	SERVICEABLE	289.00	-
1	REAR END PANEL	TO REPAIR SEE LABOUR	599.30	-
	LESS 10% DISCOUNT		-	-75.40
			2,168.30	678.60
	SPECIAL NETT ITEMS			
1	REAR BUMPER LOWER LIP (SN)	CRUMPLED	650.00	480.00
	,		650.00	480.00
	<u>LABOUR</u>			
	TO CHECK REAR LIGHTINGS AND ELECTRICAL WIRING SYSTEM INCLUDE PERFORMING WATER LEAKAGE TEST.	NOT NECESSARY	80.00	-
	TO PROVIDE LABOUR, WORKMANSHIP TO RE-ALIGN, CUTTING REAR END PANEL, DISMANTLE & REPLACE THE ABOVE MENTIONED PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		900.00	280.00
	LABOUR FOR RESPRAY REAR END PANEL, REAR BOOT LID COVER, REAR BUMPER AND REAR BUMPER LOWER LIP.		1,000.00	300.00
	TO SPRAY ANTI-RUST COATING ON NEW & AFFECTED PANEL.	NOT NECESSARY	200.00	-
	TO REMOVE AND REINSTALL REAR REVERSE SENSOR.		80.00	40.00
			-	-
			2,260.00	620.00
	GRAND TOTAL		5,078.30	1,778.60

Report Ref No. CS/INC19022207/Qsf3e2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		1,400.00
(TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)		

Report Ref No. CS/INC19022207/Qsf3e2

Jæ

OI SUN PIN

Asst. Automotive Assessor

L

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser