

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG19022213/KBA3Q2
Date: 23/03/2021

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1900107853
Claimant Vehicle No :	SHD5262L	Insured Vehicle No :	SJR5408L
Date of Loss:	11/12/2019	Nature of Claim:	TP
		Claim No:	8001409390SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHD5262L		
Make & Model:	TOYOTA PRIUS, 1.8 5DR HATCHBACK (A)	Engine No:	2ZR2B80237
Reg. Date:	12/12/2018 (Man. Year: 2018)	Chassis No:	JTDKB3FU103077327
Colour:	Metallic White/Red	Odometer:	93563 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Giti 9 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	64,975.93	9,801.98	55,173.95	84.91
Miscellaneous Items	0.00	0.00	0.00	
Labour	25,080.00	4,520.00	20,560.00	81.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	90,055.93	14,321.98	75,733.95	84.10
+ GST 7.00/7.00% (\$\$)	6,303.92	1,002.54	5,301.38	84.10
Nett Amount (\$\$)	96,359.85	15,324.52	81,035.33	84.10
+ Loss of Use (15.0 x S\$50.00/day) (\$\$)		750.00		
+ Car Rental (15.0 x S\$113.40/day) (\$\$)		1,701.00		
+ Doc/Search Fee (\$\$)		7.49		
Nett Liability (\$\$)		17,783.01		

INSPECTION

Date of Assignment:	13/12/2019		
Date Inspected:	13/12/2019	Inspected At:	Trans-cab Auto Services Pte Ltd No 2 Ang Mo Kio Street 63 Singapore 569111
Estimated Period of Repair:	11.0 days		

3/23/2021

Adjuster Report

Adjuster: KENNETH KONG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Bent	442.61 FL	*442.61 FL
2	1		*REAR BUMPER REINFORCEMENT	Bent	332.70 FL	*332.70 FL
3	1		*REAR BUMPER TOWING COVER	Dented	15.40 FL	*15.40 FL
4	1		*REAR BUMPER UNDER COVER (BLACK)	Bent	576.30 FL	*576.30 FL
5	1		*ANTENNA ELECTRICAL KEY	Serviceable	72.00 FL	*- FL
6	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	116.50 FL	*- FL
7	1		*REAR BUMPER SIDE RETAINER RH	Cracked	117.70 FL	*117.70 FL
8	1		*REAR BUMPER SIDE LH	Serviceable	123.70 FL	*- FL
9	1		*REAR BUMPER SIDE RH	Cracked	123.70 FL	*123.70 FL
10	1		*REAR TAILGATE	Bent	1,147.80 FL	*1,147.80 FL
11	1		*REAR TAILGATE OUTER GARNISH	Cracked	925.60 FL	*925.60 FL
12	1		*COVER ,REAR COMBINATION LAMP ,RH	Serviceable	64.50 FL	*- FL
13	1		*BOARD ASSY ,BACK DOOR TRIM	Serviceable	259.20 FL	*- FL
14	1		*REAR TAILGATE WEATHERSTRIP	Serviceable	372.30 FL	*- FL
15	1		*MOULDING ,BACK DOOR OUTSIDE GARNISH ,LOWER RH	Serviceable	56.50 FL	*- FL
16	1		*BOARD ,BACK DOOR TRIM	Serviceable	225.20 FL	*- FL
17	1		*PANEL SUB-ASSY ,BODY LOWER BACK	Bent	650.30 FL	*650.30 FL
18	1		*TAILLAMP LOWER RH	Cracked	502.00 FL	*502.00 FL
19	1		*TAILLAMP UPPER RH	Not Necessary	451.80 FL	*- FL
20	1		*TAILLAMP LOWER LH	Serviceable	502.00 FL	*- FL
21	1		*TAILLAMP UPPER LH	Serviceable	443.30 FL	*- FL
22	1		*PANEL ASSY ,DECK TRIM SIDE ,RH	Serviceable	355.90 FL	*- FL
23	1		*BOX ,DECK FLOOR ,RH	Serviceable	313.60 FL	*- FL
24	1		*BOX ,DECK FLOOR ,LH	Serviceable	313.00 FL	*- FL
25	1		*BOARD ,REAR FLOOR ,NO.1	Repair	519.00 FL	*- FL
26	1		*BOX ,DECK FLOOR REAR	Serviceable	105.80 FL	*- FL
27	1		*PANEL ASSY ,DECK TRIM SIDE ,LH	Repair	355.90 FL	*- FL
28	1		*PANEL SUB ASSY ,QUARTER ,RH	Repair	854.80 FL	*- FL
29	1		*LINER ,REAR WHEEL HOUSE ,RH	Repair	139.80 FL	*- FL
30	1		*SEAL ,REAR BUMPER SIDE ,RH	Serviceable	88.50 FL	*- FL
31	1		*DUCT ASSY ,QUARTER VENT ,RH	Dented	67.00 FL	*67.00 FL
32	1		*COVER ,FLOOR UNDER ,NO.1	Serviceable	175.10 FL	*- FL
33	1		*COVER ,FLOOR UNDER ,NO.2	Serviceable	241.90 FL	*- FL
34	1		*COVER ,REAR FLOOR	Serviceable	229.90 FL	*- FL
35	1		*COVER ,DECK TRIM ,REAR	Serviceable	126.70 FL	*- FL
36	1		*PIPE ASSY ,EXHAUST ,TAIL	Repair	1,655.40 FL	*- FL
37	1		*SUPPORT ,EXHAUST PIPE ,NO.4	Serviceable	49.10 FL	*- FL
38	1		*SUPPORT ,EXHAUST PIPE ,NO.5	Serviceable	49.10 FL	*- FL
39	1		*GASKET ,EXHAUST PIPE	Serviceable	53.50 FL	*- FL
40	1		*PAN ,REAR FLOOR	Repair	583.40 FL	*- FL
41	1		*EXTENSION ,REAR FLOOR SIDE PANEL ,RH	Repair	78.30 FL	*- FL
42	1		*EXTENSION ,REAR FLOOR PAN TO QUARTER PANE, RH	Repair	196.50 FL	*- FL
43	1		*TROUGH ,BACK DOOR OPENING RH	Serviceable	103.40 FL	*- FL
44	1		*ARM ASSY ,TRAILING ,REAR RH	Serviceable	370.40 FL	*- FL
45	1		*ARM ASSY ,UPPER CONTROL ,REAR RH	Serviceable	420.80 FL	*- FL
46	1		*ARM ASSY ,REAR SUSPENSION ,NO.1 RH	Serviceable	239.20 FL	*- FL
47	1		*ARM ASSY ,REAR SUSPENSION ,NO.2 RH	Serviceable	497.50 FL	*- FL
48	1		*WIRE ,SKID CONTROL SENSOR ,RH	Serviceable	94.70 FL	*- FL
49	1		*CARRIER SUB ASSY ,REAR AXLE, RH	Serviceable	953.60 FL	*- FL
50	1		*HUB & BEARING ASSY ,REAR AXLE ,RH	Serviceable	725.60 FL	*- FL
51	1		*DISC ,REAR	Serviceable	450.70 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
52	1		*CYLINDER ASSY ,DISC BRAKE ,REAR RH	Serviceable	1,001.90 FL	*- FL
53	1		*ABSORBER ASSY ,SHOCK ,REAR RH	Serviceable	127.00 FL	*- FL
54	1		*SUPPORT ASSY ,REAR SUSPENSION ,RH	Serviceable	149.30 FL	*- FL
55	1		*WIRE ,BACK DOOR, NO.2	Serviceable	294.40 FL	*- FL
56	1		*WIRE ,LUGGAGE ROOM ,NO.3	Serviceable	170.70 FL	*- FL
57	1		*WIRE ,ENGINE ROOM MAIN	Serviceable	7,323.90 FL	*- FL
58	1		*WIRE ,ENGINE	Serviceable	2,577.20 FL	*- FL
59	1		*PANEL SUB ASSY ,FRONT DOOR ,RH	Repair	1,287.40 FL	*- FL
60	1		*MIRROR ASSY ,OUTER REAR VIEW ,RH	Serviceable	1,436.60 FL	*- FL
61	1		*HINGE ASSY ,FRONT DOOR ,UPPER RH	Repair	97.50 FL	*- FL
62	1		*HINGE ASSY ,FRONT DOOR ,LOWER RH	Repair	110.60 FL	*- FL
63	1		*CHECK ASSY ,FRONT DOOR	Serviceable	183.80 FL	*- FL
64	1		*WEATHERSTRIP ,FRONT DOOR ,RH	Serviceable	231.30 FL	*- FL
65	1		*RUN ,FRONT DOOR GLASS ,RH	Serviceable	153.60 FL	*- FL
66	1		*WEATHERSTRIP ,FRONT DOOR OPENING TRIM RH	Serviceable	321.10 FL	*- FL
67	1		*MOULDING ASSY ,FRONT DOOR BELT RH	Serviceable	92.00 FL	*- FL
68	1		*TAPE,BLACK OUT NO.1 RH	Not Necessary	13.30 FL	*- FL
69	1		*TAPE,BLACK OUT NO.2 RH	Not Necessary	43.50 FL	*- FL
70	1		*TAPE,BLACK OUT NO.3 RH	Not Necessary	26.30 FL	*- FL
71	1		*WIRE ,FRONT DOOR, RH	Serviceable	532.80 FL	*- FL
72	1		*MOULDING ASSY ,BODY ROCKER PANEL ,RH	Serviceable	594.80 FL	*- FL
73	1		*FRONT BUMPER	Buckled	516.00 FL	*516.00 FL
74	1		*BRACKET ,FRONT BUMPER EXTENSION MOUNTING	Serviceable	103.40 FL	*- FL
75	1		*REINFORCEMENT ,FRONT BUMPER	Serviceable	716.60 FL	*- FL
76	1		*REINFORCEMENT ,FRONT BUMPER ,NO.2	Serviceable	246.10 FL	*- FL
77	1		*ABSORBER ,FRONT BUMPER ,LOWER	Serviceable	132.70 FL	*- FL
78	1		*ABSORBER ,FRONT BUMPER ENERGY	Serviceable	79.60 FL	*- FL
79	1		*FRONT BUMPER SIDE RETAINER RH	Distorted	80.10 FL	*80.10 FL
80	1		*FRONT BUMPER SIDE RETAINER LH	Serviceable	82.30 FL	*- FL
81	1		*COVER SUB-ASSY ,ENGINE ,NO.1	Serviceable	472.40 FL	*- FL
82	1		*COVER SUB-ASSY ,ENGINE UNDER ,NO.2	Serviceable	241.90 FL	*- FL
83	1		*EXTENSION ,FRONT BUMPER ,RH	Repair	120.10 FL	*- FL
84	1		*EXTENSION ,FRONT BUMPER ,LH	Repair	120.10 FL	*- FL
85	1		*COVER ,FRONT BUMPER HOLE ,LH	Serviceable	29.30 FL	*- FL
86	1		*COVER ,FRONT BUMPER HOLE ,RH	Serviceable	29.30 FL	*- FL
87	1		*FRONT LED LAMP (LOWER) RH	Serviceable	951.40 FL	*- FL
88	1		*FRONT HEADLAMP RH	Serviceable	2,637.60 FL	*- FL
89	1		*COMPUTER SUB-ASSY ,HEADLAMP ,LH NO.1	Serviceable	960.50 FL	*- FL
90	1		*MOTOR ,HEADLAMP LEVELING ,LH	Serviceable	487.50 FL	*- FL
91	1		*FRONT LED LAMP (LOWER) RH	Cracked	951.40 FL	*951.40 FL
92	1		*FRONT HEADLAMP RH	Cracked	2,637.60 FL	*2,637.60 FL
93	1		*COMPUTER SUB-ASSY ,HEADLAMP RH NO.1	Serviceable	960.50 FL	*- FL
94	1		*MOTOR ,HEADLAMP LEVELING ,RH	Serviceable	487.50 FL	*- FL
95	1		*GRILLE SUB-ASSY ,RADIATOR	Dented	346.00 FL	*346.00 FL
96	1		*GRILLE RADIATOR ,LOWER NO.1	Not Necessary	170.10 FL	*- FL
97	1		*EMBLEM ASSY ,RADIATOR GRILLE	Necessary	90.80 FL	*90.80 FL
98	1		*FRONT FENDER RH	Buckled	977.80 FL	*977.80 FL
99	1		*LINER FRONT FENDER ,RH	Distorted	206.70 FL	*206.70 FL
100	1		*PROTECTOR ,FRONT FENDER SIDE PANEL, RH	Repair	93.90 FL	*- FL
101	1		*SEAL ,FENDER APRON MUDGUARD ,RH	Serviceable	51.90 FL	*- FL
102	1		*EMBLEM ,SIDE PANEL RH	Necessary	54.60 FL	*54.60 FL
103	1		*COVER SUB ASSY ,FRONT PILLAR ,UPR RH	Serviceable	100.40 FL	*- FL
104	1		*BRACE SUB ASSY ,FENDER APRON RH	Serviceable	292.10 FL	*- FL
105	1		*MEMBER ,FRONT APRON TO COWL SIDE ,LOWER FRONT RH	Repair	62.80 FL	*- FL
106	1		*MEMBER ,FRONT APRON TO COWL SIDE ,UPPER RH	Repair	110.00 FL	*- FL
107	1		*APRON ASSY ,FRONT FENDER ,RH	Repair	176.80 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
108	1		*SUPPORT SUB ASSY RADIATOR ,RH	Repair	245.10 FL	*- FL
109	1		*SUPPORT SUB ASSY RADIATOR ,LH	Repair	245.10 FL	*- FL
110	1		*SUPPORT SUB ASSY RADIATOR ,UPPER	Repair	377.10 FL	*- FL
111	1		*SUPPORT SUB ASSY RADIATOR ,LOWER	Repair	409.90 FL	*- FL
112	1		*SUPPORT ,RADIATOR ,UPPER RH	Buckled	78.90 FL	*78.90 FL
113	1		*SUPPORT ,RADIATOR ,UPPER LH	Repair	78.90 FL	*- FL
114	1		*FRONT FENDER LH	Repair	977.80 FL	*- FL
115	1		*LINER ,FRONT FENDER ,LH	Serviceable	202.50 FL	*- FL
116	1		*EMBLEM ,SIDE PANEL ,LH	Serviceable	54.60 FL	*- FL
117	1		*COVE SUB ASSY,FRONT PILLAR ,UPR LH	Serviceable	100.40 FL	*- FL
118	1		*COVER ,RADIATOR SUPPORT OPENING	Serviceable	235.30 FL	*- FL
119	1		*FRONT BONNET	Bent	983.10 FL	*983.10 FL
120	1		*HINGE ASSY ,HOOD,LH	Repair	58.90 FL	*- FL
121	1		*HINGE ASSY ,HOOD,RH	Distorted	58.90 FL	*58.90 FL
122	1		*INSULATOR ,HOOD	Serviceable	410.90 FL	*- FL
123	1		*LOCK ASSY ,HOOD	Repair	135.00 FL	*- FL
124	1		*CABLE ASSY ,HOOD LOCK CONTROL	Serviceable	54.90 FL	*- FL
125	1		*SEAL ,HOOD TO FRONT END PANEL	Serviceable	51.60 FL	*- FL
126	1		*BRACE ,HOOD LOCK SUPPORT	Repair	78.30 FL	*- FL
127	1		*GUIDE ,RADIATOR AIR NO.3	Serviceable	112.70 FL	*- FL
128	1		*SHAFT ASSY ,FRONT DRIVE ,RH	Repair	1,352.50 FL	*- FL
129	1		*ARM SUB-ASSY ,FRONT SUSPENSION ,LOWER NO.1 RH	Serviceable	760.10 FL	*- FL
130	1		*KNUCKLE ,STEERING ,RH	Serviceable	663.40 FL	*- FL
131	1		*LINK ASSY ,FRONT STABILIZER ,RH	Serviceable	237.10 FL	*- FL
132	1		*BAR ,STABILIZER ,FRONT	Serviceable	367.30 FL	*- FL
133	1		*FRONT SHOCK ABSORBER	Serviceable	438.30 FL	*- FL
134	1		*SUPPORT SUB-ASSY ,FRONT SUSPENSION ,RH	Serviceable	236.40 FL	*- FL
135	1		*GEAR ASSY ,STEERING	Serviceable	1,955.40 FL	*- FL
136	1		*SENSOR ,SPEED ,FRONT RH	Serviceable	543.90 FL	*- FL
137	1		*SOCKET & WIRE SUB-ASSY ,REAR COMBINATION LAMP ,LH	Serviceable	63.30 FL	*- FL
138	1		*SOCKET & WIRE SUB-ASSY ,REAR COMBINATION LAMP ,RH	Serviceable	63.30 FL	*- FL
139	1		*SEAL, RADIATOR TO SUPPORT ,NO.3	Serviceable	29.60 FL	*- FL
140	1		*GUIDE ,RADIATOR AIR ,NO.1 LH	Serviceable	69.90 FL	*- FL
141	1		*SEAL ,RADIATOR TO SUPPORT ,NO.2	Serviceable	29.60 FL	*- FL
142	1		*GUIDE ,RADIATOR AIR ,NO.1 RH	Serviceable	65.30 FL	*- FL
143	1		*GUIDE ,RADIATOR AIR ,NO.2	Serviceable	53.40 FL	*- FL
144	1		*FAN ,RH	Serviceable	281.30 FL	*- FL
145	1		*FAN ,LH	Serviceable	219.10 FL	*- FL
146	1		*SHROUD ,FAN	Serviceable	264.70 FL	*- FL
147	1		*MOTOR ,COOLING FAN ,LH	Serviceable	655.10 FL	*- FL
148	1		*MOTOR ,COOLING FAN ,RH	Serviceable	535.50 FL	*- FL
149	1		*CONDENSER ASSY ,COOLER	Serviceable	1,783.20 FL	*- FL
150	1		*HOSE SUB ASSY ,SUCTION	Serviceable	646.80 FL	*- FL
151	1		*HOSE SUB ASSY ,DISCHARGE	Serviceable	402.90 FL	*- FL
152	1		*PIPE SUB ASSY ,FUNCTION	Serviceable	465.80 FL	*- FL
153	1		*TUBE & ACCESSORY ASSY ,AIR CONDITIONER	Serviceable	691.00 FL	*- FL
154	1		*RADIATOR ASSY	Serviceable	2,218.00 FL	*- FL
155	1		*HOSE ,WASHER BY PASS,NO.1	Serviceable	45.20 FL	*- FL
156	1		*HOSE ,WASHER BY PASS,NO.2	Serviceable	45.20 FL	*- FL
157	1		*HOSE ,WASHER BY PASS,NO.3	Serviceable	24.40 FL	*- FL
158	1		*HOSE ,WASHER BY PASS,NO.4	Serviceable	15.90 FL	*- FL
159	1		*HOSE ,WASHER BY PASS,NO.8	Serviceable	45.20 FL	*- FL
160	1		*PIPE ,WATER BY PASS ,NO.1	Serviceable	13.20 FL	*- FL
161	1		*HOSE ,RADIATOR ,NO.2	Serviceable	48.60 FL	*- FL
162	1		*HOSE ,RADIATOR ,NO.1	Serviceable	51.60 FL	*- FL
163	1		*JAR ASSY ,WINDSHIELD WASHER	Dented	219.10 FL	*219.10 FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
164	1		*INLET SUB ASSY ,WASHER	Serviceable	67.00 FL	*- FL
165	1		*MOTOR AND PUMP ASSY ,WINDSHIELD WASHER	Serviceable	292.40 FL	*- FL
166	1		*HORN ASSY ,HIGH PITCHED	Serviceable	134.80 FL	*- FL
167	1		*HORN ASSY ,LOW PITCHED	Serviceable	134.80 FL	*- FL
168	1		*MOULDING ,WINDSHIELD ,OUTSID RH	Serviceable	85.50 FL	*- FL
169	1		*INLET ,AIR CLEANER ,NO.3	Serviceable	42.10 FL	*- FL
170	1		*INLET ,AIR CLEANER ,NO.2	Serviceable	112.70 FL	*- FL
171	1		*INLET ,AIR CLEANER ,NO.1	Serviceable	155.60 FL	*- FL
172	1		*CROSSMEMBER SUB ASSY ,FRONT SUSPENSION	Serviceable	2,585.50 FL	*- FL
173	1		*SET PARKING AID	Shorted	700.00 FS	*250.00 FS
174	1		*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
175	2		*REAR WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
176	1		*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*- FS
177	1		*REAR WINDSCREEN INNER SPONGE SEAL	Necessary	100.00 FS	*30.00 FS
178	1		*REAR TAILGATE TOYOTA LOGO	Necessary	47.00 FS	*47.00 FS
179	1		*REAR TAILGATE WORDING PRIUS	Necessary	52.90 FS	*52.90 FS
180	1		*REAR TAILGATE WORDING HYBRID	Necessary	53.50 FS	*53.50 FS
181	1		*REAR TAILGATE STICKER TRANS-CAB	Necessary	80.00 FS	*30.00 FS
182	1		*REAR TAILGATE STICKER 6555-3333	Necessary	80.00 FS	*30.00 FS
183	1		*REAR BUMPER PROTECTOR	Serviceable	100.00 FS	*- FS
184	1		*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
185	1		*FRONT NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
186	1		*CLIP,FRONT FENDER LINER RH	Necessary	25.00 FS	*25.00 FS
187	1		*REAR BUMPER PROTECTOR	Not Necessary	100.00 FS	*- FS
188	1		*SPARE WHEEL RIM	Serviceable	1,570.55 FS	*- FS
189	1		*SPARE WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
190	1		*SPARE TYRE 195/65/15	Serviceable	350.00 FS	*- FS
191	1		*SET REAR RH FENDER LINER CLIP	Necessary	35.00 FS	*35.00 FS
192	1		*SET FRONT RH BUMPER RETAINER CLIP	Not Necessary	25.00 FS	*- FS
193	1		*SET REAR RH BUMPER RETAINER CLIP	Not Necessary	25.00 FS	*- FS
194	1		*FRONT WHEEL RIM	Serviceable	1,570.55 FS	*- FS
195	1		*FRONT WHEEL RIM COVER	Serviceable	175.80 FS	*- FS
196	1		*FRONT TYRE 195/65/15	Serviceable	350.00 FS	*- FS
197	1		*REAR WHEL RIM	Serviceable	1,570.55 FS	*- FS
198	1		*REAR WHEL RIM COVER	Serviceable	175.80 FS	*- FS
199	1		*REAR TYRE 195/65/15	Serviceable	350.00 FS	*- FS
200	1		*REAR NUMBER PLATE WITH MOULDING	Serviceable	200.00 FS	*- FS
201	1		*WINDSCREEN SEALANT	Serviceable	253.80 FS	*- FS
202	1		*FRONT WINDSCREEN MOULDING	Not Necessary	120.00 FS	*- FS
203	1		*FRONT WINDSCREEN INNER SPONGE SEAL	Not Necessary	100.00 FS	*- FS
204	1		*FRONT DOOR STICKER TRANS-CAB	Not Necessary	100.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	83,635.16	12,827.51
- List Item Discount on L Items 25.00/25.00% (S\$)	18,659.23	3,025.53
Total Parts (S\$)	64,975.93	9,801.98

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,000.00	1,980.00
2	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.	New	9,000.00	2,000.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	120.00
4	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	50.00
5	TO TRANSFER OF TAILGATE FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
6	TO TRANSFER OF REAR BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
7	TO TRANSFER OF REAR END PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
8	TO TRANSFER OF BONNET FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	170.00	0.00
9	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	100.00
10	TO TRANSFER OF FRONT BUMPER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
11	TOWING FEES	New	170.00	50.00
12	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	0.00
13	TO REMOVE AND REFIT FRONT W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
14	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	120.00
15	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
16	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
17	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	40.00
18	TO TRANSFER OF LUGGAGE FLOOR PANEL FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
19	TO DROP REAR EXHAUST BOX ,RENEW THE SAME ,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	0.00
20	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
21	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
22	TO DROP PETROL TANK PIPES ,HOSES TO FACILITATE BODYWORK REPAIR ,FINAL CHECKING AND TESTING	New	380.00	0.00
23	TO DISMANTLE AND REFIT FRONT END SUSPENSION ,UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
24	TO CHECK ABS AND BRAKE EFFICIENCY ,FINAL CHECKING AND TESTING	New	380.00	0.00
25	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
26	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
27	TO DISMANTLE AND REFIT REAR UNDERCARRIAGE PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
28	TO DISMANTLE AND REFIT REAR AXLE ASSY ,REMOVE AND RENEWAL OF PARTS ,FINAL CHECKING AND TESTING	New	380.00	0.00
29	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
30	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AID OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
31	TO DISMANTLE AND REFIT ENGINE CROSS -MEMBER AND ENGINE MOUNTING	New	380.00	0.00
Gross Labour Cost (\$\$)			25,080.00	4,520.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >