

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022220/BBA3Q2

Date: 03/02/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100343657

Claimant
Vehicle No : SBW320G **Insured Vehicle No :** SKJ4066B

Date of Loss: 13/12/2019 Nature of Claim: TP Claim No: 3173826804SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SBW320G		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB6550166
Reg. Date:	20/04/2018 (Man. Year: 2018)	Chassis No:	GP71208316
Colour:	Black	Odometer:	121577 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65 R15	Rear Tyre Size:	185/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	9,818.24	5,547.68	4,270.56	43.50
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,320.00	1,920.00	1,400.00	42.17
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	13,138.24	7,467.68	5,670.56	43.16
Approved Total (Overridden) (\$)		6,000.00		
(\$)	13,138.24	6,000.00	7,138.24	54.33
+ GST 7.00/7.00% (\$)	919.68	420.00	499.68	54.33
Nett Amount (\$)	14,057.92	6,420.00	7,637.92	54.33
Global Sum Settlement (\$)		0.00		

INSPECTION

Date of Assignment: 16/12/2019

Date Inspected: 16/12/2019 Inspected At:

160 SIN MING DRIVE#01-14
Repairer: Team Autopro Pte Ltd - Sin Ming (HQ)

Estimated Period of Repair: 7.0 days

Adjuster: Lim Teow Guan

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER ASSY	Cut	1,863.40 FL	*1,841.10 FL
2	1		*FRONT BUMPER BRACKET	Not Damaged	152.00 FL	*- FL
3	2		*FRONT BUMPER SIDE RETAINER	Necessary	277.00 FL	*182.20 FL
4	1		*FRONT LEFT HEADLAMP ASSY	Cut	1,678.00 FL	*1,678.00 FL
5	1		*FRONT LEFT HEADLAMP LOWER BRACKET	Not Damaged	152.10 FL	*- FL
6	1		*FRONT LEFT FOG LAMP	No such part	280.00 FL	*- FL
7	1		*FRONT LEFT FOG LAMP GARNISH	Not Damaged	121.00 FL	*- FL
8	1		*FRONT LEFT FENDER ASSY	Dented	785.80 FL	*785.80 FL
9	1		*FRONT LEFT FENDER HYBRID EMBLEM	Necessary	186.20 FL	*65.80 FL
10	1		*FRONT LEFT FENDER GARNISH	Not Damaged	157.20 FL	*- FL
11	1		*FRONT LEFT FENDER INNER COWLING	Not Damaged	278.00 FL	*- FL
12	1		*FRONT LEFT ABSORBER	Dented	456.20 FL	*420.00 FL
13	1		*FRONT LEFT LOWER CONTROL ARM	Dented	398.00 FL	*200.00 FL
14	1		*FRONT LEFT KNUCKLE ARM	Dented	348.00 FL	*348.00 FL
15	1		*FRONT LEFT WHEEL HUB WITH BEARING	Necessary	352.00 FL	*185.00 FL
16	1		*FRONT LEFT RIM CAP	Missing	218.00 FL	*182.20 FL
17	1		*FRONT LEFT DOOR	Repair	1,684.30 FL	*- FL
18	1		*FRONT LEFT SIDE MIRROR	Dislodged	783.20 FL	*681.50 FL
19	1		*FRONT LEFT SIDE MIRROR CAVER	Cut	352.40 FL	*90.00 FL
20	1		*FRONT BUMPER CLIPS	Necessary	50.00 FS	*30.00 FS
21	1		*FRONT BUMPER LOWER GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
22	1		*FRONT GRILLE CLIPS	Not Necessary	50.00 FS	*- FS
23	1		*FRONT LEFT FENDER SEALANT	Necessary	80.00 FS	*30.00 FS
24	1		*FRONT LEFT FENDER INNER COWLING CLIPS	Necessary	50.00 FS	*30.00 FS
25	1		*FRONT LEFT FENDER PROTECTOR CLIPS	Not Necessary	60.00 FS	*- FS
26	1		*FRONT LEFT SIDE MIRROR SEAL	Necessary	80.00 FS	*30.00 FS
27	1		*FRONT LEFT DOOR SEALANT	Not Necessary	80.00 FS	*- FS
28	1		*FRONT LEFT DOOR INNER TRIMBOARD CLIPS	Not Necessary	50.00 FS	*- FS
29	1		*FRONT LEFT RIM (COVER)	Missing	550.00 FS	*100.00 FS
30	1		*FRONT LEFT TYRE	Not Damaged	300.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	11,922.80	6,879.60
- List Item Discount on L Items 20.00/20.00% (S\$)	2,104.56	1,331.92
Total Parts (S\$)	9,818.24	5,547.68

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT	New	1,200.00	800.00
2	RUST PROOFING	New	150.00	60.00
3	CHECK WIRING	New	100.00	50.00
4	WHEEL ALIGNMENT	New	120.00	60.00
5	R&R FRONT LEFT DOOR COMPONENT	New	150.00	0.00
6	R&R FRONT LEFT TYRE AND BALANCING	New	50.00	0.00
7	R&R FRONT LEFT UNDERCARIAGE PARTS	New	350.00	150.00
8	SPRAY PAINT	New	1,200.00	800.00
Gross Labour Cost (\$\$)			3,320.00	1,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >