

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022226/KPA3Q2

Date: 23/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SDG5488J	Insured Vehicle No :	SHA6541R
Date of Loss: 12/12/2019	Nature of Claim: TP	Claim No: MCT19120268

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDG5488J	Engine No:	2NRX437953
Make & Model:	TOYOTA VIOS, 1.5 E (A)	Chassis No:	MR2B23F3601175412
Reg. Date:	30/04/2019 (Man. Year: 2019)	Odometer:	27188 km
Colour:	Metallic Pearl White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/45 R16	Rear Tyre Size:	205/45 R16
Front Left Side:	Continental 8 mm	Rear Left Side:	Continental 8 mm
Front Right Side:	Continental 8 mm	Rear Right Side:	Continental 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,589.65	1,589.65	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,000.00	760.00	240.00	24.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,589.65	2,349.65	240.00	9.27
+ GST 7.00/7.00% (S\$)	181.28	164.48	16.80	9.27
Nett Amount (S\$)	2,770.93	2,514.13	256.80	9.27
+ Loss of Use (5.0 x S\$100.00/day) (S\$)		500.00		
Nett Liability (S\$)		3,014.13		

INSPECTION

Date of Assignment:	16/12/2019	
Date Inspected:	26/12/2019 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun)
		Blk 1019 #01-374/382, Yishun
		Industrial Park A
		Singapore 768761
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2020)
Parts:	143	TOYOTA VIOS 1.5 E (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SDG5488J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Buckled	479.20 FL	*479.20 FL
2	1		*FRONT BUMPER RH SIDE RETAINER	Distorted	92.33 FL	*92.33 FL
3	1		*FRONT BUMPER RH FOG LAMP	Cracked	248.20 FL	*248.20 FL
4	1		*FRONT BUMPER RH FOG LAMP GARNISH	Cut	133.90 FL	*133.90 FL
5	6		*FRONT BUMPER CLIPS	Necessary	21.00 FL	*21.00 FL
6	1		*RH HEADLAMP	Cut	1,144.90 FL	*1,144.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	2,119.53	2,119.53
- List Item Discount on L Items 25.00/25.00% (S\$)	529.88	529.88
Total Parts (S\$)	1,589.65	1,589.65

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	REMOVE & REFIX FRT BUMPER ASSY ,FOG LAMPS ,HEADLAMPS ,KNOCK & REPAIR FRT RH FENDER ,FRT BUMPER REINFORCEMENT & REALIGN THE SAME	New	500.00	360.00
2	PUTTY & RESPRAY ON FRT BUMPER ,REINFORCEMENT ,FRT RH FENDER	New	500.00	400.00
Gross Labour Cost (\$)			1,000.00	760.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >