

COMFORTDELGRO ENGINEERING

Our Job Ref No : 305366386

Date : 19/12/19

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156

FINALIZATION FORM

To : LKK

Fax :

Attn : PARAM

: SHA2616K

11/12/19

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: AIG SLX2108S
2. The finalized amount shall be:
- | | |
|---|-------------------|
| (a) Spare Parts after List discount | <u>\$1,272.02</u> |
| (b) Labour Charges | <u>\$600.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,872.02</u> |
| (c) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | |
| Final Lumpsum Repair cost | |

To: Khia Chien


Receipt


3. Estimated normal period for repairs: 2 working days.

4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and finalized amount

Signature : 

Signature : 

Name : CHIANG

Name : Ram

Tel : 62148314

Date : 20/12/19

Fax : 65468156

For Official Use Only

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		N		
3. Survey Fees				
4. LTA Search Fee	7.49			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305366386
 REGN NO : SHA2616K
 MILEAGE : 000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 30.04.2019
 DATE/TIME IN : 11.12.2019 14:20
 ACCIDENT DATE : 11.12.2019

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	459.40	20.00	367.52	CU ✓
0002	04-01-0104-2533-G	IONIQV2 MOULDING ASSY-RR	1	451.25	20.00	361.00	scr ✓
0003	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	rec ✓
0004	04-01-0104-1150-A	IONIQVC PROTECTOR MAT	1	50.00		50.00	rec ✓
0005	FNPS	NO PLATE(S)	1 N	55.00		55.00	cr ✓
0006	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1	155.00	20.00	124.00	cr ✓
0007	04-01-0104-2370-G	IONIQ LAMP ASSY-REAR FOG	1	201.50	20.00	161.20	cr ✓
0008	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1	135.70		135.70	scr ✓
						SUB-TOTAL	: 1,272.02

Supplementary →

JOB NATURE

0000	PB	PANEL BEATING				320.00	✓
0001	SP	SPRAYPAINT CHARGE				200.00	✓
0002	20-00	TUFF COAT ON AFFECTED PARTS.				30.00	✓

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305366386
REGN NO : SHA2616K
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 30.04.2019
DATE/TIME IN : 11.12.2019 14:2
ACCIDENT DATE : 11.12.2019

JOB / PARTS DESCRIPTION	QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0003 20-22 REMOVE/REFIX REVERSE SENSOR	50.00				

SUB-TOTAL : 600.00

TOTAL : 1,872.02

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 2616K

DATE 11/12/2019 16:50

Alfa

MAKE :

MODEL : HYUNDAI IONIQ

Olmar

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Boot Lid 'H' Emblem <i>XAN</i>			\$ 28.00
	Emblem -Hybrid <i>XAN</i>			\$ 24.30
	Emblem -Ioniq <i>XAN</i>			\$ 31.30
	Rear Bumper <i>Cut</i>			\$ 459.40
	Rear Bumper Reinforcement ? <i>XAN</i>			\$ 294.80
	Rear Bumper Reinforcement Bracket (LH/RH) ? <i>XAN</i>	\$	138.10	\$ 276.20
	Rear Bumper Centre Moulding Assy <i>Scr</i>			\$ 451.25
	Rear Bumper Lower Centre Moulding Assy <i>scr</i> <i>an</i>			\$ 155.00
	Rear Bumper Stay <i>XAN</i>			\$ 138.10
	Rear Bumper Side Bracket (LH/RH) <i>XAN</i>	\$	33.10	\$ 66.20
	Rear Bumper Cover Clips <i>rec</i>			\$ 22.00
	SUB TOTAL			\$ 1,946.55
	LESS 20%			\$ 389.31
	DISCOUNTED TOTAL			\$ 1,557.24
	Boot Lid Comfort Logo & Tel No. Sticker <i>rec</i>			\$ 30.00 Nett
	Rear No. Plate <i>cr</i>			\$ 25.00 Nett
	Rear No. Plate Trim Cover <i>B</i>			\$ 30.00 Nett
	Rear Bumper Reverse Sensor <i>scr</i>			\$ 135.70 Nett
	Rear Bumper Rubber Mat <i>rec</i>			\$ 50.00 Nett
				\$ 270.70
	Labour Charge			\$320 \$240
	Panel Beating			\$ 350.00 \$320
	Spray Painting Charge			\$ 500.00 \$200
	Wiring Charge			\$ 50.00 ---
	Tuff Kote			\$ 50.00 \$30
	Remove/Refix Reverse Sensor			\$ 80.00 \$50
	TOTAL LABOUR			\$ 1,030.00
	ESTIMATE TOTAL			\$ 2,857.94

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2am (LKE)
12/12/19 1300 hrs
Rayo Surian @ lkkauto.com
88622728 hy
3 repair days
Est. Paint
Photo

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.