

NRZ

NS/INC19022254/INC3

X 1 → 21990/hb

ASSIGNMENT

Estimated Cost:

OD TP/WS/TP RES/OD RES/EVA/INV/MV

To inspect Vehicle No:

at Workshop no:

of

Insured

Policy No

Claims No.

Sum Insured:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

GIA / PR. Seen:

Est. Repair:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time Action / Instruction

NO Policy
3/1/2020 FINISHED LUMP SUM REPAIR \$1,350.00 / 3 REPAIR DAYS
9/1/2020 INCORRECT INSURANCE TP INSURE IS ATG. CANCEL CASE. DOUBLE REFERENCE: Refer to CC#19021990/hb3

Date/Time: File Pass 4/7

1)

Date/Time: File Return 4/7

2)

Page 4 of 4

Emp: Sam / K. R. R.

☐: Prel. Report
☐: Final Report

Days Of Repair:

Resurvey No. of Trip:

Adel Fee: ☐ Site Insp: \$5
☐ Interview: \$5
☐ Tech. Insp: \$5
☐ Wash up: \$5

Survey Fee:

Transportation:

5 + RS: \$1

Phone:

Other:

4/7/20

13/12/19

Unit No:

SHA 1161L

26 May 2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

HYUNDAI

Colour:

BLUE

Sp Reading

352,476

Eng/No:

C/No:

Gen. Cond. Good / Fair / Poor / Burnt

Steering: / Jammed / Leaked / Burnt or

Brake: / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / Rim or

Tyre Size:

F: 205/60 R16

R:

11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

HANKOOK

Front

R/Bal:

5

mm

L/Bal:

5

mm

D.O.A.

7/12/19

Rear

R/Bal:

6

mm

L/Bal:

6

mm

D.O.A.

13/12/19

Survey held at

CDGE LYANG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

REAR, O/S REAR

The U/C / Chassis frame / Body Structure affected due to collision.

ATG L/S