

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022258/KVF3E2

Date: 28/04/2020

REFERENCE

Insured/Claimant: ZHANG QINGUI Policy No: DMPCSN3072621900

Date of Loss: 13/12/2019 Nature of Claim: OD

Claim No: SNM19D205989/SMR9319Z/BEN

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMR9319Z**

Make & Model: BMW 640I, 3.0 Gran Coupe (F13) (A)

Engine No: 08878179N55B30A

Reg. Date: 20/07/2012 (Man. Year: 2012)

Chassis No: WBA6A02070DF13923

Colour: Metallic Grey

Odometer: 75582 km

Engine Capacity: 2979 cc

Market Value/New Car Price: S\$90,000.00

Sum Insured (\$\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 245/40 R19

Rear Tyre Size:

275/35 R19

Front Left Side: Michelin 9 mm

Rear Left Side:

Michelin 9 mm

Front Right Side: Michelin 9 mm

Rear Right Side:

Michelin 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	19,280.00	16,723.00	2,557.00	13.26
Miscellaneous Items	100.00	100.00	0.00	0.00
Labour	1,484.15	1,414.81	69.34	4.67
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	20,864.15	18,237.81	2,626.34	12.59
- Excess (\$\$)	0.00	1,500.00	-1,500.00	
(\$\$)	20,864.15	16,737.81	4,126.34	19.78
+ GST 7.00/7.00% (\$\$)	1,460.49	1,171.65	288.84	19.78
Nett Amount (\$\$)	22,324.64	17,909.46	4,415.18	19.78

INSPECTION

Date of Assignment: 18/12/2019 Present Location:

Cheng Hoe Motor Pte Ltd (Yishun)

Date Inspected: 18/12/2019 Inspected At:

Cheng Hoe Motor Pte Ltd (Yishun)

Blk 1019 #01-374/382, Yishun Industrial Park A

Singapore 768761

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 28 Apr 2020)	
Parts:	N/A	BMW 640I 3.0 Gran Coupe (F13) (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMR9319Z)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*parts		19,280.00 F	*16,185.00 F
2	1		*2L PWR STEERING OIL	Necessary	-	*40.00 F
3	1		*EXPANSION TANK	Dented	-	*145.00 F
4	1		*R/F AIR DUCT	Dented	-	*68.00 F
5	1		*SUPOUT CTR TOP PANEL PARTS	Buckled	-	*165.00 F
6	1		*2L COOLANT	Necessary	-	*40.00 FS
7	1		*FRT NO PLATE	Bent	-	*80.00 FS
					Total Parts (S\$)	19,280.00 16,723.00

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
Miscellaneous Items				
1	1	sundry (NECESSARY)	100.00	100.00
Sub Total (\$\$)			100.00	100.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	labour	New	742.00	686.00
2	spray painting	New	742.15	728.81
Gross Labour Cost (\$\$)			1,484.15	1,414.81

Report was unsubmitted during this print-out.

< END OF ESTIMATES >