

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 19 Dec 2019

Preliminary Advice

Vehicle No	: YL29J	Accident Date	: 16/12/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3038901901
Assignment Date	: 18/12/2019	Excess	: S\$3,550.00
Date of Inspection	: 18/12/2019	Est. Duration of Repair	: 7
Inspection At	: LAI HUAT (MENG KEE) MOTOR PTE LTD		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front o/s portion and front windscreen cracked and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,267.40
Revised Amount	:S\$	5,924.40
Check Items (Estimated)	:S\$	0.00
Total	:S\$	5,924.40

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	62,000.00
COE / PARF Rebate	:S\$	14,249.00
Salvage Value	:S\$	
Margin for Repair	:S\$	47,751.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Vehicle repair on part by part.