ASS. REC. BY		REF:	C1/1/191907	289 Ng	Brecial Intraction	м
MALIN		ASSIGNMENT OF SP		MI (Omco)	Date/Time: 21 11 2019	
stimated Cost:				Bill to:		
OD-PPP+W	STTP RES / OD	RESTEV.	ALINVIMVICE 2128	3	Insured:	
					f Tel:	
	tu/s					
Policy No. MHASPF 06000028412/1					70/10/63795	5/2019
Sum Insured:			Hxcoss:		utinha	
Make of Vehi (Climits Recer					D.O.A	
	/ REP. / REV 2					ocasment;
Date/Time:		Pe	erson Contacted; _		Vehicle-IN/	OUT
Date/Tune	Action/Instructi	on (	) Estimate			
					1.01/1/	
					115014	7
					1	
						(
					1	-

across the 4 lanes and landed on the grass verge near the road shoulder. The Involved Party came to a stop and realised that the Deceased had landed on the grass verge along the centre divider. As a result of the accident, the Deceased sustained multiple injuries and was conveyed unconscious to the Khoo Teck Phuat Hospital by ambulance. The Deceased succumbed to his injuries and was pronounced dead in hospital on the same day at 5.35 a.m., by Dr Ng Zheng Han Ernest Clement.

Vehicles to be inspected: SMJ1564B - Driver (Involved party)
JRR7688 - Rider (Deceased)

IO In-Charge: SIO Saleha

m) Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motor Lorry, JAH 1469 (TP/IP/63795/2019)

n) Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motorcycle, JQA 2128 [TP/IP/63795/2019]

o) Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motorcycle, JSV 1224 (TP/IP/63795/2019)

On 11 October 2019 (Friday) at about 7.56 p.m., the 2nd Deceased, the driver of motor lorry, JAH 1469 was travelling on the single lane, two way road along Mandai Estate towards Woodlands Road when his motor lorry veered onto the opposite direction along Mandai Estate. Location has a mild slope along the way up from Woodlands Road towards Mandai Estate. While the 2nd Deceased's motor lorry went onto the opposite direction, his motor lorry continued moving down the mild gradual slope towards Woodlands Road and collided onto the 1st Deceased, rider of Malaysian Motorcycle: JQA 2128, 1st Deceased's motorcycle and the Involved Party's motorcycle, rider of Malaysian Motorcycle JSV 1224 which was turning onto Mandai Estate from Woodlands Road. After the collision, the 2nd Deceased's motor lorry continued moving forward with the 1st Deceased and his motorcycle underneath his motor lorry when his motor lorry eventually came to a stop along the center divider along Woodlands Road. The 2nd Deceased's motor lorry was stopped by a traffic light pole. 3 portions of green railing and 1 traffic light pole uprooted. Due to the accident, the 1st Deceased was pronounced dead at the scene of accident by Paramedic SGT Azmi at 8.22 am. The 2nd Deceased conveyed by ambulance to the Khoo Teck Puat Hospital however, he succumbed to his injuries and was pronounced dead in hospital on the same day, at 9.02 a.m. by Dr Alethea. The Involved Party refused conveyance to the hospital.

Vehicles to be inspected: JAH 1469 - Driver (Deceased)

JQA 2128 - Rider (Deceased)

JSV 1224 - Rider (Involved Party) 427 9 19 621 615

IO In-Charge: IO Clarence Lim

p) Case IAFP-IB-20191115 - Mechanical Inspection of Malaysian Motor Lorry, YP 9377 Z (TP/IP/65989/2019)

(TP/IP/65989/2019)

On 23 October 2019 (Wednesday) at about 7.31 a.m., the Deceased was travelling alone on his motorcycle along KJE (PIE) 7.3 km and was riding in between lanes 1 and 2 of the 4-lanes road. While riding, the Deceased self-skidded and fell to his left, under the Involved Party's lorry, which was travelling on lane 2 of the 4 lanes road. The Deceased was subsequently run over by the right rear tyre of the Involved Party's motor lorry. As a result of the accident, the Deceased sustained facial injuries and was pronounced dead at the scene by Paramedic Joshua at 7.52 a.m.

Vehicles to be inspected: YP 9377 Z - Driver (Involved Party)
FBF 3707 U - Rider (Deceased) — 4411/19 6185 6k