

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

### VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way, #09-16  
Singapore 079120

**Our File No:** CC3/AIG19022297/T1SD3E2

**Date:** 26/11/2020

#### REFERENCE

|                   |                     |                  |                           |
|-------------------|---------------------|------------------|---------------------------|
| Insured/Claimant: | KOH LONG YI ADILSON | Policy No:       |                           |
| Date of Loss:     | 14/12/2019          | Nature of Claim: | OD Claim No: 0458110457SG |

#### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                   |             |                   |
|-----------------------------|-----------------------------------|-------------|-------------------|
| Reg No:                     | SKG3293J                          | Engine No:  | CVK075791         |
| Make & Model:               | AUDI A5, 2.0 SPORTBACK (A)        | Chassis No: | WAUZZZF5XKA022277 |
| Reg. Date:                  | 31/01/2019 (Man. Year: 2018)      | Odometer:   | 7874 km           |
| Colour:                     | White                             |             |                   |
| Engine Capacity:            | 1984 cc                           |             |                   |
| Market Value/New Car Price: | S\$155,000.00                     |             |                   |
| Sum Insured (S\$):          | <b>Market Value/New Car Price</b> |             |                   |

#### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

#### CONDITION OF TYRES

|                   |              |                  |              |
|-------------------|--------------|------------------|--------------|
| Front Tyre Size:  | 245/40 R18   | Rear Tyre Size:  | 245/40 R18   |
| Front Left Side:  | Pirelli 6 mm | Rear Left Side:  | Pirelli 6 mm |
| Front Right Side: | Pirelli 6 mm | Rear Right Side: | Pirelli 6 mm |

*The above values represent the remaining tyre treads depth*

| COST OF CLAIMS                      | Repairer's       | Adjuster's       | Difference      | Diff %       |
|-------------------------------------|------------------|------------------|-----------------|--------------|
| Parts                               | 15,433.00        | 9,730.00         | 5,703.00        | 36.95        |
| Miscellaneous Items                 | 0.00             | 0.00             | 0.00            |              |
| Labour                              | 5,952.00         | 3,302.00         | 2,650.00        | 44.52        |
| Paintwork Labour                    | 0.00             | 0.00             | 0.00            |              |
| Towing                              | 0.00             | 0.00             | 0.00            |              |
| <b>Calculated Gross Total (S\$)</b> | <b>21,385.00</b> | <b>13,032.00</b> | <b>8,353.00</b> | <b>39.06</b> |
| <b>- Excess (S\$)</b>               | <b>1,800.00</b>  | <b>1,800.00</b>  | <b>0.00</b>     | <b>0.00</b>  |
| <b>(S\$)</b>                        | <b>19,585.00</b> | <b>11,232.00</b> | <b>8,353.00</b> | <b>42.65</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>       | <b>1,370.95</b>  | <b>786.24</b>    | <b>584.71</b>   | <b>42.65</b> |
| <b>Nett Amount (S\$)</b>            | <b>20,955.95</b> | <b>12,018.24</b> | <b>8,937.71</b> | <b>42.65</b> |

#### INSPECTION

|                     |            |               |  |
|---------------------|------------|---------------|--|
| Date of Assignment: | 19/12/2019 |               |  |
| Date Inspected:     | 18/12/2019 | Inspected At: | Premium Automobiles Pte Ltd (UBI)<br>55 Ubi Road 1<br>Singapore 408699 |

Estimated Period of Repair: 4.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Hiew May Fung

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--|---------------|-------------|--------------|
| 1   | 1   |          | *FRONT BUMPER                                | Deformed      | 2,660.00 FS | *2,128.00 FS |
| 2   | 1   |          | *FRONT BUMPER FIXING PARTS                   | Not Necessary | 368.00 FS   | *- FS        |
| 3   | 1   |          | *FRONT BUMPER SECURING STRIP                 | Not Necessary | 32.00 FS    | *- FS        |
| 4   | 1   |          | *FRONT BUMPER GRILLE - CENTRE                | Not Necessary | 178.00 FS   | *- FS        |
| 5   | 1   |          | *FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | Not Necessary | 207.00 FS   | *- FS        |
| 6   | 1   |          | *FRONT BUMPER SPOILER                        | Not Necessary | 489.00 FS   | *- FS        |
| 7   | 1   |          | *FRONT BUMPER AIR GUIDE - LH                 | Not Necessary | 56.00 FS    | *- FS        |
| 8   | 1   |          | *FRONT BUMPER AIR GUIDE GRILLE - LH          | Not Necessary | 431.00 FS   | *- FS        |
| 9   | 1   |          | *FRONT BUMPER GUIDE SECTION - LH             | Not Necessary | 33.00 FS    | *- FS        |
| 10  | 1   |          | *FRONT PARKING AID SENSOR - OUTER / INNER    | Not Necessary | 231.00 FS   | *- FS        |
| 11  | 4   |          | *FRONT PARKING AID SEAL RING                 | Necessary     | 12.00 FS    | *9.60 FS     |
| 12  | 1   |          | *FRONT FENDER - LH                           | Bent          | 968.00 FS   | *774.40 FS   |
| 13  | 1   |          | *FRONT FENDER ATTACHMENT PARTS               | Not Necessary | 48.00 FS    | *- FS        |
| 14  | 1   |          | *FRONT FENDER CLOSING ELEMENT - LH           | Not Necessary | 68.00 FS    | *- FS        |
| 15  | 1   |          | *FRONT FENDER BRACKET - LH                   | Not Necessary | 32.00 FS    | *- FS        |
| 16  | 1   |          | *FRONT FENDER BRACE - LH                     | Bent          | 107.00 FS   | *85.60 FS    |
| 17  | 1   |          | *FRONT FENDER BRACKET                        | Not Necessary | 32.00 FS    | *- FS        |
| 18  | 1   |          | *DEFORMATION ELEMENT BRACKET - LH            | Not Necessary | 45.00 FS    | *- FS        |
| 19  | 1   |          | *FRONT WHEEL HOUSING LINER - LH              | Not Necessary | 256.00 FS   | *- FS        |
| 20  | 1   |          | *WHEEL HOUSING LINER ATTACHMENT PARTS        | Not Necessary | 82.00 FS    | *- FS        |
| 21  | 1   |          | *WHEEL SPOILER                               | Deformed      | 66.00 FS    | *52.32 FS    |
| 22  | 1   |          | *WHEEL SPOILER TRIM - LH / RH                | Not Necessary | 32.00 FS    | *- FS        |
| 23  | 1   |          | *STONE CHIP GUARD - LH                       | Not Necessary | 46.00 FS    | *- FS        |
| 24  | 1   |          | *TRIM BRACKET - LH                           | Not Necessary | 22.00 FS    | *- FS        |
| 25  | 1   |          | *FRONT FENDER TRIM - LH                      | Deformed      | 145.00 FS   | *115.60 FS   |
| 26  | 1   |          | *FENDER LEDGE COVER                          | Not Necessary | 32.00 FS    | *- FS        |
| 27  | 1   |          | *FENDER LEDGE TOP COVER - LH                 | Not Necessary | 14.00 FS    | *- FS        |
| 28  | 1   |          | *LED HEADLIGHT - LH                          | Cracked       | 7,204.00 FS | *5,763.20 FS |
| 29  | 1   |          | *LIFT CYLINDER - LH                          | Not Necessary | 181.00 FS   | *- FS        |
| 30  | 1   |          | *FRONT ALUMINIUM RIM - LH                    | Cut           | 943.00 FS   | *754.40 FS   |
| 31  | 4   |          | *ALUMINIUM RIM RUBBER VALVE                  | Necessary     | 13.00 FS    | *10.40 FS    |
| 32  | 1   |          | *SUNDRIES                                    | Necessary     | 400.00 FS   | *36.48 FS    |

F=Franchise part. S=SpcNett.

**Total Parts (S\$) 15,433.00 9,730.00**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                  | Particulars   | Lab.Type | Repairer's                     | Amount          |
|---------------------|---|----------|--------------------------------|-----------------|
| <b>Labour Items</b> |   |          |                                |                 |
| 1                   | TO REMOVE, CHECK AN REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID | New      | 480.00                         | 480.00          |
| 2                   | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED   | New      | 2,800.00                       | 1,250.00        |
| 3                   | TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER  | New      | 2,200.00                       | 1,100.00        |
| 4                   | TO RENEW LHS FRONT RIM AND CARRY OUT WHEEL ALIGNMENT  | New      | 280.00                         | 280.00          |
| 5                   | TO CARRY OUT DIAGNOSTIC CHECKS  | New      | 192.00                         | 192.00          |
|                     |   |          | <b>Gross Labour Cost (S\$)</b> | <b>3,302.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >