



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHB 9948B

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	DOOR PANEL FRT RH (CONSISTENT)	TO REPAIR SEE LABOUR	1,823.50	-
1	ROCKER PANEL OUTER RH (CONSISTENT)	BENT	633.01	633.01
1	DOOR PANEL REAR RH (CONSISTENT)	BENT	1,823.50	1,823.50
1	DOOR HINGE UPPER RH (CONSISTENT)	TO REPAIR SEE LABOUR	202.40	-
1	DOOR HINGE LOWER RH (CONSISTENT)	TO REPAIR SEE LABOUR	192.66	-
1	DOOR HANDLE OUTER REAR RH (CONSISTENT)	SERVICEABLE	81.09	-
1	DOOR SEAL REAR RH (CONSISTENT)	SERVICEABLE	119.44	-
1	DOOR REGULATOR MOTOR REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	572.92	-
1	BUMPER COVER REAR (CONSISTENT)	TO REPAIR SEE LABOUR	710.55	-
1	BUMPER BRACKET SIDE RH REAR (CONSISTENT)	SERVICEABLE	87.16	-
1	BUMPER RETAINER RH REAR (CONSISTENT)	SERVICEABLE	28.84	-
1	FENDER PANEL REAR RH (CONSISTENT)	TO REPAIR SEE LABOUR	2,114.83	-
	LESS 10% DISCOUNT		-838.99	-245.65
			7,550.91	2,210.86
<u>SPECIAL NETT ITEMS</u>				
1	DOOR STICKER 'TRANS-CAB' (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
1	DOOR STICKER 'CLASSIC' (CONSISTENT) (SN)	NOT NECESSARY	30.00	-
1	DOOR STICKER '6555-3333' (CONSISTENT) (SN)	NECESSARY	80.00	60.00
2	REAR WINDSCREEN SEALANT (CONSISTENT) (SN)	NOT NECESSARY	80.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (CONSISTENT) (SN)	NOT NECESSARY	150.00	-
			420.00	60.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR			
	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF DOOR PANEL FRT RH,DOOR HINGE UPPER RH,DOOR HINGE LOWER RH,DOOR REGULATOR MOTOR REAR RH,BUMPER COVER REAR AND FENDER PANEL REAR RH .		2,800.00	600.00
	TO CHECK ELECTRICAL LIGHTING CONCERNED.		170.00	20.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		3,000.00	880.00
	TO TRANSFER OF REAR FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REMOVE AND REFIT REAR W/SCREEN GLASS TO FACILITATE BODYWORK REPAIR.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.		220.00	60.00
	TO TRANSFER OF DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
			6,700.00	1,620.00
	GRAND TOTAL		14,670.91	3,890.86
RECOMMENDED COST OF REPAIRS				3,890.86

Report Ref No. CC3/AXA14016319/Kpa3q2-1

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.