

Surveyor

Kenneth

ASSIGNMENT (Office)

From (Person): Tan Kah Leong

of

CT1

Date/Time: 19.12.19 15:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SLZ 45357

Insured:

GBJ 7321B

at Workshop m/s Hui Yang Motor

Tel:

64515752

of 176 Sh Ming Drive #04-02

Policy No: DM(VSR)19299519000

Claim No: SNM19020603302

Sum Insured:

Excess:

Make of Veh:

D.O.A. 14.12.19

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 19.12.19 3:11p.m

Person Contacted:

Channel

Vehicle: IN (OUT)

Date/Time Action/Instruction (✓) Estimate

SLZ 45357-X

GBJ 7321B-MBA / CT1 1902299914

DOR - 10/12/2019

28/1 11 Pm @ 2700 email & confirmed
 (\$ 2,829.04 red 51%)

ASS. REC. BY:

REF:

C721

ASSIGNMENT

From:

Date:

Estimated Cost:

QD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop n/s

of:

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.:

Yes or No

Lum Sum:

20

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SL 2 45 35

Yr Regn:

05, 18

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda

c.c

1496

Colour

M. D. Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

175.268

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GP 7

1208823

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/60R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

A Plus

Front

Rear

R/Bal.

9

mm

R/Bal.

9

mm

L/Bal.

9

mm

L/Bal.

9

mm

D.O.A.

14/12/19

D.O.I.

30/12/19

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

File pass to

RECEIVED 13 FEB 2020

Date/Time, For Pass to?

13/02/20

1) Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

4

Resurvey No. of Trip:

)

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format:

Lump Sum / L.B.I. (\$

2,700 / 415

TOTAL

220

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Ad	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	18 Dec 2019	19 Dec 2019 15:07 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Created by Insurer

Insured:			
Main Claimant:	M/S HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K		
Vehicle Reg. No.:	SLZ4535T	Date of Loss:	14/12/2019 00:00 - :59
Claim Type:	TP / SNM19D206033C02	Policy/Cover Note No.:	DMCVSN19299519000
Vehicle Reg. No. (Insured):	GBJ7321B	Policy No. (Claimant):	DMHCSN1930471900
		Excess:	S\$1,500.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 170 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Tan Kah Leong - 63896193]		
Claimant's Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 31/12/2019]		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.							

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) , Fax: 64514658

GST & Reg No. 201629438M

China
Yanneth
30/12 10AM

14/12/2019

Owner: HYMS CAR LEASING PTE LTD

Not Authorized
11 Pmg @ 2700h
Resurvey After Paint

ESTIMATE TO REPAIR HONDA SHUTTLE - SLZ4535T

1pc	rear tailgate
1pc	rear tailgate "H" logo
1pc	rear tailgate "SHUTTLE" emblem
1pc	rear tailgate chrome
1pc	rear tailgate windscreen moulding
1pc	rear tailgate inner lock
1pc	rear tailgate inner rubber
1pc	rear tailgate inner garnish
1pc	rear bumper
2pcs	rear bumper side retainer @\$38.50
10pcs	rear bumper clip @\$5.00

RM	\$ 1,193.70	✓
RM	\$ 58.00	✓
RM	\$ 55.00	✓
RM	\$ 383.10	X
RM	\$ 195.00	✓
RM	\$ 289.40	X
RM	\$ 188.50	X
RM	\$ 358.50	X
MYCMT	\$ 1,150.60	✓
RM	\$ 77.00	X
RM	\$ 50.00	✓

less 20%

\$ 3,998.80
\$ 799.76
\$ 3,199.04

1set	rear parking sensor
1set	rear number plate & casing

shar	s.nett	\$ 280.00	2005m
RM	s.nett	\$ 50.00	X

remove & refit rear windscreen glass
sealant
wiring
tuffkote
spray painting
labour charges
Total

RM	\$ 120.00	✓
RM	\$ 80.00	405m
	\$ 100.00	15h
	\$ 100.00	30h
	\$ 800.00	400h
	\$ 800.00	400h
	\$ 5,529.04	



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CT119022335/KSF3N2

Date: 14/02/2020

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN19299519000
Claimant Vehicle No :	SLZ4535T	Insured Vehicle No :	GBJ7321B
Date of Loss:	14/12/2019	Nature of Claim:	TP
		Claim No:	SNM19D206033C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLZ4535T	Engine No:	LEB6550781
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Chassis No:	GP71208823
Reg. Date:	03/05/2018 (Man. Year: 2018)	Odometer:	175268 km
Colour:	Metallic Dark Grey		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60R15	Rear Tyre Size:	185/60R15
Front Left Side:	APLUS 9 mm	Rear Left Side:	APLUS 9 mm
Front Right Side:	APLUS 9 mm	Rear Right Side:	APLUS 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,609.04	2,401.84	1,207.20	33.45
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,920.00	965.00	955.00	49.74
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,529.04	3,366.84	2,162.20	39.11
Approved Total (Overridden) (S\$)		2,700.00		
(S\$)	5,529.04	2,700.00	2,829.04	51.17
+ GST 7.00/7.00% (S\$)	387.03	189.00	198.03	51.17
Nett Amount (S\$)	5,916.07	2,889.00	3,027.07	51.17

INSPECTION

Date of Assignment:	19/12/2019	
Date Inspected:	30/12/2019	Inspected At: Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 13 Feb 2020)	
Parts:	N/A	HONDA SHUTTLE HYBRID 1.5 (A) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLZ4535T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE	Bent	1,193.70 FL	*1,193.70 FL
2	1		*REAR TAILGATE H LOGO	Necessary	58.00 FL	*58.00 FL
3	1		*REAR TAILGATE SHUTTLE EMBLEM	Necessary	55.00 FL	*55.00 FL
4	1		*REAR TAILGATE CHROME	Serviceable	383.10 FL	*- FL
5	1		*REAR TAILGATE WINDSCREEN MOULDING	Necessary	195.00 FL	*195.00 FL
6	1		*REAR TAILGATE INNER LOCK	Repair	289.40 FL	*- FL
7	1		*REAR TAILGATE INNER RUBBER	Serviceable	188.50 FL	*- FL
8	1		*REAR TAILGATE INNER GARNISH	Serviceable	358.50 FL	*- FL
9	1		*REAR BUMPER	Mtg Cracked	1,150.60 FL	*1,150.60 FL
10	2		*REAR BUMPER SIDE RETAINER	Serviceable	77.00 FL	*- FL
11	10		*REAR BUMPER CLIP	Necessary	50.00 FL	*50.00 FL
12	1		*SET REAR PARKING SENSOR	Shorted	280.00 FS	*200.00 FS
13	1		*SET REAR NUMBER PLATE & CASING	Serviceable	50.00 FS	*- FS
14	1		*SEALANT	Necessary	80.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	4,408.80	2,942.30
- List Item Discount on L Items 20.00/20.00% (\$\$)	799.76	540.46
Total Parts (\$\$)	3,609.04	2,401.84

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	REMOVE & REFIT REAR WINDSCREEN GLASS	New	120.00	120.00
2	WIRING	New	100.00	15.00
3	TUFF KOTE	New	100.00	30.00
4	SPRAY PAINTING	New	800.00	400.00
5	LABOUR CHARGES	New	800.00	400.00
Gross Labour Cost (S\$)			1,920.00	965.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >