

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022357/KGA3Q2

Date: 29/04/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SGN5242D	Insured Vehicle No :	SHA4332R
Date of Loss: 11/12/2019	Nature of Claim: TP	Claim No: MCT19120244

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SGN5242D		
Make & Model:	HONDA CIVIC, 1.6 VTI (A)	Engine No:	R16A11000395
Reg. Date:	21/11/2006 (Man. Year: 2006)	Chassis No:	JHMF46206S200326
Colour:	Blue	Odometer:	189207 km
Engine Capacity:	1595 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/55 R16	Rear Tyre Size:	205/55 R16
Front Left Side:	Linglong 6 mm	Rear Left Side:	Yokohama 7 mm
Front Right Side:	Linglong 6 mm	Rear Right Side:	Yokohama 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,021.36	1,622.88	1,398.48	46.29
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,400.00	880.00	1,520.00	63.33
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$)	5,421.36	2,502.88	2,918.48	53.83
Approved Total (Overridden) (\$)		2,000.00		
Nett Amount (\$)	5,421.36	2,000.00	3,421.36	63.11
+ Loss of Use (5.0 x S\$60.00/day) (\$)		300.00		
+ Doc/Search Fee (\$)		7.45		
Nett Liability (\$)		2,307.45		
Global Sum Settlement (\$)		2,300.00		

INSPECTION

Date of Assignment:	18/12/2019	
Date Inspected:	18/12/2019	Inspected At: Ngs Automotive (HQ) BLK 10 AMK IND PK 2A #02-01 Singapore 568047
Estimated Period of Repair:	4.0 days	

Adjuster: KENNETH KONG

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Feb 2020)
Parts:	143	HONDA CIVIC 1.6 VTI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SGN5242D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT FENDER RH	Repair	450.80 FL	*- FL
2	1		*FRT DOOR OUTER PILLAR RH	Repair	609.90 FL	*- FL
3	1		*FRT DOOR RH	Bent	949.20 FL	*949.20 FL
4	1		*SIDE MIRROR RH	Broken	659.40 FL	*659.40 FL
5	1		*FRT OUTER HANDLE RH	Dented	175.40 FL	*175.40 FL
6	1		*REAR DOOR RH	Repair	687.40 FL	*- FL
7	1		*FRT DOOR WINDOW MOULDING TOP CHANNEL RH	Dented	90.50 FL	*90.50 FL
8	1		*FRT DOOR OUTER MOULDING	Dented	99.20 FL	*99.20 FL
9	1		*FRT DOOR TAPE	Necessary	54.90 FL	*54.90 FL

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	3,776.70	2,028.60
- List Item Discount on L Items 20.00/20.00% (S\$)	755.34	405.72

Total Parts (S\$)	3,021.36	1,622.88
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REOVE ALL DAMAGED PART WITH ALL NECESSARY COMPONENT /ATTACHMENT ,STRAIGHTEN CHASSIS MEMBER ,REPAIR /RESHAPE DENTED BODY PANEL REPLACE DAMAGED PART REFIT INTO POSITION	New	1,200.00	400.00
2	TO SPRAY PAINTING	New	1,000.00	400.00
3	TRANSFER DOOR MECHANISM	New	150.00	60.00
4	CHECK WIRING & LIGHT FUNCTION	New	50.00	20.00
Gross Labour Cost (\$\$)			2,400.00	880.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >