

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022358/KDA3Q2

Date: 15/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 1900232547

Claimant
Vehicle No : SMJ6598X **Insured Vehicle No :** SMP9273G

Date of Loss: 07/12/2019 Nature of Claim: TP Claim No: 8482826150SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMJ6598X	Engine No:	R18A13850235
Make & Model:	HONDA STREAM, 1.8 L (A)	Chassis No:	JHMRN68609C200227
Reg. Date:	02/12/2010 (Man. Year: 2009)	Odometer:	230054 km
Colour:	Metallic Grey		
Engine Capacity:	1799 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 7 mm	Rear Left Side:	Firenza 7 mm
Front Right Side:	Firenza 7 mm	Rear Right Side:	Firenza 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,207.20	719.20	488.00	40.42
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,500.00	900.00	600.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	2,707.20	1,619.20	1,088.00	40.19
Approved Total (Overridden) (\$\$)		1,300.00		
(\$\$)	2,707.20	1,300.00	1,407.20	51.98
+ GST 7.00/7.00% (\$\$)	189.50	91.00	98.50	51.98
Nett Amount (\$\$)	2,896.70	1,391.00	1,505.70	51.98
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 19/12/2019 Inspected At:

Wei Lee Motor Works (HQ)
BLOCK 9 SIN MING INDUSTRIAL
ESTATE #01-32
Singapore 575644

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled/ Dented	588.50 FL	*588.50 FL
2	2		*REAR BUMPER RETAINER	Serviceable	54.00 FL	*- FL
3	1		*REAR BUMPER TOW COVER	Dented	22.00 FL	*22.00 FL
4	1		*END PANEL	Repair	306.70 FL	*- FL
5	1		*TAILGATE LOCK	Repair	198.60 FL	*- FL
6	1		*TAILGATE H LOGO	Not Necessary	25.70 FL	*- FL
7	1		*TAILGATE STREAM EMBLEM	Necessary	38.50 FL	*38.50 FL
8	1		*REVERSE SENSOR	Dented	220.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	1,454.00	849.00
- List Item Discount on L Items 20.00/20.00% (\$\$)	246.80	129.80
Total Parts (\$\$)	1,207.20	719.20

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REMOVE DAMAGED PARTS N ATTACHMENTS CUT N WELD DAMAGED PANEL REPAIR DENTED TAILGATE REPLACE/ALIGN ABOVE PARTS INTO POSITION	New	800.00	400.00
2	TO SPRAY PAINT	New	700.00	500.00
Gross Labour Cost (\$\$)			1,500.00	900.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >