

威利摩哆 WEI LEE MOTOR WORKS

BLOCK 9 SIN MING INDUSTRIAL ESTATE #01-32,
SINGAPORE 575644.
TEL: 6456 9830 • FAX: 6458 0128 • EMAIL: weileemotorworks@gmail.com
Business Regn No: 269436/00J

16, Dec 2019

AIG Pacific Insurance Pte Ltd
78 She nton Way
#07-16
S 079120

*Not Notified
C/Ly @ 130d
Repair After Rain
3-8 days*

Attn: Motor claim dept-3rd party claim

Claiming against your insured vehicle no: SMP9273G

Accident involving vehicle no: SMJ6598X/SMP9273G/SJK5578R/SJG4337U/SMN2087J

DOA: 07/12/2019 AT PIE (Steven Rd twds Tuas)

Dear officer incharge

Cost of repair for vehicle no: SMJ6598X

To supply—

Description	Qty	Amount
Rear bumper	1 <i>Broken</i>	588.50 ✓
Rear bumper retainer @27	2 <i>in</i>	54.00 X
Rear bumper tow cover	1 <i>in</i>	22.00 ✓
End panel	1 <i>in</i>	306.70 X
Tailgate lock	1 <i>in</i>	198.60 X
Tailgate H logo	1 <i>in</i>	25.70 +
Tailgate stream emblem	1 <i>in</i>	38.50 ✓
Parts		1,234.00
Parts less 20%		246.80
		987.20

reverse sensor ✓

To remove damaged parts n attachments

Cut n weld damaged panel

Repair dented tailgate

Replace/align above parts into position

To spray paint

800.00 *400*
700.00 *500*

2,707.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: