Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022371/R1GA3Q2

Date: 12/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SMH2820R

Insured Vehicle No: SHA7995H Vehicle No:

Date of Loss: Nature of Claim: ΤP 25/11/2019 Claim No: MCT19110641

DESCRIPTION & IDENTIFICATION OF VEHICLE

SMH2820R Reg No:

Make & Model: HONDA VEZEL, 1.5 X CVT (A) Engine No: L15B4404585 Chassis No: Reg. Date: 29/09/2016 (Man. Year: 2016) RU11204580 Colour: Odometer: 81076 km Red

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17 Rear Left Side: Front Left Side: Roadstone 6 mm Roadstone 6 mm Front Right Side: Rear Right Side: Roadstone 6 mm Roadstone 6 mm

The above values represent the remaining tyre treads depth

Repairer's	Adjuster's	Difference	Diff %
3,448.00	1,809.00	1,639.00	47.53
0.00	0.00	0.00	
3,510.00	1,935.00	1,575.00	44.87
0.00	0.00	0.00	
0.00	0.00	0.00	
6,958.00	3,744.00	3,214.00	46.19
487.06	262.08	224.98	46.19
7,445.06	4,006.08	3,438.98	46.19
\$\$50.00/day) (S\$)	350.00		
	3,448.00 0.00 3,510.00 0.00 0.00 6,958.00 487.06 7,445.06	3,448.00 1,809.00 0.00 0.00 3,510.00 1,935.00 0.00 0.00 0.00 0.00 6,958.00 3,744.00 487.06 262.08 7,445.06 4,006.08	3,448.00 1,809.00 1,639.00 0.00 0.00 0.00 3,510.00 1,935.00 1,575.00 0.00 0.00 0.00 0.00 0.00 0.00 6,958.00 3,744.00 3,214.00 487.06 262.08 224.98 7,445.06 4,006.08 3,438.98

INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 10/02/2020 Diplomat Parts Pte Ltd (HQ) Inspected At:

Nett Liability (S\$)

209 Pandan Gardens Singapore 609339

4,356.08

Estimated Period of Repair: 5.0 days

Adjuster: MOHD RASUL Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 2 of 4

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Jul 2020)

Parts: M1-SUV HONDA VEZEL 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMH2820R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

0----

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	50.00 FS	*20.00 FS
2	1		*REAR TAILGATE	Bent	972.00 FS	*972.00 FS
3	1		*REAR BRAKE LAMP RH (BODY)	Serviceable	650.00 FS	*- FS
4	1		*REAR BRAKE LAMP RH (TAILGATE)	Serviceable	267.00 FS	*-FS
5	1		*REAR BUMPER	Deformed	465.00 FS	*465.00 FS
6	1		*REFLECTOR REAR RH	Cracked	151.00 FS	*151.00 FS
7	1		*EMBLEM VEZEL	Necessary	46.00 FS	*46.00 FS
8	1		*REAR BUMPER RH	Serviceable	162.00 FS	*- FS
9	1		*REAR RH WHEEL ARCH TRIM	Deformed	155.00 FS	*155.00 FS
10	1		*REAR RH WHEEL SHIELD	Serviceable	175.00 FS	*- FS
11	1		*RH SIDE PANEL COVER	Serviceable	280.00 FS	*-FS
12	1		*REAR RH WHEEL SHIELD	Serviceable	75.00 FS	*-FS
F=Fra	nchise	part. S=SpcN	lett.			
				Total Parts (S\$)	3,448.00	1,809.00
				_	•	

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount				
Lab	<u>Labour Items</u>							
1	TO RENEW REAR TAILGATE ,REAR RH BUMPER ,REAR BUMPER ,REAR RH WHEEL SHIELD TRIM ,RH ROCKER COVER & AFFECTED AREA	New	1,600.00	875.00				
2	PAINT WORK ON REAR TAILGATE & REAR RH BUMPER	New	840.00	420.00				
3	TO REMOVE & INSTALL REAR PARKING ASSIST	New	120.00	80.00				
4	TO REMOVE & INSTALL REAR WINDSCREEN GLASS	New	240.00	150.00				
5	TO APPLY SEALANT ON REAR WINDSCREEN	New	80.00	60.00				
6	PERFORM RUST PREVENTION	New	80.00	40.00				
7	TO APPLY BODY SEALANT	New	80.00	0.00				
8	TO REMOVE & INSTALL REAR BOOT COMPARTMENT	New	120.00	0.00				
9	TO REMOVE & INSTALL REAR TAILGATE TRIM & OTHERS ATTACHMENTS TO NEW PANEL	New	120.00	80.00				
10	CHECK ELECTRICAL SYSTEM	New	50.00	50.00				
11	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST	New	180.00	180.00				
	Gross Labour Cost (S\$)		3,510.00	1,935.00				

< END OF ESTIMATES >

Report was unsubmitted during this print-out.