

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.  
AIG Building, 78 Shenton Way #07-16  
Singapore 079120

**Our File No:** CS/AIG19022377/KTD3E2

**Date:** 08/04/2020

### REFERENCE

Insured/Claimant: DAIMLER FLEET MANAGEMENT SINGAPORE PTE. LTD	Policy No: 999995580
Date of Loss: 04/12/2019	Nature of Claim: OD
	Claim No: 3696610826SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: <b>GBH9240Z</b>	
Make & Model: MERCEDES-BENZ CITAN 109 CDI VAN, 1.5 EXTRA LONG 2 SEATERS (A)	Engine No: K9KE628D626900
Reg. Date: 02/11/2018 (Man. Year: 2018)	Chassis No: WDF4156052U255200
Colour: White	Odometer: 19893 km
Engine Capacity: 1461 cc	
Market Value/New Car Price: S\$64,000.00	
Sum Insured (S\$): <b>Market Value/New Car Price</b>	

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Engine Modification:	No	Pre-accident Condition:	

### CONDITION OF TYRES

Front Tyre Size: 195/65 R15	Rear Tyre Size: 195/65 R15
Front Left Side: Michelin 6 mm	Rear Left Side: Michelin 6 mm
Front Right Side: Michelin 6 mm	Rear Right Side: Michelin 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	8,858.40	7,077.60	1,780.80	20.10
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,230.00	1,880.00	1,350.00	41.80
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>12,088.40</b>	<b>8,957.60</b>	<b>3,130.80</b>	<b>25.90</b>
<b>- Excess (S\$)</b>	<b>1,400.00</b>	<b>1,400.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>10,688.40</b>	<b>7,557.60</b>	<b>3,130.80</b>	<b>29.29</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>748.19</b>	<b>529.03</b>	<b>219.16</b>	<b>29.29</b>
<b>Nett Amount (S\$)</b>	<b>11,436.59</b>	<b>8,086.63</b>	<b>3,349.96</b>	<b>29.29</b>

### INSPECTION

Date of Assignment: 20/12/2019  
Date Inspected: 20/12/2019 Inspected At:

Tong Luck Auto Pte Ltd (HQ)  
160 Sin Ming Drive, #07-01 Sin Ming  
AutoCity  
Singapore 575722

Estimated Period of Repair: 5.0 days

---

**Adjuster:** KENNETH KONG**Manager:** DENISE TAY KWEE CHENG

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		<b>*BONNET</b> (WCP)	Bent	780.00 F	*780.00 F
2	2		<b>*BONNET HINGES</b> (WCP)	Repair	250.00 F	*- F
3	1		<b>*BONNET INSULATOR CLIPS</b> (15PCS)	Necessary (8Pcs Only)	107.25 FS	*30.00 FS
4	1		<b>*SUPPORT PANEL</b> (WCP)	Cracked	495.00 F	*495.00 F
5	1		<b>*FRONT APRON GARNISH</b> (WCP)	Serviceable	255.00 F	*- F
6	1		<b>*HEADLAMP ASSY - RH</b> (WCP)	Broken	620.00 F	*620.00 F
7	1		<b>*HEADLAMP CONTROL UNIT - RH</b> (WCP)	Serviceable	195.00 F	*- F
8	1		<b>*FRONT BUMPER</b> (WCP)	Buckled / Cracked	1,250.00 F	*1,250.00 F
9	1		<b>*FRONT BUMPER REINFORCEMENT</b> (WCP)	Bent	480.00 F	*480.00 F
10	1		<b>*FRONT BUMPER SIDE BRACKET - RH</b> (WCP)	Serviceable	48.00 F	*- F
11	1		<b>*FRONT BUMPER TOWING COVER</b> (WCP)	Missing	20.00 F	*20.00 F
12	1		<b>*FRONT BUMPER FOG LAMP COVER - RH</b> (WCP)	Cut	98.00 F	*98.00 F
13	1		<b>*FRONT BUMPER CENTRE GRILLE</b> (WCP)	Serviceable	80.00 F	*- F
14	1		<b>*FRONT BUMPER CLIPS</b> (15PCS)	Necessary	90.75 FS	*50.00 FS
15	1		<b>*WASHER TANK</b> (WCP)	Dented	155.00 F	*155.00 F
16	1		<b>*FRONT SPORT RIM - RH</b> (WCP)	Dented	450.00 F	*450.00 F
17	1		<b>*FRONT FENDER - RH</b> (WCP)	Bent / Cracked	295.00 F	*295.00 F
18	1		<b>*FRONT FENDER INNER SHIELD (FRONT) - RH</b> (WCP)	Distorted	220.00 F	*220.00 F
19	1		<b>*FRONT FENDER INNER SHIELD - RH (REAR)</b> (WCP)	Serviceable	295.00 F	*- F
20	1		<b>*FRONT LOWER ARM - RH</b> (WCP)	Bent	330.00 F	*330.00 F
21	1		<b>*FRONT SHOCK ABSORBER - RH</b> (WCP)	Serviceable	285.00 F	*- F
22	1		<b>*FRONT TYRE - RH (60%)</b>	Cut	285.00 FS	*171.00 FS
23	1		<b>*FRONT GRILLE SUPPORT</b> (WCP)	Cracked	105.00 F	*105.00 F
24	1		<b>*HEADLAMP ASSY - LH</b> (WCP)	Mtg Cracked	620.00 F	*620.00 F
25	1		<b>*FRONT BUMPER UNDER COVER</b> (WCP)	Distorted	125.00 F	*125.00 F
26	1		<b>*FRONT FENDER TOP BRACKET - RH</b> (WCP)	Cracked	98.00 F	*98.00 F
27	1		<b>*FRONT LOWER ARM BUSE - RH</b> (WCP)	Cracked	65.00 F	*65.00 F

F=Franchise part. S=SpcNett.

<b>Sub Total (\$\$)</b>	<b>8,097.00</b>	<b>6,457.00</b>
<b>+ Margin on L,N Items 10.00/10.00% (\$\$)</b>	761.40	620.60

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
<b>Total Parts (S\$)</b>					<b>8,858.40</b>	<b>7,077.60</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO REMOVE AND REFIT AIR-CON CONDENSER, RADIATOR AND REFILL AIR-CON GAS	New	150.00	100.00
2	TO PANEL BEAT AND STRAIGHTEN RH FRONT PILLAR, RH FRONT FENDER INNER PANEL, RH FRONT CHASSIS FRAME, INCLUDING REPLACEMENT OF PARTS AND ALIGN WHERE NECESSARY, TO REFIT AND ADJUST THE SAME	New	1,200.00	600.00
3	TO PUTTY AND SPRAY PAINT ON AFFECTED AREAS	New	1,200.00	800.00
4	TO SUPPLY AND PASTE BONNET ADVERTISEMENT	New	580.00	320.00
5	TO CHECK WHEEL ALIGNMENT	New	100.00	60.00
<b>Gross Labour Cost (S\$)</b>			<b>3,230.00</b>	<b>1,880.00</b>

Report was unsubmitted during this print-out.

**< END OF ESTIMATES >**