Adjuster Report Page 1 of 8

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/III19022385/KPA3Q2

Date: 05/05/2020

**REFERENCE** 

Handling Insurer: India International Insurance Pte Ltd MCOM0015 Policy No: Claimant SHD9787M Insured Vehicle No: SHA3213H

Vehicle No:

Date of Loss: TP 18/12/2019 Nature of Claim: Claim No: MCT19120428

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

SHD9787M Reg No:

RENAULT LATITUDE, 2.0 L DCI AUTO D/AB 4DR Engine No: Make & Model: M9R8839C001033

14/04/2014 (Man. Year: 2013) VF1ABL15AUC277266 Reg. Date: Chassis No:

Colour: Metallic White/Red Odometer: 580412 km

1995 cc **Engine Capacity:** Market Value/New Car

N/A Price:

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60R16 Rear Tyre Size: 215/60R16 Front Left Side: Giti 6 mm Rear Left Side: Giti 8 mm Front Right Side: Rear Right Side: Giti 8 mm Giti 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	48,592.24	4,593.12	43,999.12	90.55
Miscellaneous Items	0.00	0.00	0.00	
Labour	24,220.00	1,720.00	22,500.00	92.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	72,812.24	6,313.12	66,499.12	91.33
Approved Total (Overridden) (S\$)		5,050.00		
(S\$)	72,812.24	5,050.00	67,762.24	93.06
+ GST 7.00/7.00% (S\$)	5,096.86	353.50	4,743.36	93.06
Nett Amount (S\$)	77,909.10	5,403.50	72,505.60	93.06
+ Loss of Use (5.0 x S\$4	40.00/day) (S\$)	200.00		
+ Car Rental (5.0 x S\$8	31.13/day) (S\$)	405.65		
Ne	tt Liability (S\$)	6,009.15		
Global Sum S	ettlement (S\$)	6,000.00		

**INSPECTION** 

Date of Assignment: 19/12/2019

Trans-cab Auto Services Pte Ltd Date Inspected: 19/12/2019 Inspected At:

No 2 Ang Mo Kio Street 63

Singapore 569111

Estimated Period of Repair: 4.0 days Adjuster Report Page 2 of 8

Adjuster: KENNETH KONG Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 8

### REPAIR DETAILS

Reference

**Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 28 Apr 2020)

Parts: 143 RENAULT LATITUDE 2.0 L DCI AUTO D/AB 4DR (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

**Print Code:** (Unsubmitted, no print-code for SHD9787M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk \*.

#### **Recommended Parts**

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
	1	*BUMPER COVER REAR	Buckled	561.70 FL	*561.70 F
	1	*BUMPER LOWER REAR	Distorted	411.90 FL	*411.90 F
	1	*BUMPER BRACKET CTR REAR	Serviceable	98.10 FL	*-F
	1	*BUMPER BRACKET SIDE RH REAR	Serviceable	82.10 FL	*-F
	1	*BUMPER RETAINER RH REAR	Serviceable	59.80 FL	*- F
	1	*BUMPER REFLECTOR RH	Buckled	16.60 FL	*16.60 F
	1	*BUMPER BRACKET SIDE LH REAR	Serviceable	80.80 FL	*- F
	1	*BUMPER RETAINER LH REAR	Serviceable	54.20 FL	*- F
	1	*BUMPER REFLECTOR LH	Serviceable	16.60 FL	*- F
0	1	*BUMPER BEAM REAR	Bent	547.80 FL	*547.80 F
1	1	*BUMPER BEAM BRACKET LH REAR	Repair	114.50 FL	*- F
2	1	*BUMPER BEAM BRACKET RH REAR	Distorted	100.90 FL	*100.90 F
3	1	*BUMPER BLOCK LH REAR	Serviceable	75.70 FL	*- F
4	1	*BUMPER BLOCK RH REAR	Serviceable	76.50 FL	*- F
5	1	*BUMPER HARNESS REAR	Serviceable	301.10 FL	*-F
6	1	*BOOT REAR	Repair	1,677.20 FL	*- F
7	1	*BOOT FINISHER	Serviceable	344.70 FL	*- F
8	1	*BOOT WEATHERSTRIP	Serviceable	178.20 FL	*- F
9	1	*BOOT REFLECTOR LAMP LH	Serviceable	277.70 FL	*- F
0	1	*BOOT REFLECTOR LAMP RH	Serviceable	277.70 FL	*- F
1	1	*BOOT BADGE RENAULT	Necessary	82.40 FL	*82.40 F
2	1	*BOOT BADGE	Necessary	95.80 FL	*95.80 F
3	1	*BOOT STRUT LH	Serviceable	145.10 FL	*- F
4	1	*BOOT STRUT RH	Serviceable	145.10 FL	*- F
5	1	*BOOT HINGE LH	Repair	254.20 FL	*- F
6	1	*BOOT HINGE RH	Repair	253.80 FL	*- F
7	1	*BOOT INNER TRIM BOARD	Serviceable	611.00 FL	*- F
8	1	*BOOT SWITCH	Serviceable	113.00 FL	*- F
9	1	*BOOT LOCK	Repair	246.60 FL	*- F
0	1	*BOOT LOCK CATCH	Repair	41.70 FL	*- F
1	2	*LICENCE PLATE LAMP	Serviceable	26.30 FL	*- F
2	2	*BOOT RUBBER PLUG	Serviceable	139.30 FL	*- F
3	1	*BOOT LOCK LINKAGE	Serviceable	20.60 FL	*- F
4	1	*BOOT LOCK LINKAGE HOLDER	Serviceable	99.50 FL	*- F
5	1	*FENDER PANEL INNER TRIM REAR RH	Serviceable	671.45 FL	*- F
6	1	*FENDER PANEL REAR RH	Repair	1,933.20 FL	*- F
7	1	*WHEELARCH REAR RH	Serviceable	275.40 FL	*- F
8	1	*TAILLAMP RH	Serviceable	313.10 FL	*-F
9	1	*TAILLAMP PANEL RH	Repair	401.40 FL	*- F
0	1	*TAILLAMP LH	Serviceable	401.40 FL	*-F
1	1	*TAILLAMP PANEL LH	Repair	401.40 FL	*- F
2	1	*AIR VENT LH	Serviceable	59.40 FL	*- F
3	1	*AIR VENT RH	Serviceable	59.40 FL	*- F

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 8

1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*OUTER PANEL REAR (END PANEL)  *OUTER PANEL REAR (END PANEL) TRIM  *SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)  *SPARE WHEEL PANEL TRIM  *SPARE TYRE BOARD  *EXHAUST REAR  *EXHAUST CAP REAR  *BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT  *BUMPER RETAINER FRT RH	Repair Serviceable Repair Serviceable Serviceable Repair Missing Buckled Serviceable Serviceable Serviceable		*-FL *-FL *-FL *-FL *-FL *125.40 FL *747.20 FL *-FL
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	*SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)  *SPARE WHEEL PANEL TRIM  *SPARE TYRE BOARD  *EXHAUST REAR  *EXHAUST CAP REAR  *BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Repair Serviceable Serviceable Repair Missing Buckled Serviceable Serviceable	1,229.40 FL 612.21 FL 680.90 FL 5,263.60 FL 125.40 FL 747.20 FL 344.70 FL	*-FL *-FL *-FL *-FL *125.40 FL *747.20 FL
1 1 1 1 1 1 1 1 1 1 1 1 1	*SPARE WHEEL PANEL TRIM  *SPARE TYRE BOARD  *EXHAUST REAR  *EXHAUST CAP REAR  *BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Serviceable Serviceable Repair Missing Buckled Serviceable Serviceable	612.21 FL 680.90 FL 5,263.60 FL 125.40 FL 747.20 FL 344.70 FL	*- FL *- FL *- FL *125.40 FL *747.20 FL
1 1 1 1 1 1 1 1 1 1 1 1 1	*SPARE TYRE BOARD  *EXHAUST REAR  *EXHAUST CAP REAR  *BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Serviceable Repair Missing Buckled Serviceable Serviceable	680.90 FL 5,263.60 FL 125.40 FL 747.20 FL 344.70 FL	*- FL *- FL *125.40 FL *747.20 FL
1 1 1 1 1 1 1 1 1 1 1	*EXHAUST REAR  *EXHAUST CAP REAR  *BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Repair Missing Buckled Serviceable Serviceable	5,263.60 FL 125.40 FL 747.20 FL 344.70 FL	*-FL *125.40 FL *747.20 FL
1 1 1 1 1 1 1 1 1 1 1	*EXHAUST CAP REAR  *BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Missing Buckled Serviceable Serviceable	125.40 FL 747.20 FL 344.70 FL	*125.40 FL *747.20 FL
1 1 1 1 1 1 1 1 1	*BUMPER COVER FRT  *BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Buckled Serviceable Serviceable	747.20 FL 344.70 FL	*747.20 FL
1 1 1 1 1 1 1 1	*BUMPER SPOILER FRT  *BUMPER ABSORBER FRT  *BUMPER RETAINER FRT LH  *BUMPER SUPPORT FRT	Serviceable Serviceable	344.70 FL	
1 1 1 1 1 1 1 1	*BUMPER ABSORBER FRT *BUMPER RETAINER FRT LH *BUMPER SUPPORT FRT	Serviceable		*_ FI
1 1 1 1 1 1 1	*BUMPER RETAINER FRT LH *BUMPER SUPPORT FRT		394.68 FL	
1 1 1 1 1 1	*BUMPER SUPPORT FRT	Serviceable		*-FL
1 1 1 1 1			101.40 FL	*-FL
1 1 1 1 1	*BUMPER RETAINER FRT RH	Serviceable	10.70 FL	*-FL
1 1 1 1		Distorted	101.40 FL	*101.40 FL
1 1 1	*BUMPER SUPPORT FRT	Serviceable	10.70 FL	*- FL
1 1	*BUMPER UNDERTRAY FRT	Serviceable	292.50 FL	*-FL
1	*BUMPER GRILLE LOWER FRT	Serviceable	147.00 FL	*-FL
	*BUMPER FOG LAMP GRILLE LH	Serviceable	207.21 FL	*-FL
1	*BUMPER FOG LAMP GRILLE RH	Serviceable	207.21 FL	*-FL
	*BUMPER BEAM FRT	Repair	663.70 FL	*-FL
1	*TOW COVER FRT	Serviceable	60.90 FL	*-FL
1	*RADIATOR GRILLE	Mtg Cracked	969.90 FL	*969.90 FL
1	*RADIATOR GRILLE BADGE RENAULT	Necessary	225.36 FL	*225.36 FL
1	*RADIATOR GRILLE FRAME	Cracked	686.00 FL	*686.00 FL
1	*FRAME FULL SUPPORT PANEL	Repair	592.70 FL	*- FL
1	*FRAME FULL SUPPORT BRACKET	Repair	41.60 FL	*-FL
1	*FRONT BRACE PANEL	Repair	177.22 FL	*- FL
1	*HORN	Serviceable	449.90 FL	*-FL
1	*HORN BRACKET	Serviceable	21.90 FL	*- FL
1	*HEADLAMP LH	Serviceable	743.60 FL	*-FL
1	*HEADLAMP RH	Serviceable	743.60 FL	*- FL
1	*HEADLAMP PANEL FRT LH	Serviceable	127.70 FL	*-FL
1	*HEADLAMP PANEL FRT RH	Serviceable	128.30 FL	*- FL
1	*BONNET	Serviceable	1,312.70 FL	*-FL
1	*BONNET INSULATOR	Serviceable	294.30 FL	*- FL
1	*BONNET STRUT LH	Serviceable	53.30 FL	*-FL
1	*BONNET STRUT RH	Serviceable	53.30 FL	*- FL
1	*BONNET HINGE LH	Serviceable	236.50 FL	*-FL
1	*BONNET HINGE RH	Serviceable	237.40 FL	*- FL
1	*BONNET LOCK	Serviceable	152.80 FL	*- FL
1	*BONNET CABLE	Serviceable	55.20 FL	*- FL
1	*BONNET CABLE COVER	Serviceable	80.60 FL	*- FL
1	*BONNET SEAL OUTER	Serviceable	83.20 FL	*- FL
1	*BONNET SEAL INNER	Serviceable	70.10 FL	*- FL
1	*FENDER PANEL FRT LH	Serviceable	414.40 FL	*- FL
1	*WHEELARCH FRT LH	Serviceable	112.30 FL	*- FL
1	*FENDER BRACKET LOWER LH	Serviceable	11.80 FL	*-FL
1	*FENDER INSULATOR LH	Serviceable	65.50 FL	*-FL
1	*FENDER BRACKET FRT LH	Serviceable	38.90 FL	*-FL
1	*FENDER INSULATOR RH	Serviceable	66.30 FL	*-FL
1	*FENDER PANEL FRT RH	Serviceable	437.10 FL	*-FL
1	*WHEELARCH FRT RH	Serviceable	191.40 FL	*-FL
1	*FENDER BRACKET LOWER RH	Serviceable	11.80 FL	*-FL
1	*FENDER BRACKET FRT RH	Serviceable	106.40 FL	*-FL
1	*WIPER RESERVOIR	Serviceable	179.60 FL	*-FL
1	*WIPER RESERVOIR NECK	Serviceable	29.30 FL	*-FL
1				
1 1	*WIPER RESERVOIR MOTOR	Serviceable	82.60 FL	*-FL
1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		*HEADLAMP RH *HEADLAMP PANEL FRT LH  *HEADLAMP PANEL FRT RH *BONNET *BONNET INSULATOR *BONNET STRUT LH *BONNET STRUT RH *BONNET HINGE LH *BONNET HINGE RH *BONNET CABLE *BONNET CABLE *BONNET CABLE COVER *BONNET SEAL OUTER *BONNET SEAL INNER *FENDER PANEL FRT LH *WHEELARCH FRT LH *FENDER BRACKET LOWER LH *FENDER BRACKET FRT LH *FENDER INSULATOR RH *FENDER PANEL FRT RH *WHEELARCH FRT RH *WHEELARCH FRT RH *FENDER PANEL FRT RH *WHEELARCH FRT RH	*HEADLAMP RH  *HEADLAMP PANEL FRT LH  *HEADLAMP PANEL FRT RH  *BONNET  *BONNET  *BONNET INSULATOR  *BONNET STRUT LH  *BONNET STRUT LH  *BONNET HINGE LH  *BONNET HINGE RH  *BONNET CABLE  *BONNET CABLE  *BONNET SEAL OUTER  *BONNET SEAL INNER  *FENDER PANEL FRT LH  *FENDER BRACKET LOWER LH  *FENDER BRACKET FRT LH  *FENDER BRACKET LOWER RH  *FENDER BRACKET FRT RH  Serviceable  *FENDER BRACKET LOWER RH  *FENDER BRACKET LOWER RH  *FENDER BRACKET LOWER RH  *FENDER BRACKET FRT RH  Serviceable  *FENDER BRACKET LOWER RH  *FENDER BRACKET FRT RH  Serviceable  *FENDER BRACKET FRT RH  Serviceable	*HEADLAMP RH         Serviceable         743.60 FL           *HEADLAMP PANEL FRT LH         Serviceable         127.70 FL           *HEADLAMP PANEL FRT RH         Serviceable         128.30 FL           *BONNET         Serviceable         1,312.70 FL           *BONNET INSULATOR         Serviceable         294.30 FL           *BONNET STRUT LH         Serviceable         53.30 FL           *BONNET STRUT RH         Serviceable         236.50 FL           *BONNET HINGE LH         Serviceable         236.50 FL           *BONNET HINGE RH         Serviceable         237.40 FL           *BONNET LOCK         Serviceable         152.80 FL           *BONNET CABLE         Serviceable         55.20 FL           *BONNET CABLE         Serviceable         80.60 FL           *BONNET SEAL OUTER         Serviceable         83.20 FL           *BONNET SEAL INNER         Serviceable         70.10 FL           *FENDER PANEL FRT LH         Serviceable         414.40 FL           *WHEELARCH FRT LH         Serviceable         112.30 FL           *FENDER BRACKET LOWER LH         Serviceable         65.50 FL           *FENDER BRACKET FRT LH         Serviceable         66.30 FL           *FENDER BRACKET FRT RH         Serviceable </td

Report was unsubmitted during this print-out.

Adjuster Report Page 5 of 8

No.		Part No.	Particulars	Condition	Repairer's	Amount
101	1		*AIR CLEANER HOSE	Serviceable	76.14 FL	*-FL
	1		*AIR CLEANER BOX	Serviceable	464.20 FL	*-FL
03			*SUBFRAME OUTER FRT	Serviceable	1,094.20 FL	*-FL
	1		*SUBFRAME BRACKET OUTER LH	Serviceable	49.00 FL	*-FL
	1		*SUBFRAME BRACKET OUTER RH	Serviceable	49.00 FL	*- FL
	1		*A/C CONDENSER	Serviceable	1,537.80 FL	*- FL
	1		*A/C PIPE CONDENSER TO COMPRESSOR	Serviceable	187.20 FL	*- FL
	1		*A/C PIPE CONDENSER TO EXPANSION VALVE	Serviceable	380.20 FL	*- FL
109			*A/C PIPE COMPRESSOR	Serviceable	222.70 FL	*- FL
110			*A/C PIPE	Serviceable	486.50 FL	*- FL
	1		*LOWER ARM LH L70Y	Serviceable	192.70 FL	*- FL
112			*KNUCKLE ARM LH L70Y	Serviceable	481.50 FL	*- FL
	1		*ABSORBER FRT LH L70Y	Serviceable	274.10 FL	*- FL
114			*KNUCKLE HUB + BEARING LH/RH	Serviceable	272.30 FL	*- FL
115			*DRIVESHAFT LH	Serviceable	1,355.70 FL	*- FL
116			*STEERING PINION RACK	Serviceable	3,765.30 FL	*- FL
117			*STABILIZER BAR FRT	Serviceable	427.90 FL	*- FL
118			*LOWER ARM RH L70Y	Serviceable	192.70 FL	*- FL
119			*KNUCKLE ARM RH L70Y	Serviceable	481.50 FL	*- FL
120			*ABSORBER FRT RH L70Y	Serviceable	203.50 FL	*- FL
121			*DRIVESHAFT RH	Serviceable	1,355.70 FL	*- FL
122			*SET PARKING AID	Serviceable	700.00 FS	*-FS
123			*SET REAR BUMPER CLIP	Necessary	66.00 FS	*66.00 FS
124			*SET BUMPER BRACKET CTR CLIP	Necessary	33.00 FS	*33.00 FS
125			*SET BUMPER BRACKET SIDE CLIP RH RR	Not Necessary	10.00 FS	*- FS
126			*SET BUMPER RETAINER RH CLIP RR	Not Necessary	20.00 FS	*- FS
127			*SET BUMPER BRACKET SIDE CLIP LH RR	Not Necessary		*- FS
128			*SET BUMPER RETAINER CLIP LH RR	Not Necessary	20.00 FS	*-FS
129			*SET BUMPER LOWER REAR RIVET	Not Necessary		*-FS
	1		*SET BUMPER LOWER REAR CLIP	Necessary	66.00 FS	*66.00 FS
	1		*EXHAUST MOUNTING REAR	Not Necessary		*- FS
132			*EXHAUST BRACKET REAR	Repair	24.80 FS	*- FS
133			*SET REAR LICENCE PLATE WITH HOLDER	Serviceable	80.00 FS	*- FS
	1		*SET BOOT FINISHER CLIP	Not Necessary		*-FS
135			*BOOT INNER TRIM CLIP	Not Necessary	45.00 FS	*- FS
136			*TAILLAMP CLIP RH	Not Necessary	5.00 FS	*-FS
137			*TAILLAMP CLIP LH	Not Necessary		*-FS
138			*SET FENDER WHEELARCH REAR RH CLIP	Not Necessary		*- FS
139			*FENDER INNER TRIM CLIP RH	Not Necessary		*- FS
140			*REAR BUMPER PROTECTOR	Not Necessary		*-FS
141			*REAR WINDSCREEN SEALANT	Not Necessary		*-FS
142			*WINDSCREEN MOULDING	Not Necessary	100.00 FS	*-FS
143			*REAR WINDSCREEN INNER SPONGE SEAL	Not Necessary		*- FS
144			*SPARE TYRE RIM (ROUE 7J 16H 2547)	Serviceable	385.00 FS	*-FS
145			*SPARE TYRE	Serviceable	330.00 FS	*- FS
146			*BOOT STICKER TRANS-CAB	Necessary	30.00 FS	*30.00 FS
147			*BOOT STICKER 6555-3333	Necessary	30.00 FS	*30.00 FS
148			*SET RADIATOR GRILLE FRAME CLIP	Necessary	52.00 FS	*52.00 FS
149			*SET BUMPER CLIP FRT	Necessary	66.00 FS	*66.00 FS
150			*BUMPER BRACKET CLIP FRT LH	Not Necessary		*- FS
151			*BUMPER SUPPORT CLIP FRT LH	Not Necessary		*-FS
152			*BUMPER BRACKET CLIP FRT RH	Not Necessary		*- FS
153			*BUMPER SUPPORT CLIP FRT RH	Not Necessary		*-FS
154			*SET RADIATOR GRILLE SCREW	Not Necessary		*-FS
155			*SET BUMPER GRILLE LOWER CLIP	Not Necessary		*-FS
156			*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary		*-FS
157	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*-FS

https://singapore.merimen.com/claims/index.cfm?fusebox=MTRadjuster&fuseaction=ge... 5/5/2020

Adjuster Report Page 6 of 8

No.	Qty	Part No.	. Particulars	Condition	Repairer's	Amount
158	2		*FRAME FULL SUPPORT PANEL STUD	Not Necessary	30.00 FS	*-FS
159	1		*SET FRONT LICENCE PLATE WITH HOLDER	Bent	80.00 FS	*45.00 FS
160	1		*WHEELARCH CLIP FRT LH	Not Necessary		*-FS
161	1		*WHEELARCH CLIP FRT RH	Not Necessary	30.50 FS	*-FS
162	2		*BONNET CABLE COVER SCREW L70Y	Serviceable	10.85 FS	*-FS
163	2		*BONNET CABLE CLIP L70Y	Not Necessary		*-FS
164	1		*FRONT RH RENAULT TYRE RIM	Serviceable	385.00 FS	*-FS
165	1		*FRONT RH RENAULT TYRE	Serviceable	330.00 FS	*-FS
166	1		*FRONT LH RENAULT TYRE RIM	Serviceable		*-FS
167	1		*FRONT LH RENAULT TYRE	TYRE Serviceable		*-FS
168	1		*REAR LH RENAULT TYRE RIM	Serviceable		*-FS
169	1		*REAR LH RENAULT TYRE	Serviceable	330.00 FS	*- FS
170	1		*REAR RH RENAULT TYRE RIM	Serviceable	385.00 FS	*-FS
171	1		*REAR RH RENAULT TYRE	Serviceable	330.00 FS	*-FS
F=Fra	nchise	part. S=Spo	cNett. L=ListItemDisc.			
				Sub Total (S\$)	53,352.36	5,060.36
			- List Item Discount on L Items 10	0.00/10.00% (S\$)	4,760.12	467.24
				Total Parts (S\$)	48,592.24	4,593.12
			Report was unsubmitted during this pri	nt-out.		

Adjuster Report Page 7 of 8

# Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
2	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME	New	9,000.00	600.00
3	TO DROP DIESEL TANK,PIPES,HOSES TO FACILITATE BODYWORK REPAIR,FINAL CHECKING AND TESTING	New	380.00	0.00
4	TO DROP REAR EXHAUST BOX,RENEW THE SAME,TO REPAIR AND REALIGN CENTRE EXHAUST PIPE	New	170.00	60.00
5	TO TRANSFER OF REAR END PANEL FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	170.00	0.00
6	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	9,000.00	880.00
7	TO REINSTALL REAR BUMPER PARKING SENSOR	New	170.00	60.00
8	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	30.00
9	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	30.00
10	TO TRANSFER OF BOOTLID FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	170.00	60.00
11	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING	New	380.00	0.00
12	TO TRANSFER OF REAR WINDSCREEN GLASS TO FACILITATE BODYWORK REPAIR	New	170.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH, TO FACILITATE REPAIR	New	380.00	0.00
14	TO DISMANTLE AND REFIT AIRCON ASSY AND ATTACHMENT, VACUUM AND CHARGE-IN-GAS	New	380.00	0.00
15	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
16	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH, FITTINGS AND OTHER,TO ENABLE REPAIR	New	380.00	0.00
17	TO REPAIR AND REALIGN REAR EXHAUST PIPE	New	170.00	0.00
18	TO TRANSFER OF FENDER FITTINGS,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	340.00	0.00
19	TO TRANSFER OF FRONT BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
20	TO TRANSFER OF FRONT BONNET FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
21	TO TRANSFER OF REAR BUMPER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	180.00	0.00
22	TO TRANSFER OF TIRE, RIM AND ON WHEEL BALANCING	New	170.00	0.00
23	TO TRANSFER OF REAR FENDER FITTINGS,ATTACHMENT AND PERFORM WATER SEEPAGE TEST	New	380.00	0.00
24	TO DISMANTLE AND REFIT FRONT END SUSPENSION,UNDERCARRIAGE PARTS,FINAL CHECKING AND TESTING	New	380.00	0.00
25		New	380.00	0.00
	Report was unsubmitted during	g this print-out.		

Adjuster Report Page 8 of 8

No	Particulars	Lab.Type	Repairer's	Amount
	TO CHECK ABS AND BRAKE EFFICIENCY,FINAL CHECKING AND TESTING			
26	TO VACUUM,REPLACE,REFIX AND RECHARGE AIR CONDENSER	New	380.00	0.00
	Gross Lab	our Cost (S\$)	24,220.00	1,720.00
	Report was unsubmitted du	ring this print-out.		

< END OF ESTIMATES >