

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kah Leong

Date: 20 Dec 2019

**Preliminary Advice**

Vehicle No	: SFV398R	Accident Date	: 10/12/2019
Make	: TOYOTA LEXUS GS300 AUTO	Policy No.	: DMPCSN3075291901
Assignment Date	: 20/12/2019	Excess	: S\$500.00
Date of Inspection	: 20/12/2019	Est. Duration of Repair	: 16
Inspection At	: CHENG HOE MOTOR PTE LTD		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages n/s front portion, o/s body and undercarriage and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	21,836.30
Revised Amount	:S\$	17,057.08
Check Items (Estimated)	:S\$	2,805.00
Total	:S\$	19,862.08
 Lump Sum Repair (estimated)	 :S\$	 15,900.00

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	48,000.00
COE / PARF Rebate	:S\$	40,113.00
Salvage Value	:S\$	
Margin for Repair	:S\$	7,887.00

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( X ) Other comments :Kindly advice on offer repair cost to repairer. Please note the margin repair cost is \$7,887.00