



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving 1 2009 HYUNDAI AVANTE 1.6 (SJS5369K)

Date of Loss 15 December 2019

Time of Loss 12.30

Loss Description SJS5369K (insd) C/W WALL

Comment

Workshop Details

Total Rebate Amount 29306

Nett Loss Amount \$7,694.00

Assigned Workshop LKK AUTO CONSULTANTS PTE LTD (OD)

Days of work completion 20

*



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJS5369K

Registration State SINGAPORE

Mileage 204202

Purchase Date dd/mm/yyyy

Registration Date * 24/08/2009



Age of Vehicle 10

Driver Details

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2009	2009
Make	HYUNDAI	HYUNDAI
Model	AVANTE 1.6	HD AVANTE 1.6 A
Type		
Type of Paint		
Chassis No	KMH DU41BR9U802951	KMH DU41BR9U8029!
Engine No	G4FC9U681620	G4FC9U681620

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	RAJA FADDLY SHAH BIN RAJA MD LOKMAN	
Date of Birth	26 May 1999	dd/mm/yyyy
Age	20	
Occupation	Unknown	
Education Qualification	Other	
Driving Experience	2	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Engine Capacity		<input type="text" value="1591"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="37000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver License #		<input type="text"/>
License Type		<input type="text" value="▼"/>
License Issue Date	1 January 2018	<input type="text" value="dd/mm/yyyy"/> 
License Expiration Date		<input type="text" value="dd/mm/yyyy"/> 
Address	BLK 121 PENDING RD #08-158, 670121, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Male	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	S9917010G	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

20/12/2019



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

2800

Young/Inexperienced/Unn
amed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Fair ▼

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Fair ▼

Tyre Condition

Age of Tyres

Front Tyre Size

195/60R15

Front left side

FIRENZA6mm

Front right side

FIRENZA6mm

Spare wheel

Rear Tyre Size

195/60R15

Rear left side

FIRENZA6mm

Rear right side

FIRENZA6mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

Yes

No

Part Supplied by AXA

Yes

No

Save







































<< Assessment Details





































General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary





































Parts








































Add Approve Deny Submit All





































	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		FRONT NUMBER PLATE (NPA) (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		FRONT BUMPER (WCP) (10%)	Deformed	0	220	No					220	Reviewing	
		0	1		FRONT BUMPER SPOILER (WCP) (10%)	Cut	0	22	No					22	Reviewing	
		0	1		FRT BUMPER AIR GRILL (WCP) (10%)	Cut	0	38.5	No					38.5	Reviewing	
		0	1		FRT BUMPER ABSORBER (WCP) (10%)	Cracked	0	60.5	No					60.5	Reviewing	
		0	1		L/BUMPER MNTG REINF (WCP) (10%)	Bent	0	27.5	No					27.5	Reviewing	
		0	1		R/BUMPER MNTG REINF (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		LEFT RETAINER (WCP) (10%)	Necessary	0	19.8	No					19.8	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		RIGHT RETAINER (WCP) (10%)	Necessary	0	19.8	No					19.8	Reviewing	
		0	1		FRT BUMPER SUPPORT (WCP) (10%)	Bent	0	126.5	No					126.5	Reviewing	
		0	1		FRT BUMPER CLAMP KIT (WCP) (10%)	Necessary	0	16.5	No					16.5	Reviewing	
		0	1		GRILLE (WCP) (10%)	Cracked	0	143	No					143	Reviewing	
		0	1		BONNET (WCP) (10%)	Bent	0	385	No					385	Reviewing	
		0	1		LEFT BONNET HINGE (WCP) (10%)	Bent	0	27.5	No					27.5	Reviewing	
		0	1		RIGHT BONNET HINGE (WCP) (10%)	Bent	0	27.5	No					27.5	Reviewing	
		0	1		BONNET LOCK (WCP) (10%)	Bent	0	27.5	No					27.5	Reviewing	
		0	1		BONNET FRONT SEAL (WCP) (10%)	Necessary	0	13.2	No					13.2	Reviewing	
		0	1		LEFT HEADLAMP ASSY (WCP) (10%)	Cracked	0	209	No					209	Reviewing	
		0	1		RIGHT HEADLAMP ASSY (WCP) (10%)	Cracked	0	209	No					209	Reviewing	
		0	1		L/F FOG LAMP (WCP) (10%)	Cracked	0	88	No					88	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		L/F WING (WCP) (10%)	Buckled	0	154	No					154	Reviewing	
		0	1		R/F WING (WCP) (10%)	Bent	0	154	No					154	Reviewing	
		0	1		L/F WING BADGE (NPA) (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		R/F WING BADGE (NPA) (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		L/F WHEELHOUSE COVER (WCP) (10%)	Cracked	0	38.5	No					38.5	Reviewing	
		0	1		R/F WHEELHOUSE COVER (WCP) (10%)	Cracked	0	38.5	No					38.5	Reviewing	
		0	1		L/SCREW (WCP) (10%)	Necessary	0	13.2	No					13.2	Reviewing	
		0	1		R/SCREW (WCP) (10%)	Necessary	0	13.2	No					13.2	Reviewing	
		0	1		INNER FRT PANEL CPL (WCP) (10%)	Deformed	0	275	No					275	Reviewing	
		0	1		BATTERY CARRIER (WCP) (10%)	Cracked	0	22	No					22	Reviewing	
		0	1		LWR WINDSCREEN COVER (WCP) (10%)	Cut	0	55	No					55	Reviewing	
		0	1		L/COWL MOULDING (WCP) (10%)	Cut	0	17.6	No					17.6	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		R/COWL MOULDING (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		REAR BUMPER (WCP) (10%)	Deformed	0	242	No					242	Reviewing	
		0	1		RR BUMPER CLAMP KIT (WCP) (10%)	Necessary	0	16.5	No					16.5	Reviewing	
		0	1		L/R OUTER LAMP (WCP) (10%)	Broken	0	104.5	No					104.5	Reviewing	
		0	1		L/NUT (WCP) (10%)	Necessary	0	2.2	No					2.2	Reviewing	
		0	1		R/NUT (WCP) (10%)	Necessary	0	2.2	No					2.2	Reviewing	
		0	1		AIR CON CONDENSER (WCP) (10%)	Bent	0	198	No					198	Reviewing	
		0	1		COND / EVAPORATOR PIPE (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		COMPR / EVAP PIPE (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		L/F ENGINE MOUNTING (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		R/F ENGINE MOUNTING (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		L/F LWR CONTROL ARM (WCP) (10%)	Bent	0	121	No					121	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV/ AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		L/F SHOCK ABSORBER (WCP) (10%)	Bent	0	137.5	No					137.5	Reviewing	
		0	1		L/F STEERING KNUCKLE (WCP) (10%)	Bent	0	143	No					143	Reviewing	
		0	1		L/F WHEEL BEARING (WCP) (10%)	Necessary	0	49.5	No					49.5	Reviewing	
		0	1		L/F WHEEL HUB (WCP) (10%)	Bent	0	82.5	No					82.5	Reviewing	
		0	1		L/F WHEEL (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		L/F TYRE (NPA) (WCP) (10%)	Damaged	0	0	No					0	Reviewing	
		0	1		L/TIE ROD (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		R/TIE ROD (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		L/OUTER TIE ROD BALL (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		R/OUTER TIE ROD BALL (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		L/RADIATOR AIR GUIDE (WCP) (10%)	Cut	0	18.7	No					18.7	Reviewing	
		0	1		R/RADIATOR AIR GUIDE (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		RADIATOR (WCP) (10%)	Bent	0	286	No					286	Reviewing	

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		LWR RADIATOR HOSE (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		FAN SHROUD CPL (WCP) (10%)	Cracked	0	126.5	No					126.5	Reviewing	
		0	1		AIR INTAKE HOSE (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		AIR FILTER RESONATOR (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		R/ENGINE MOUNTING (WCP) (10%)	Cracked	0	99	No					99	Reviewing	
		0	1		LWR ENG COMP COVER (WCP) (10%)	Cracked	0	33	No					33	Reviewing	
		0	1		BATTERY (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		BATTERY BOX (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		FRT BUMPER (WCP) (10%)	Necessary	0	16.5	No					16.5	Reviewing	
		0	1		FRT BONNET LOCK (WCP) (10%)	Serviceable	0	0	No					0	Deny	
		0	1		ENGINE MOUNTING FRONT (WCP) (10%)	Cracked	0	77	No					77	Reviewing	
		0	1		ENGINE MOUNTING REAR (WCP) (10%)	Cracked	0	77	No					77	Reviewing	

	EDIT	SR NO	QUANTITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR/ BTTR%	DISCOUNT%	SALVAGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)	REMOVE
		0	1		ENGINE MOUNTING (WCP) (10%)	Cracked	0	110	No					110	Reviewing	
		0	1		ENGINE MOUNTING (WCP) (10%)	Cracked	0	110	No					110	Reviewing	
		0	1		FRONT AXLE SUPPORT (WCP) (10%)	Cracked	0	990	No					990	Reviewing	
		0	1		L/F STABILIZER LINKAGE (WCP) (10%)	Bent	0	49.5	No					49.5	Reviewing	
		0	1		REAR BUMPER SUPPORT (WCP) (10%)	Cracked	0	126.5	No					126.5	Reviewing	
		0	1		STEERING GEAR (WCP) (10%)	Bent	0	770	No					770	Reviewing	

Labour

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		TO CHECK WIRING	0	20	0	0	Reviewing		
		0		TOP UP AIRCON GAS	0	30	0	0	Reviewing		
		0		TO DO WHEEL ALIGNMENT	0	60	0	0	Reviewing		
		0		TO DO WHEEL ALIGNMENT	0	0	0	0	Deny		
		0		TOTAL 230.0 WU X 45.00 SGD/H	0	850.5	0	0	Reviewing		
		0		ALIGNMENT MEASURING WORK	0	27	0	0	Reviewing		

EDIT		SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT	REMOVE
		0		LABOUR COST 175.0 WU X 45.0 SGD / H	0	787.5	0	0	Reviewing		
		0		MATERIAL COST	0	366.99	0	0	Reviewing		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary

Add Approve Deny Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	DAYS OF REPAIR : 9 DAYS	Reviewing		0		
		0	[E] : FRT BUMPER CLAM P KIT: (NPA)	Deny		0	SERVICEABLE	
		0	FRT NUMBER PLATE	Reviewing		35	SCRATCHED	
		0	COOLANT	Reviewing		20	NECESSARY	
		0	BATTERY	Deny		0	SERVICEABLE	
		0	FRT TYRE LH (\$280.00) (70%)	Reviewing		196	PUNCTURED	
		0	FRT RIM LH	Reviewing		150	BENT	

[SERVICE REQUESTS](#)[MESSAGES](#)[CLAIMS](#)

Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$6,193.39	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$6,450.40			
Labour		\$0.00		\$2,141.99			
Miscellaneous		\$0.00		\$401.00			
Excess				-\$2,800.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
		0	FINAL LUMP SUM	Reviewing	7000		



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$4,200.00	
CATEGORY		ESTIMATE		ADJUSTED			
Miscellaneous		\$0.00		\$7,000.00			
Excess				-\$2,800.00			

Submit for Review