

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC6/AIG19022436/AHA3Q2**Date:** 12/05/2020REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : SDV7632S **Insured Vehicle No :** SJT9215P

Date of Loss: 18/12/2019 Nature of Claim: TP Claim No: 3611059398SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDV7632S	Engine No:	2ARU031697
Make & Model:	TOYOTA CAMRY, 2.5 HYBRID CVT (A)	Chassis No:	MR053CK5004011750
Reg. Date:	21/05/2013 (Man. Year: 2013)	Odometer:	162605 km
Colour:	Grey		
Engine Capacity:	2494 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R17	Rear Tyre Size:	225/50 R17
Front Left Side:	Michelin 6 mm	Rear Left Side:	Michelin 6 mm
Front Right Side:	Michelin 6 mm	Rear Right Side:	Michelin 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	21,131.55	5,296.70	15,834.85	74.93
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,680.00	2,220.00	2,460.00	52.56
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	25,811.55	7,516.70	18,294.85	70.88
Approved Total (Overridden) (S\$)		6,000.00		
(S\$)	25,811.55	6,000.00	19,811.55	76.75
+ GST 7.00/7.00% (S\$)	1,806.81	420.00	1,386.81	76.75
Nett Amount (S\$)	27,618.36	6,420.00	21,198.36	76.75
+ Loss of Use (7.0 x S\$60.00/day) (S\$)		420.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,847.45		
Global Sum Settlement (S\$)		6,800.00		

INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 19/12/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)
1 Kaki Bukit Ave 6, #01-46/48/50
Autobay
Singapore 417883

Estimated Period of Repair: 7.0 days

Adjuster: ADRIAN LING

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BONNET	Not Necessary	1,243.90 FL	*- FL
2	1		*FRONT BONNET CHROME MOULDING	Not Necessary	246.00 FL	*- FL
3	1		*FRONT BONNET LOCK	Not Necessary	128.20 FL	*- FL
4	1		*FRONT BONNET LOCK CATCH	Not Necessary	55.90 FL	*- FL
5	1		*FRONT BONNET INSULATOR	Not Necessary	258.00 FL	*- FL
6	2		*FRONT BONNET HINGE	Not Necessary	113.20 FL	*- FL
7	2		*FRONT BONNET ABSORBER	Not Necessary	585.00 FL	*- FL
8	1		*FRONT GRILLE	Cracked	510.50 FL	*510.50 FL
9	1		*FRONT GRILLE LOGO	Necessary	60.10 FL	*60.10 FL
10	1		*FRONT SUPPORT PANEL	Not Necessary	1,084.40 FL	*- FL
11	1		*FRONT HEAD LAMP ASSY	O/S Cracked	5,700.00 FL	*1,345.00 FL
12	2		*FRONT HORN	Not Necessary	292.60 FL	*- FL
13	1		*FRONT BUMPER	Deformed	567.70 FL	*567.70 FL
14	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	411.40 FL	*- FL
15	2		*FRONT BUMPER SIDE RETAINER	Necessary	133.40 FL	*133.40 FL
16	2		*FRONT BUMPER FOG LAMP	Not Necessary	616.60 FL	*- FL
17	2		*FRONT BUMPER FOG LAMP COVER	Not Necessary	317.40 FL	*- FL
18	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	97.70 FL	*- FL
19	1		*FRONT BUMPER INNER SPONGE	Cracked	135.50 FL	*135.50 FL
20	1		*FRONT BUMPER LOWER GRILLE CHROME	Not Necessary	280.50 FL	*- FL
21	1		*FRONT NUMBER PLATE GARNISH	Cracked	65.80 FL	*65.80 FL
22	2		*FRONT BUMPER FOG LAMP COVER OUTER RIM	Not Necessary	130.00 FL	*- FL
23	2		*FRONT FENDER	Not Necessary	1,172.60 FL	*- FL
24	1		*REAR BOOT LID	Repair	931.30 FL	*- FL
25	1		*REAR BOOT LOCK	Not Necessary	892.20 FL	*- FL
26	1		*REAR BOOT LOCK CATCH	Not Necessary	51.80 FL	*- FL
27	1		*REAR BOOT LID CENTRE GARNISH	Not Necessary	393.80 FL	*- FL
28	1		*REAR BOOT LID CENTRE EMBLEM	Not Necessary	77.40 FL	*- FL
29	1		*REAR BOOT LID (HYBRID)	Necessary	48.20 FL	*48.20 FL
30	1		*REAR BOOT INNER BOARD	Not Necessary	499.80 FL	*- FL
31	1		*REAR BOOT EMBLEM (CAMRY)	Necessary	58.50 FL	*58.50 FL
32	1		*REAR BOOT EMBLEM (HYBRID SYNERGY DRIVE)	Necessary	48.20 FL	*48.20 FL
33	1		*REAR BOOT CENTRE EMBLEM	Necessary	77.40 FL	*77.40 FL
34	2		*REAR BOOT REFLECTOR LAMP	Not Necessary	798.80 FL	*- FL
35	2		*REAR BOOT HINGE	Not Necessary	243.80 FL	*- FL
36	1		*REAR BOOT RUBBER	Cut	207.30 FL	*207.30 FL
37	2		*REAR BOOT NUMBER PLATE LAMP	Not Necessary	73.40 FL	*- FL
38	2		*REAR TAIL LAMP	Cracked	1,378.40 FL	*842.60 FL
39	2		*REAR TAIL LAMP PANEL	Not Necessary	489.60 FL	*- FL
40	2		*REAR TAIL LAMP LOWER BRACKET	Not Necessary	50.40 FL	*- FL
41	1		*REAR END PANEL	Dented	647.30 FL	*647.30 FL
42	1		*REAR END PANEL TOP GARNISH	Deformed	421.30 FL	*221.30 FL
43	2		*REAR FENDER INNER GARNISH	Not Necessary	838.60 FL	*- FL
44	1		*REAR SPARE TYRE PANEL TOP COVER BOARD	Not Necessary	244.80 FL	*- FL
45	1		*REAR BUMPER	Distorted	585.70 FL	*585.70 FL
46	2		*REAR BUMPER SIDE RETAINER	Necessary	206.20 FL	*206.20 FL
47	1		*REAR BUMPER TOWING COVER	Not Necessary	26.50 FL	*- FL
48	1		*REAR BUMPER REINFORCEMENT	Bent	561.30 FL	*455.60 FL
49	1		*REAR EXHAUST SILENCER	Repair	981.30 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
50	2		*REAR EXHAUST RUBBER	Not Necessary	121.60 FL	*- FL
51	1		*REAR EXHAUST CHROME TAIL PIPE	Bent	125.00 FL	*125.00 FL
52	1		*REAR BUMPER LOWER COVER	Deformed	86.30 FL	*86.30 FL
53	4		*REAR BUMPER PARKING SENSOR	Damaged (2 PCS ONLY)	1,300.00 FL	*500.00 FL
54	4		*REAR BUMPER PARKING SENSOR HOLDER	Not Necessary	166.80 FL	*- FL
55	4		*REAR TAIL LAMP CLIPS	Necessary	26.00 FS	*26.00 FS
56	12		*REAR FENDER INNER GARNISH CLIPS	Not Necessary	78.00 FS	*- FS
57	12		*REAR BOOT INNER BOARD CLIPS	Not Necessary	78.00 FS	*- FS
58	1		*SET REAR BUMPER CLIP	Necessary	80.00 FS	*30.00 FS
59	1		*REAR NUMBER PLATE	Not Necessary	45.00 FS	*- FS
60	1		*REAR REVERSE CAMERA	Not Necessary	650.00 FS	*- FS
61	1		*FRONT NUMBER PLATE	Bent	45.00 FS	*45.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	27,841.40	7,028.60
- List Item Discount on L Items 25.00/25.00% (\$)	6,709.85	1,731.90
Total Parts (\$)	21,131.55	5,296.70

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	150.00	60.00
2	TUFF KOTE	New	200.00	60.00
3	REMOVE AND REFIX UPHOLSTERY	New	160.00	60.00
4	REMOVE AND REPLACE EXHAUST PIPE	New	160.00	80.00
5	REMOVE AND REPLACE REVERSE SENSOR	New	160.00	60.00
6	TO REMOVE AND REPLACE SPARE PART AND PANEL BEATING	New	1,800.00	900.00
7	TO SPRAY PAINTING AND ETC	New	1,800.00	1,000.00
8	REMOVE AND REFIX AIRCON CONDENSER AND REFIX GAS	New	150.00	0.00
9	REMOVE AND REFIX RADIATOR	New	100.00	0.00
			Gross Labour Cost (\$\$)	2,220.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >