

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC6/AIG19022438/ABA3Q2

**Date:** 24/06/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

**Claimant**  
**Vehicle No :** GBJ200M **Insured Vehicle No :** GBH307A

**Date of Loss:** 18/12/2019 **Nature of Claim:** TP **Claim No:** 7603007470SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

|                             |                                    |             |                   |
|-----------------------------|------------------------------------|-------------|-------------------|
| Reg No:                     | GBJ200M                            |             |                   |
| Make & Model:               | TOYOTA HIACE, 3.0 D TURBO 5 DR (M) | Engine No:  | 1KD2829130        |
| Reg. Date:                  | 23/11/2018 (Man. Year: 2018)       | Chassis No: | JTFHT02P100245773 |
| Colour:                     | Silver                             | Odometer:   | 40996 km          |
| Engine Capacity:            | 2982 cc                            |             |                   |
| Market Value/New Car Price: | N/A                                |             |                   |
| Sum Insured (\$\$):         | <b>Market Value/New Car Price</b>  |             |                   |

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |                         |                      |                          |                         |
|--------------------------|-------------------------|----------------------|--------------------------|-------------------------|
| General Condition:       | Steering (Serviceable): | Yes                  | Footbrake (Serviceable): | Yes                     |
| Handbrake (Serviceable): | Yes                     | Engine Modification: | No                       | Pre-accident Condition: |

### CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 195 R15C         | Rear Tyre Size:  | 195 R15C         |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

*The above values represent the remaining tyre treads depth*

| <b>COST OF CLAIMS</b>                             | <b>Repairer's</b> | <b>Adjuster's</b> | <b>Difference</b> | <b>Diff %</b> |
|---------------------------------------------------|-------------------|-------------------|-------------------|---------------|
| Parts                                             | 16,465.00         | 5,369.80          | 11,095.20         | 67.39         |
| Miscellaneous Items                               | 0.00              | 0.00              | 0.00              |               |
| Labour                                            | 5,820.00          | 2,880.00          | 2,940.00          | 50.52         |
| Paintwork Labour                                  | 0.00              | 0.00              | 0.00              |               |
| Towing                                            | 0.00              | 0.00              | 0.00              |               |
| <b>Calculated Gross Total (\$\$)</b>              | <b>22,285.00</b>  | <b>8,249.80</b>   | <b>14,035.20</b>  | <b>62.98</b>  |
| <b>Approved Total (Overridden) (\$\$)</b>         |                   | <b>6,600.00</b>   |                   |               |
| <b>(\$\$)</b>                                     | 22,285.00         | 6,600.00          | 15,685.00         | 70.38         |
| <b>+ GST 7.00/7.00% (\$\$)</b>                    | 1,559.95          | 462.00            | 1,097.95          | 70.38         |
| <b>Nett Amount (\$\$)</b>                         | <b>23,844.95</b>  | <b>7,062.00</b>   | <b>16,782.95</b>  | <b>70.38</b>  |
| <b>+ Loss of Use (9.0 x S\$100.00/day) (\$\$)</b> |                   | 900.00            |                   |               |
| <b>+ Doc/Search Fee (\$\$)</b>                    |                   | 2.00              |                   |               |
| <b>Nett Liability (\$\$)</b>                      |                   | <b>7,964.00</b>   |                   |               |
| <b>Global Sum Settlement (\$\$)</b>               |                   | <b>7,400.00</b>   |                   |               |

### INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 19/12/2019 Inspected At:

Fastech Auto Pte Ltd (HQ)  
1 Kaki Bukit Ave 6, #01-46/48/50  
Autobay  
Singapore 417883

Estimated Period of Repair: 7.0 days

---

**Adjuster:** ADRIAN LING**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

| No. | Qty | Part No. | Particulars                                | Condition     | Repairer's  | Amount       |
|-----|-----|----------|--------------------------------------------|---------------|-------------|--------------|
| 1   | 1   |          | *REAR BOOT COVER                           | Distorted     | 2,265.00 FL | *1,772.70 FL |
| 2   | 1   |          | *REAR BOOT RUBBER                          | Cut           | 328.50 FL   | *328.50 FL   |
| 3   | 1   |          | *REAR BOOT LOCK                            | Jammed        | 265.10 FL   | *265.10 FL   |
| 4   | 2   |          | *REAR BOOT HINGE                           | Not Necessary | 170.40 FL   | *- FL        |
| 5   | 2   |          | *REAR BOOT ABSORBER                        | Not Necessary | 570.00 FL   | *- FL        |
| 6   | 1   |          | *REAR BOOT CENTRE GARNISH                  | Cracked       | 176.50 FL   | *176.50 FL   |
| 7   | 1   |          | *REAR BOOT INNER BOARD                     | Torn          | 315.20 FL   | *165.30 FL   |
| 8   | 1   |          | *REAR BOOT WINDSCREEN GLASS MOULDING       | Necessary     | 1,243.60 FL | *172.50 FL   |
| 9   | 1   |          | *REAR BOOT LOCK ACTUATOR                   | Damaged       | 410.60 FL   | *245.30 FL   |
| 10  | 1   |          | *REAR BOOT MIRROR WITH BRACKET             | Not Necessary | 356.50 FL   | *- FL        |
| 11  | 1   |          | *REAR BOOT WIPER MOTOR                     | Not Necessary | 498.50 FL   | *- FL        |
| 12  | 1   |          | *REAR BOOT WIPER ARM                       | Not Necessary | 145.40 FL   | *- FL        |
| 13  | 1   |          | *REAR BOOT WIPER BLADE                     | Not Necessary | 89.50 FL    | *- FL        |
| 14  | 1   |          | *REAR BOOT EMBLEM LOGO                     | Necessary     | 65.20 FL    | *65.20 FL    |
| 15  | 1   |          | *REAR BOOT STICKER TOYOTA                  | Necessary     | 38.50 FL    | *38.50 FL    |
| 16  | 1   |          | *REAR BOOT STICKER HIACE                   | Necessary     | 38.50 FL    | *38.50 FL    |
| 17  | 1   |          | *REAR END PANEL INNER                      | Dented        | 850.00 FL   | *585.00 FL   |
| 18  | 1   |          | *REAR END PANEL OUTER                      | Dented        | 486.50 FL   | *486.50 FL   |
| 19  | 1   |          | *REAR THIRD BRAKE LIGHT                    | Not Necessary | 410.40 FL   | *- FL        |
| 20  | 1   |          | *REAR FLOOR BOARD PANEL                    | Repair        | 2,381.40 FL | *- FL        |
| 21  | 1   |          | *REAR BUMPER                               | Deformed      | 498.00 FL   | *498.00 FL   |
| 22  | 2   |          | *REAR BUMPER SIDE RETAINER                 | Necessary     | 121.60 FL   | *121.60 FL   |
| 23  | 4   |          | *REAR BUMPER LOWER SUPPOT BRACKET          | Bent          | 224.80 FL   | *180.00 FL   |
| 24  | 2   |          | *REAR NUMBER PLATE LAMP                    | Not Necessary | 131.20 FL   | *- FL        |
| 25  | 2   |          | *REAR TAILLAMP                             | Cracked       | 704.60 FL   | *610.00 FL   |
| 26  | 1   |          | *REAR TAILLAMP GARNISH                     | O/S Torn      | 219.00 FL   | *109.50 FL   |
| 27  | 1   |          | *REAR EXHAUST SILENCER                     | Not Necessary | 825.00 FL   | *- FL        |
| 28  | 2   |          | *REAR EXHAUST RUBBER                       | Not Necessary | 117.40 FL   | *- FL        |
| 29  | 1   |          | *REAR SPARE TYRE CARRIER                   | Bent          | 412.10 FL   | *345.00 FL   |
| 30  | 1   |          | *REAR BOOT RUBBER TOP GARNISH              | Bent          | 82.70 FL    | *82.70 FL    |
| 31  | 2   |          | *REAR FENDER                               | Repair        | 4,111.20 FL | *- FL        |
| 32  | 2   |          | *REAR FENDER INNER BOARD                   | Not Necessary | 730.40 FL   | *- FL        |
| 33  | 1   |          | *REAR FENDER AIR DUCT                      | Not Necessary | 76.70 FL    | *- FL        |
| 34  | 1   |          | *REAR WOODEN FLOOR BOARD PANEL             | Not Necessary | 550.00 FS   | *- FS        |
| 35  | 1   |          | *SET REAR BUMPER CLIP                      | Necessary     | 50.00 FS    | *30.00 FS    |
| 36  | 1   |          | *SET REAR WINDSCREEN GLASS SEALANT         | Necessary     | 120.00 FS   | *60.00 FS    |
| 37  | 1   |          | *REAR 70KM STICKER                         | Necessary     | 25.00 FS    | *15.00 FS    |
| 38  | 1   |          | *SET RESERSING SENSOR                      | Damaged       | 350.00 FS   | *200.00 FS   |
| 39  | 1   |          | *SET REAR BOOT COVER ,SIDE PANEL LETTERING | Necessary     | 850.00 FS   | *350.00 FS   |

F=Franchise part. S=SpcNett. L=ListItemDisc.

**Sub Total (\$\$) 21,305.00 6,941.40**  
**- List Item Discount on L Items 25.00/25.00% (\$\$) 4,840.00 1,571.60**

**Total Parts (\$\$) 16,465.00 5,369.80**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars                                                                    | Lab.Type | Repairer's      | Amount          |
|---------------------------------|--------------------------------------------------------------------------------|----------|-----------------|-----------------|
| <b><u>Labour Items</u></b>      |                                                                                |          |                 |                 |
| 1                               | TO CHECK WIRING                                                                | New      | 100.00          | 30.00           |
| 2                               | APPLY ANTI RUST CHEMICAL                                                       | New      | 150.00          | 80.00           |
| 3                               | REMOVE & REFIX REAR WINDSCREEN GLASS                                           | New      | 150.00          | 120.00          |
| 4                               | REMOVE,REFIX & RENEW REAR EXHAUST PIPE                                         | New      | 150.00          | 0.00            |
| 5                               | REMOVE & REFIX REAR FLOOR MAT ETC                                              | New      | 120.00          | 0.00            |
| 6                               | REMOVE & RENEW REVERSING SENSOR                                                | New      | 150.00          | 50.00           |
| 7                               | LABOUR CHARGE KNOCK DENTS ON REAR DAMAGE<br>PORTION CUT ,WELDING & RENEW PARTS | New      | 2,500.00        | 1,300.00        |
| 8                               | TO SPRAY PAINT AFFECTED PORTION                                                | New      | 2,500.00        | 1,300.00        |
| <b>Gross Labour Cost (\$\$)</b> |                                                                                |          | <b>5,820.00</b> | <b>2,880.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >