



ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	: GBE/SVC/SALES-4982/191218
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/12/2019
Attn.	: ENKGWOKLONG	Policy No.	:
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
1		GLASS, WINDSHIELD <i>cr</i>	1	1,131.37	1,131.37	1,131.37
2		WEATHERSTRIP, WINDSHIELD <i>nc</i>	1	486.78	486.78	486.78
3		GARNISH, FR PANEL <i>cr</i>	1	373.08	373.08	373.08
4		PANEL ASSY, FR <i>bt</i>	1	2,367.22	2,367.22	2,367.22
5		RAIL ASSY, WINDSHIELD <i>bt</i>	1	1,439.87	1,439.87	1,439.87
6		MARK, FUSO <i>nc</i>	1	150.59	150.59	150.59
7		MARK, 3-DIA <i>nc</i>	1	80.22	80.22	80.22
8		EMBLEM, CANTER <i>mps</i>	1	76.22	76.22	76.22
9		GRILLE, FRONT <i>mis</i>	1	719.33	719.33	719.33
10		GRILLE CLIP <i>nc</i>	8	6.19	6.19	49.52
11		PAD, RADIATOR GRILLE BRACKET <i>nc</i>	2	11.15	11.15	22.30
12		BRKT, RADIATOR GRILLE -CTR <i>bt</i>	1	25.52	25.52	25.52
13		PANEL, CAB FR CORNER -LH <i>cr</i>	1	492.41	492.41	492.41
14		PANEL, CAB FR CORNER -RH <i>x su</i>	1	492.41	492.41	492.41
15		CAP, MIRROR COVER (FLAP) <i>mis</i>	1	28.83	28.83	28.83
16		COVER, RR VIEW MIRROR STAY (ROUND) <i>mis</i>	1	13.42	13.42	13.42
17		MIRROR, UNDER VIEW <i>cut</i>	1	55.22	55.22	55.22
18		BUMPER, FR <i>ble</i>	1	948.37	948.37	948.37
19		STAY, FR BUMPER -LH <i>bt</i>	1	190.69	190.69	190.69
20		STAY, FR BUMPER -RH <i>x su</i>	1	190.69	190.69	190.69
21		BRKT, FR BUMPER, RH <i>x su</i>	1	158.92	158.92	158.92
22		BRKT, FR BUMPER, LH <i>bt</i>	1	158.92	158.92	158.92
23		COVER, FR BUMPER -LH <i>tan</i>	1	332.06	332.06	332.06
24		COVER, FR BUMPER -RH <i>x su</i>	1	332.06	332.06	332.06
25		HORN, ELECTRIC HIGH <i>at</i>	1	144.72	144.72	144.72
26		COVER, HORN <i>bt</i>	1	32.11	32.11	32.11
27		PIPE ASSY, HEATER WATER <i>bt</i>	1	71.67	71.67	71.67
28		C FUSO LLC 4L <i>nc</i>	1	62.00	62.00	62.00
29		CLAMP, HEATER WATER (TOP) <i>x su</i>	2	7.32	7.32	14.64
30		AIR INTAKE BOX, HEATER UNIT <i>? cr</i>	1	845.66	845.66	845.66
31		HEATER UNIT <i>? cr</i>	1	2,384.46	2,384.46	2,384.46
32		BRACKET, CAB FR MOUNTING CROSSMEMBER, RH <i>3 bt</i>	1	800.08	800.08	800.08



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 5 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

Page 2 / 5

ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD,	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	: GBE/SVC/SALES-4982/191218
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/12/2019
Attn.	: ENGKWOKLONG	Policy No.	:
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
33		C/MBR ASSY,FR.FLOOR (CENTER) ? bt ✓	1	462.67	462.67	462.67
34		BRKT,CAB HINGE (LH) ? bt ✓	1	896.98	896.98	896.98
35		LEVER,ANCHOR (OUTER MOST)CAP ? bt ✓	1	243.00	243.00	243.00
36		BAR,TORSTION ? bt ✓	1	583.15	583.15	583.15
37		CUSHION,CAB FR (MOUNTING) ? ne ✓	1	216.12	216.12	216.12
38		BUSHING,CAB FR MOUNTING YELLOW ? ne ✓	1	17.92	17.92	17.92
39		CONNECTOR (BRAKE JOINT 3) X sue	1	206.69	206.69	206.69
40		PIPE ASSY,BRAKE X sue	1	240.18	240.18	240.18
41		HEADLAMP ASSY -LH bro ✓	1	470.69	470.69	470.69
42		BEZEL,HEADLAMP,LWR me ✓	1	14.14	14.14	14.14
43		RIVET,SCREW (BEZEL HEADLAMP) ne ✓	2	2.55	2.55	5.10
44		LAMP ASSY,TURN SIGNAL,FR -LH bro ✓	1	197.31	197.31	197.31
45		GARNISH, HEADLAMP -LH bro ✓	1	216.22	216.22	216.22
46		HEADLAMP ASSY -RH bro ✓	1	470.69	470.69	470.69
47		LAMP ASSY,TURN SIGNAL,FR -RH X sue	1	192.83	192.83	192.83
48		CROSSMEMBER,CHASSIS FRAME (A) bt ✓	1	1,153.62	1,153.62	1,153.62
49		LINK,W/SHLD WIPER ? X sue	1	614.32	614.32	614.32
50		TANK,W/SHLD WASHER ? X sue	1	155.74	155.74	155.74
51		CLIP,INSTRUMENT PANEL UNDER TRIM ne ✓	6	3.42	3.42	20.52
52		PILLAR, FR -LH LOWER bt ✓	1	1,315.31	1,315.31	1,315.31
53		PANEL ASSY,FR DR 02TD DOM bro ✓	1	1,944.56	1,944.56	1,944.56
54		LATCH,F/DOOR POWER ? X sue	1	652.21	652.21	652.21
55		REGULATOR ASSY,F/DR PWR WD ? X sue	1	1,279.57	1,279.57	1,279.57
56		TRIM ASSY,FR DOOR LWR LH ? X sue	1	403.25	403.25	403.25
57		DECAL,BLUETEC ne ✓	1	41.12	41.12	41.12
58		SCUFF PLATE,FR LH cu ✓	1	101.46	101.46	101.46
59		FENDER,SIDE,FR UPR -LH (DOOR) de ✓	1	64.93	64.93	64.93
60		HOSE, A/C PIPING,NO.2 bt ✓	1	474.84	474.84	474.84
61		HOSE, A/C PIPING,NO.3 (SMALL) st ✓	1	444.43	444.43	444.43
62		CONDENSER A/C REFRIGERANT st ✓	1	650.00	650.00	650.00
63		REAR BRACKET, A/C CONDENSER st ✓	1	805.52	805.52	805.52
64		MOTOR,A/C CONDENSER FAN ? short ✓	1	433.28	433.28	433.28
65		RECEIVER ASSY X sue	1	288.15	288.15	288.15

FUSO AIRMAN.

biSAFE
ST & R





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3575

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Ce Reg No: 158039630

Page 3 / 5

ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	: GBE/SVC/SALES-4982/191218
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/12/2019
Attn.	: ENGBKWOKLONG	Policy No.	:
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
66		FRONT BRACKET, A/C CONDENSER "X" <i>bt</i>	2	35.84	35.84	71.68
67		FENDER, FR FLOOR SIDE -LH (TOP OF AC CONDENSER) <i>bt</i>	1	304.96	304.96	304.96
68		STEP, FR SIDE -LH (BLACK) <i>bn</i>	1	285.00	285.00	285.00
69		GARNISH, AIR OUTLET <i>? xsu</i>	1	47.23	47.23	47.23
70		RESERVOIR, P/S OIL <i>? xsu</i>	1	541.44	541.44	541.44
71		TANK, RADIATOR SURGE (Superseded from ME418253) <i>? xsu</i>	1	176.31	176.31	176.31
72		BRKT, W/WPR MOTOR <i>? xsu</i>	1	110.33	110.33	110.33
73		MOTOR, W/SHLD WIPER <i>? xsu</i>	1	643.30	643.30	643.30
PARTS TOTAL :					32,128.13	

SPECIAL NETT ITEMS

1	IU BRACKET <i>ne</i>	1	20.00
2	NUMBER PLATE <i>bt</i>	1	25.00
3	BRAKE FLUID <i>X an</i>	1	45.00
PARTS TOTAL:			90.00

FUSO

AIRMAN.

bizSAFE
S T & R





ESTIMATE

Date :	18/12/2019	Reg No :	YQ1085M
To :	CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model :	FEB21ER4SDEN CBU MT
Attn. :		Chassis No :	FEB21EA30197
Office / Mobile :		Engine No :	4P10D74589
Email Address :		Quotation No. :	102036
		Ref. No. :	GBE/SVC/SALES-4982/191218
From :	GOLDBELL ENGINEERING PTE LTD	D.O.A. :	17/12/2019
Attn. :	ENGKWOKLONG	Policy No. :	
Office / Mobile :	+65 6864 0637	Claim Type :	OD CLAIM - CHINA TAIPING
Email / Fax No. :	EngKwokLong@goldbell.com.sg	Workshop :	8 TUAS AVE 18

LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	4800.00 4200
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	200.00 180
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1575 2100.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR	200.00 180
5	TO TRANSFER/REMOVE/INSTALL DOOR LOCK MECHANISM, WINDOW REGULATOR, WINDOW GLASS, DOOR TRIM TO NEW DOOR UNIT.	300.00 250
6	TO REMOVE AND REFIX FRONT DASHBOARD	600 700.00
7	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION	600 700.00
8	TOP UP AIRCON GAS	100 120.00
9	TO REMOVE, REFIX AND REALIGN FRONT CABIN	450 600.00
10	TO REMOVE & REFIX POWER STEERING TANK ASSY/COOLANT SPARE TANK/ BRAKE SYSTEM, TO CHECK FUNCTION	700.00 500 ? XAN

LABOUR TOTAL : 10,420.00

SUB-TOTAL : 43794.01 42,638.13

GST @ 7% for \$ 42,638.13 2,984.67

GRAND TOTAL (\$\$) : 45,622.80



ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
From	: GOLDBELL ENGINEERING PTE LTD	Ref. No.	: GBE/SVC/SALES-4982/191218
Attn.	: ENKWOKLONG	D.O.A.	: 17/12/2019
Office / Mobile	: +65 6864 0637	Policy No.	:
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Claim Type	: OD CLAIM - CHINA TAIPING
		Workshop	: 8 TUAS AVE 18

PREPARED BY : ENKWOKLONG

DATE / TIME : 23/12/19 @ 1630

SURVEYOR : Rasul

MOBILE NO : 90010068

OFFICE FAX NO :

EMAIL ADDRESS : rasul@lkkauto.com

[Signature]
26/12/19

EXCESS AMOUNT : 450

REPAIR TYPE : PART-BY-PART / LUMP SUM

AUTHORISATION : AUTHORISED NOT AUTHORISED

RE-SURVEY : BEFORE PAINT AFTER PAINT

NO. OF DAYS : 12 days

REMARKS :

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 16 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 16 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 198003963G

Page 1 / 1

SUPPLEMENTARY

Date	: 04/02/2020	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	:
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/12/2019
Attn.	: ENKWOKLONG	Policy No.	: GBE/SVC/SALES-4982/191218
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
1		STEP FENDER, FR FLOOR SIDE -LH	1	328.61	328.61	328.61
2		PANEL, SHIELD FR 04TD EXP W	1	227.27	227.27	227.27
PARTS TOTAL :						555.88

LABOUR CHARGES

1 TO REMOVE AND REFIX DAMAGED PARTS,
CUT, WELD, PANEL BEAT, STRAIGHTEN &
REALIGN, ETC.

450 600.00 A

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
to submit to final approval from Insurance Company

LABOUR TOTAL :	600.00
SUB-TOTAL :	1,155.88
GST @ 7% for \$ 1155.88	80.91
GRAND TOTAL (S\$) :	1,236.79

ACKNOWLEDGED BY: ENKWOKLONG

Signature: _____
Date: 05/02/2020 @ 14:55
SURVEYOR: Raul CLKK
MOBILE NO: _____
OFFICE FAX NO: _____
EMAIL ADDRESS: _____


EXCESS AMOUNT : _____
REPAIR TYPE : PART-BY-PART / LUMP SUM
AUTHORISATION : AUTHORISED / NOT AUTHORISED
RE-SURVEY : BEFORE PAINT / AFTER PAINT
NO. OF DAYS : _____

REMARKS :

FUSO AIRMAN.

P: 25719.92
S/N: 45
L: 8135
Supp: 1005.88
Total: 34905.80 A

bizSAFE
S T R





GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3600
Website: www.goldbell.com.sg
Co. Reg. No.: 199003963G


Page 1 / 5

ESTIMATE

Date : 18/12/2019
To : CHINA TAIPING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :
From : GOLDBELL ENGINEERING PTE LTD
Attn. : ENKWKOLONG
Office / Mobile : +65 6864 0637
Email / Fax No. : EngKwokLong@goldbell.com.sg

Reg No : YQ1085M
Model : FEB21ER4SDEN CBU MT
Chassis No : FEB21EA30197
Engine No : 4P10D74589
Quotation No. : 102036
Ref. No. : GBE/SVC/SALES-4982/191218
D.O.A. : 17/12/2019
Policy No. :
Claim Type : OD CLAIM - CHINA TAIPING
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
1		GLASS, WINDSHIELD <i>cm</i>	1	1,131.37	1,131.37	1,131.37
2		WEATHERSTRIP, WINDSHIELD <i>nei</i>	1	486.78	486.78	486.78
3		GARNISH, FR PANEL <i>cm</i>	1	373.08	373.08	373.08
4		PANEL ASSY, FR <i>bt</i>	1	2,367.22	2,367.22	2,367.22
5		RAIL ASSY, WINDSHIELD <i>bt</i>	1	1,439.87	1,439.87	1,439.87
6		MARK, FUSO <i>nei</i>	1	150.59	150.59	150.59
7		MARK, 3-DIA <i>nei</i>	1	80.22	80.22	80.22
8		EMBLEM, CANTER <i>MP3</i>	1	76.22	76.22	76.22
9		GRILLE, FRONT <i>MIS</i>	1	719.33	719.33	719.33
10		GRILLE CLIP <i>nei</i>	8	6.19	6.19	49.52
11		PAD, RADIATOR GRILLE BRACKET <i>nei</i>	2	11.15	11.15	22.30
12		BRKT, RADIATOR GRILLE -CTR <i>bt</i>	1	25.52	25.52	25.52
13		PANEL, CAB FR CORNER -LH <i>cm</i>	1	492.41	492.41	492.41
14		PANEL, CAB FR CORNER -RH <i>X</i>	1	492.41	492.41	492.41
15		CAP, MIRROR COVER (FLAP) <i>MIS</i>	1	28.83	28.83	28.83
16		COVER, RR VIEW MIRROR STAY (ROUND) <i>MIS</i>	1	13.42	13.42	13.42
17		MIRROR, UNDER VIEW <i>cut</i>	1	55.22	55.22	55.22
18		BUMPER, FR <i>ble</i>	1	948.37	948.37	948.37
19		STAY, FR BUMPER -LH <i>bt</i>	1	190.69	190.69	190.69
20		STAY, FR BUMPER -RH <i>X</i>	1	190.69	190.69	190.69
21		BRKT, FR BUMPER, RH <i>X</i>	1	158.92	158.92	158.92
22		BRKT, FR BUMPER, LH <i>bt</i>	1	158.92	158.92	158.92
23		COVER, FR BUMPER -LH <i>tan</i>	1	332.06	332.06	332.06
24		COVER, FR BUMPER -RH <i>X</i>	1	332.06	332.06	332.06
25		HORN, ELECTRIC HIGH <i>cut</i>	1	144.72	144.72	144.72
26		COVER, HORN <i>bt</i>	1	32.11	32.11	32.11
27		PIPE ASSY, HEATER WATER <i>st</i>	1	71.67	71.67	71.67
28		C FUSO LLC 4L <i>nei</i>	1	62.00	62.00	62.00
29		CLAMP, HEATER WATER (TOP) <i>X</i>	2	7.32	7.32	14.64
30		AIR INTAKE BOX, HEATER UNIT <i>?cm</i>	1	845.66	845.66	845.66
31		HEATER UNIT <i>cm</i>	1	2,384.46	2,384.46	2,384.46
32		BRACKET, CAB FR MOUNTING CROSSMEMBER, RH <i>3bt</i>	1	800.08	800.08	800.08



AIRMAN.



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.


GOLDBELL ENGINEERING PTE LTD
Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3378
Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 1960036939

Page 2 / 5

ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	: GBE/SVC/SALES-4982/191218
		D.O.A.	: 17/12/2019
From	: GOLDBELL ENGINEERING PTE LTD	Policy No.	:
Attn.	: ENKWOKLONG	Claim Type	: OD CLAIM - CHINA TAIPING
Office / Mobile	: +65 6864 0637	Workshop	: 8 TUAS AVE 18
Email / Fax No.	: EngKwokLong@goldbell.com.sg		

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
33		C/MBR ASSY,FR.FLOOR (CENTER) <i>?bt</i>	1	462.67	462.67	462.67
34		BRKT,CAB HINGE (LH) <i>?bt</i>	1	896.98	896.98	896.98
35		LEVER,ANCHOR (OUTER MOST)CAP <i>(LH photo?)</i>	1	243.00	243.00	243.00
36		BAR,TORSTON <i>? (bt) photo?</i>	1	583.15	583.15	583.15
37		CUSHION,CAB FR (MOUNTING) <i>?ne</i>	1	216.12	216.12	216.12
38		BUSHING,CAB FR MOUNTING YELLOW <i>?ne</i>	1	17.92	17.92	17.92
39		CONNECTOR (BRAKE JOINT 3) <i>X</i>	1	206.69	206.69	206.69
40		PIPE ASSY,BRAKE <i>X</i>	1	240.18	240.18	240.18
41		HEADLAMP ASSY -LH <i>bro</i>	1	470.69	470.69	470.69
42		BEZEL,HEADLAMP,LWR <i>mis</i>	1	14.14	14.14	14.14
43		RIVET,SCREW (BEZEL HEADLAMP) <i>ne</i>	2	2.55	2.55	5.10
44		LAMP ASSY,TURN SIGNAL,FR -LH <i>bro</i>	1	197.31	197.31	197.31
45		GARNISH, HEADLAMP -LH <i>bro</i>	1	216.22	216.22	216.22
46		HEADLAMP ASSY -RH <i>bro</i>	1	470.69	470.69	470.69
47		LAMP ASSY,TURN SIGNAL,FR -RH <i>X</i>	1	192.83	192.83	192.83
48		CROSSMEMBER,CHASSIS FRAME (A) <i>bt</i>	1	1,153.62	1,153.62	1,153.62
49		LINK,W/SHLD WIPER	1	614.32	614.32	614.32
50		TANK,W/SHLD WASHER <i>?</i>	1	155.74	155.74	155.74
51		CLIP,INSTRUMENT PANEL UNDER TRIM <i>ne</i>	6	3.42	3.42	20.52
52		PILLAR, FR -LH LOWER <i>bt</i>	1	1,315.31	1,315.31	1,315.31
53		PANEL ASSY,FR DR 02TD <i>DOM base</i>	1	1,944.56	1,944.56	1,944.56
54		LATCH,F/DOOR POWER	1	652.21	652.21	652.21
55		REGULATOR ASSY,F/DR PWR WD <i>?</i>	1	1,279.57	1,279.57	1,279.57
56		TRIM ASSY,FR DOOR LWR LH	1	403.25	403.25	403.25
57		DÉCAL,BLUETEC <i>ne</i>	1	41.12	41.12	41.12
58		SCUFF PLATE,FR LH <i>cu</i>	1	101.46	101.46	101.46
59		FENDER,SIDE,FR UPR -LH (DOOR) <i>de</i>	1	64.93	64.93	64.93
60		HOSE, A/C PIPING,NO.2 <i>bt</i>	1	474.84	474.84	474.84
61		HOSE, A/C PIPING,NO.3 (SMALL) <i>bt</i>	1	444.43	444.43	444.43
62		CONDENSER A/C REFRIGERANT <i>bt</i>	1	650.00	650.00	650.00
63		REAR BRACKET, A/C CONDENSER <i>bt</i>	1	805.52	805.52	805.52
64		MOTOR,A/C CONDENSER FAN <i>? ✓ whatsapp.</i>	1	433.28	433.28	433.28
65		RECEIVER ASSY <i>X</i>	1	288.15	288.15	288.15



AIRMAN.



ESTIMATE

Date : 18/12/2019
To : CHINA TAIPING INSURANCE
(SINGAPORE) PTE. LTD.
Attn. :
Office / Mobile :
Email Address :
From : GOLDBELL ENGINEERING PTE LTD
Attn. : ENKWOKLONG
Office / Mobile : +65 6864 0637
Email / Fax No. : EngKwokLong@goldbell.com.sg

Reg No : YQ1085M
Model : FEB21ER4SDEN CBU MT
Chassis No : FEB21EA30197
Engine No : 4P10D74589
Quotation No. : 102036
Ref. No. : GBE/SVC/SALES-4982/191218
D.O.A. : 17/12/2019
Policy No. :
Claim Type : OD CLAIM - CHINA TAIPING
Workshop : 8 TUAS AVE 18

S/N	Part No	Description	Qty	U/Price	Net Price	Ext Price
66		FRONT BRACKET, A/C CONDENSER "X" <i>bt</i>	2	35.84	35.84	71.68
67		FENDER, FR FLOOR SIDE -LH (TOP OF AC CONDENSER) <i>bt</i>	1	304.96	304.96	304.96
68		STEP, FR SIDE -LH (BLACK) <i>bro</i>	1	285.00	285.00	285.00
69		GARNISH, AIR OUTLET	1	47.23	47.23	47.23
70		RESERVOIR, P/S OIL ?	1	541.44	541.44	541.44
71		TANK, RADIATOR SURGE (Superseded from ME418253)	1	176.31	176.31	176.31
72		BRKT, W/WPR MOTOR ?	1	110.33	110.33	110.33
73		MOTOR, W/SHLD WIPER ?	1	643.30	643.30	643.30
PARTS TOTAL :						32,128.13

SPECIAL NETT ITEMS

1	IU BRACKET <i>new</i>	1		20.00
2	NUMBER PLATE <i>st</i>	1		25.00
3	BRAKE FLUID <i>X</i>	1		45.00
PARTS TOTAL:				90.00



AIRMAN.



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 635602 Tel: 6861 0007 Fax: 6861 2878
Finance: 8 Tuas Avenue 18 Singapore 635602 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No: 198503093G

Page 4 / 5

ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	: GBE/SVC/SALES-4982/191218
		D.O.A.	: 17/12/2019
From	: GOLDBELL ENGINEERING PTE LTD	Policy No.	:
Attn.	: ENKWOKLONG	Claim Type	: OD CLAIM - CHINA TAIPING
Office / Mobile	: +65 6864 0637	Workshop	: 8 TUAS AVE 18
Email / Fax No.	: EngKwokLong@goldbell.com.sg		


LABOUR CHARGES

1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	4800.00 4200
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK	200.00 180
3	TO PUTTY, CLEAN, SPRAY PAINT AND POLISH, ETC	1575 2100.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR	200.00 180
5	TO TRANSFER/REMOVE/INSTALL DOOR LOCK MECHANISM, WINDOW REGULATOR, WINDOW GLASS, DOOR TRIM TO NEW DOOR UNIT.	300.00 250
6	TO REMOVE AND REFIX FRONT DASHBOARD	600 700.00
7	TO REMOVE AND REFIX AIRCON SYSTEM, TO CHECK FUNCTION	600 700.00
8	TOP UP AIRCON GAS	100 120.00
9	TO REMOVE, REFIX AND REALIGN FRONT CABIN	450 600.00
10	TO REMOVE & REFIX POWER STEERING TANK ASSY/COOLANT SPARE TANK/ BRAKE SYSTEM, TO CHECK FUNCTION	700.00 500?

LABOUR TOTAL :	10,420.00
SUB-TOTAL :	42,638.13
GST @ 7% for \$ 42,638.13	2,984.67
GRAND TOTAL (S\$) :	45,622.80

FUSO AIRMAN.

bizSAFE
STARK



GOLDBELL ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 630392 Tel: 6861 0007 Fax: 6861 3876
Finance: 5 Tuas Avenue 18 Singapore 630392 Tel: 6861 0007 Fax: 6862 3800
Website: www.goldbell.com.sg
Co. Reg. No.: 16903963G

Page 5 / 5

ESTIMATE

Date	: 18/12/2019	Reg No	: YQ1085M
To	: CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.	Model	: FEB21ER4SDEN CBU MT
Attn.	:	Chassis No	: FEB21EA30197
Office / Mobile	:	Engine No	: 4P10D74589
Email Address	:	Quotation No.	: 102036
		Ref. No.	: GBE/SVC/SALES-4982/191218
From	: GOLDBELL ENGINEERING PTE LTD	D.O.A.	: 17/12/2019
Attn.	: ENKWOKLONG	Policy No.	:
Office / Mobile	: +65 6864 0637	Claim Type	: OD CLAIM - CHINA TAIPING
Email / Fax No.	: EngKwokLong@goldbell.com.sg	Workshop	: 8 TUAS AVE 18


PREPARED BY : ENKWOKLONG

DATE / TIME : 23/12/19 @ 1630
SURVEYOR : Rahul
MOBILE NO : 90010068
OFFICE FAX NO :
EMAIL ADDRESS : rahul@kkauto.com

EXCESS AMOUNT :
REPAIR TYPE : PART-BY-PART / LUMP SUM
AUTHORISATION : AUTHORISED NOT AUTHORISED
RE-SURVEY : BEFORE PAINT AFTER PAINT
NO. OF DAYS : 12 days
REMARKS :

FUSO AIRMAN.

bizSAFE
STARS





GOLDBELL ENGINEERING

Industrial Vehicles, Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 630892 Tel: 6861 0007 Fax: 6861 3670
Finance: 8 Tuas Avenue 18 Singapore 630892 Tel: 6861 0007 Fax: 6862 3500
Website: www.goldbell.com.sg
Co. Reg. No.: 199003963G

Page 1 / 1

CHINA TAIPING INSURANCE (SINGAPORE) PTE.
LTD.
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Attn: MS SHARON

TAX INVOICE

GST Reg No. : M9-0002514-E
Invoice No. : EXI00211217
Invoice Date. : 20-02-2020
Account No. : C00004902
Quotation No. : 102036
Work Order No. : 915767
Service Centre. : 8 TUAS AVE 18
Agreement No. : GBE-44968

PARTICULARS		AMOUNT SGD		
Reg No	: YQ1085M			
Chassis No	: FEB21EA30197			
Engine No	: 4P10D74589			
Model No	: FEB21ER4SDEN CBU MT			
Mileage	: 22751			
SRR No	:			
ACCIDENT REPAIR: GBE/SVC/SALES-4982/191218				
DATE OF ACCIDENT: 17/12/2019				
POLICY NO.:				
**** OD CLAIM - CHINA TAIPING****				
<u>Description</u>	<u>QTY</u>	<u>Disc</u>	<u>Net Price</u>	<u>Ext Price</u>
COST OF REPAIR	1	N	34573.74	34573.74
LESS : EXCESS CHARGES BORNE BY OWNER	-1	N	-450.00	-450.00
			Parts Charges:	34123.74
			Sub Total:	34123.74
			GST @ 7.00 %	2388.66
E. & O. E				
TOTAL				36512.40

Please make all cheques payable to GOLDBELL ENGINEERING PTE LTD.
When making payment, please quote our invoice numbers.
No receipts will be issued for Cheque Payments.

Terms and conditions of sales

Interest at 1.5% per month will be charged on overdue account

This is a computer generated document. No signature is required.



AIRMAN.





GOLDBELL
ENGINEERING

Industrial Vehicles. Financial Services.
41,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

Main Office: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6861 3676

Finance: 8 Tuas Avenue 18 Singapore 638892 Tel: 6861 0007 Fax: 6862 3500

Website: www.goldbell.com.sg

Co. Reg No: 198003553G

SATISFACTION VOUCHER

To: Goldbell Engineering Pte Ltd.
8 Tuas Avenue 18
Singapore 638892

Date:
Reference:

We hereby confirm the receipt of the our vehicle in good and working condition from the repairer;
M/s Goldbell Engineering Pte Ltd., and that all necessary repairs resulting from the below mentioned
accident had been completed to our satisfactory.

Vehicle Number: YQ1085M
Make & Model : MITSUBISHI CANTER FEB21ER4SDEN CBU MT E6 (NEW)
Chassis Number: FEB21EA30197
Engine Number : 4P10D74589
Accident Date : 17/12/2019
Claim Reference: GBE/SVC/SALES-4982/191218
Remarks : OD CLAIM - CHINA TAIPING

On behalf of M/s : ACTINIUM ENGINEERING PTE. LTD.

Signature & Company
Stamp :

Name :

Date :



AIRMAN.



SATISFACTION VOUCHER

Name & Address of Insured: Actinium Engineering Pte Ltd.

Name & Address of Repairers: Goldbell Engineering Pte Ltd.

Date & Place of Accident: 17/12/2019

Policy No: DMCVSN3054161900 Claim No: _____

Vehicle No: YQ1085M Cost of Repairs: \$34573.74 (Before GST)

I/We hereby declare that I/We have received from the aforesaid repairers my/our aforesaid Motor Vehicle in good running order and repaired to my/our entire satisfaction and in consideration of CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD., settling the repair costs stated above with the said repairers I/We hereby release and discharge the said Insurers from all further obligations and liabilities under the aforesaid policy in respect of an accident involving my/our said motor vehicle on the above-mentioned date and place.

I/We agree that by virtue of such payment the said Insurers are subrogated to all my/our rights and remedies in respect of the damage to the said Motor Vehicle in accordance with the laws governing the Contract of Insurance.

I/We hereby grant the said Insurers the authority to use my/our name to the extent necessary to effectively exercise all or any of such rights and remedies including the right to give discharge and receipts therefor. I/We further agree to furnish the said insurers with any assistance that they may reasonably require of me/us when exercising such rights and remedies whilst on their part they agree to indemnify me/us against liability for costs charges and expenses arising in connection with any proceedings which they may take in my/our name in the exercise of such rights and remedies.

REPAIRERS:-



Company's Chop & Signature

INSURED:-



Company's Chop & Signature

WITNESS:-

Brian Eng.

Name & Signature

8 Tuas Ave 18, S638892

Address

2/3/2020

Date

WITNESS:-

Tan Chay Heng

Name & Signature

Address

2/3/2020

Date

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	23 Dec 2019		23 Dec 2019 10:54 Edit Adj Rpt	S\$34,573.74 Edit Estimates	S\$34,573.74 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: ACTINIUM ENGINEERING PTE LTD , Co. Reg. No.: 20111223H									
Vehicle Reg. No.: YQ1085M		Date of Loss: 17/12/2019 18:00 - :59 [5 Months and 1 Days From LTA Reg Date (Man Yr)]							
Claim Type: OD / SNM19D206047C01		Policy/Cover Note No.: DMCVSN3054161900 (Comprehensive)							
		Excess: S\$450.00							
Repairer: Goldbell Engineering Pte Ltd (Pandan) Blk K, Pandan Loop Industrial Estate, #01-12, 128219 Tuas - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Irene Tay Hui Ping - 638986192]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD RASUL] ... [Final Rpt due 03/01/2020]									
Driver/Custodian: MUTHIAH RAJAKUMAR (40 / Male) , NRIC: F8347539X, Tel: +6582045790 Email: NOEMAIL									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
- CHINA_TAIPING (20/02/2020): Alert - Adj Mandate Approved (S\$34573.74) - YQ1085M - Claim Handler: Irene Tay H... - CHINA_TAIPING (26/12/2019): Alert - Adj Mandate Approved (S\$38888.56) - YQ1085M - Claim Handler: Irene Tay H...									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***YQ1085M (SNM19D206047C01)**
OD
Dec 17 2019 6:00PM
[ACTINIUM ENGINEERING PTE LTD]
Goldbell Engineering Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View [View in Browser](#) ▼

Assessment Reports			1 per page ▼	✓
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 15:44	Accident Statement	1 Load HTM	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 12:01	Adjuster Immediate Advice	1 Load HTM	
2	18/02/20 11:44	Adjuster Immediate Advice	1 Load HTM	
Photos/Images			3 per page ▼	✓
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
2	18/12/19 15:32	INSURED LORRY CHASSIS NUMBER [Linked Accident Report Documents]	1 Load JPG	✓
3	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
4	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
5	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
6	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
7	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
8	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
9	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
10	18/12/19 15:32	INSURED LORRY [Linked Accident Report Documents]	1 Load JPG	✓
11	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
12	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
13	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
14	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
15	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
16	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
17	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
18	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
19	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
20	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
21	18/12/19 15:34	ACCIDENT SCENE [Linked Accident Report Documents]	1 Load JPG	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 11:48	General View	1 Load JPG	✓
2	24/12/19 11:48	General View	1 Load JPG	✓

Assessment Reports			1 per page ▼	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
3	24/12/19 11:48	General View	 Load JPG	☒
4	24/12/19 11:48	General View	 Load JPG	☒
5	24/12/19 11:48	General View	 Load JPG	☒
6	24/12/19 11:48	General View	 Load JPG	☒
7	24/12/19 11:48	General View	 Load JPG	☒
8	24/12/19 11:48	General View	 Load JPG	☒
9	24/12/19 11:48	General View	 Load JPG	☒
10	24/12/19 11:48	General View	 Load JPG	☒
11	24/12/19 11:48	General View	 Load JPG	☒
12	24/12/19 11:48	General View	 Load JPG	☒
13	24/12/19 11:48	General View	 Load JPG	☒
14	24/12/19 11:48	General View	 Load JPG	☒
15	24/12/19 11:48	General View	 Load JPG	☒
16	24/12/19 11:48	General View	 Load JPG	☒
17	24/12/19 11:48	General View	 Load JPG	☒
18	24/12/19 11:48	General View	 Load JPG	☒
19	24/12/19 11:48	General View	 Load JPG	☒
20	24/12/19 11:48	General View	 Load JPG	☒
21	24/12/19 11:48	General View	 Load JPG	☒
22	24/12/19 11:48	General View	 Load JPG	☒
23	24/12/19 11:48	General View	 Load JPG	☒
24	24/12/19 11:48	General View	 Load JPG	☒
25	24/12/19 11:48	General View	 Load JPG	☒
26	24/12/19 11:48	General View	 Load JPG	☒
27	24/12/19 11:48	General View	 Load JPG	☒
28	24/12/19 11:48	General View	 Load JPG	☒
29	24/12/19 11:48	General View	 Load JPG	☒
30	24/12/19 11:48	General View	 Load JPG	☒
31	24/12/19 11:48	General View	 Load JPG	☒
32	24/12/19 11:48	General View	 Load JPG	☒
33	24/12/19 11:48	General View	 Load JPG	☒
34	24/12/19 11:48	General View	 Load JPG	☒
35	24/12/19 11:48	General View	 Load JPG	☒
36	24/12/19 11:48	General View	 Load JPG	☒
37	24/12/19 11:49	General View	 Load JPG	☒
38	24/12/19 11:49	General View	 Load JPG	☒
39	24/12/19 11:49	General View	 Load JPG	☒
40	24/12/19 11:49	General View	 Load JPG	☒
41	24/12/19 11:49	General View	 Load JPG	☒
42	24/12/19 11:49	General View	 Load JPG	☒
43	24/12/19 11:49	General View	 Load JPG	☒
44	24/12/19 11:49	General View	 Load JPG	☒
45	24/12/19 11:49	General View	 Load JPG	☒
46	24/12/19 11:49	General View	 Load JPG	☒
47	24/12/19 11:49	General View	 Load JPG	☒
48	24/12/19 11:49	General View	 Load JPG	☒
49	24/12/19 11:49	General View	 Load JPG	☒
50	24/12/19 11:49	General View	Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
51	24/12/19 11:49	General View	 Load JPG	☒
52	24/12/19 11:49	General View	 Load JPG	☒
53	24/12/19 11:49	General View	 Load JPG	☒
54	24/12/19 11:49	General View	 Load JPG	☒
55	24/12/19 11:49	General View	 Load JPG	☒
56	24/12/19 11:49	General View	 Load JPG	☒
57	24/12/19 11:49	General View	 Load JPG	☒
58	24/12/19 11:49	General View	 Load JPG	☒
59	24/12/19 11:49	General View	 Load JPG	☒
60	24/12/19 11:49	General View	 Load JPG	☒
61	24/12/19 11:49	General View	 Load JPG	☒
62	24/12/19 11:49	General View	 Load JPG	☒
63	24/12/19 11:49	General View	 Load JPG	☒
64	24/12/19 11:49	General View	 Load JPG	☒
65	24/12/19 11:49	General View	 Load JPG	☒
66	24/12/19 11:49	General View	 Load JPG	☒
67	24/12/19 11:49	General View	 Load JPG	☒
68	24/12/19 11:49	General View	 Load JPG	☒
69	24/12/19 11:49	General View	 Load JPG	☒
70	24/12/19 11:49	General View	 Load JPG	☒
71	24/12/19 11:49	General View	 Load JPG	☒
72	24/12/19 11:49	General View	 Load JPG	☒
73	24/12/19 11:49	General View	 Load JPG	☒
74	24/12/19 11:49	General View	 Load JPG	☒
75	24/12/19 11:49	General View	 Load JPG	☒
76	24/12/19 11:49	General View	 Load JPG	☒
77	24/12/19 11:49	General View	 Load JPG	☒
78	24/12/19 11:49	General View	 Load JPG	☒
79	24/12/19 11:49	General View	 Load JPG	☒
80	24/12/19 11:49	General View	 Load JPG	☒
81	24/12/19 11:49	General View	 Load JPG	☒
82	24/12/19 11:49	General View	 Load JPG	☒
83	24/12/19 11:49	General View	 Load JPG	☒
84	24/12/19 11:49	General View	 Load JPG	☒
85	24/12/19 11:49	General View	 Load JPG	☒
86	24/12/19 11:49	General View	 Load JPG	☒
87	24/12/19 11:49	General View	 Load JPG	☒
88	24/12/19 11:49	General View	 Load JPG	☒
89	24/12/19 11:49	General View	 Load JPG	☒
90	24/12/19 11:49	General View	 Load JPG	☒
91	24/12/19 11:49	General View	 Load JPG	☒
92	24/12/19 11:49	General View	 Load JPG	☒
93	24/12/19 11:49	General View	 Load JPG	☒
94	24/12/19 11:49	General View	 Load JPG	☒
95	24/12/19 11:49	General View	 Load JPG	☒
96	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
97	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
98	18/02/20 11:31	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
99	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
100	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
101	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
102	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
103	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
104	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
105	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
106	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
107	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
108	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
109	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
110	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
111	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
112	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
113	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
114	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
115	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
116	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
117	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
118	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
119	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
120	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
121	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
122	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
123	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
124	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
125	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
126	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
127	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
128	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
129	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
130	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
131	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
132	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
133	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
134	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
135	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
136	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
137	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
138	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
139	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
140	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
141	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
142	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
143	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
144	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
145	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
146	18/02/20 11:31	Reinspection Photo	Load JPG	☒

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
147	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
148	18/02/20 11:31	Reinspection Photo	 Load JPG	☒
Documentation			1 per page	☒
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	23/12/19 10:55	repair estimate	 Load PDF	
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 15:28	Sketch Plan [Linked Accident Report Documents]	 Load TIF	
2	18/12/19 15:28	Sketch Plan #2 [Linked Accident Report Documents]	 Load TIF	
3	18/12/19 15:29	POLICE REPORT PAGE 1 [Linked Accident Report Documents]	 Load TIF	
4	18/12/19 15:29	POLICE REPORT PAGE 2 [Linked Accident Report Documents]	 Load TIF	
5	18/12/19 15:29	POLICE REPORT PAGE 3 [Linked Accident Report Documents]	 Load TIF	
6	18/12/19 15:29	CI [Linked Accident Report Documents]	 Load TIF	
7	18/12/19 15:29	Driving License [Linked Accident Report Documents]	 Load TIF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	24/12/19 11:49	YQ 1085M GIA.pdf	 Load PDF	
2	24/12/19 11:49	POLICE REPORT.pdf	 Load PDF	
3	24/12/19 11:49	ESTIMATE.pdf	 Load PDF	
4	18/02/20 11:32	ESTIMATE & SUPP MARKED.pdf	 Load PDF	
5	04/03/20 11:57	SATISFACTION VOUCHER	 Load PDF	
6	04/03/20 11:57	WORKSHOP INVOICE	 Load PDF	

Linked Accident Report Documents

Assessment Reports			1 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 15:44	Accident Statement	 Load HTM	
Photos/Images			3 per page	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
2	18/12/19 15:32	INSURED LORRY CHASSIS NUMBER	 Load JPG	☒
3	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
4	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
5	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
6	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
7	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
8	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
9	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
10	18/12/19 15:32	INSURED LORRY	 Load JPG	☒
11	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
12	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
13	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
14	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
15	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
16	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
17	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
18	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒

Assessment Reports			1 per page ▼	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
19	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
20	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒
21	18/12/19 15:34	ACCIDENT SCENE	 Load JPG	☒

Documentation			1 per page ▼	☒
No	Finalized On	Car City Auto Centre Pte Ltd (HQ)	Thumbnail	Print
1	18/12/19 15:28	Sketch Plan	 Load TIF	
2	18/12/19 15:28	Sketch Plan #2	 Load TIF	
3	18/12/19 15:29	POLICE REPORT PAGE 1	 Load TIF	
4	18/12/19 15:29	POLICE REPORT PAGE 2	 Load TIF	
5	18/12/19 15:29	POLICE REPORT PAGE 3	 Load TIF	
6	18/12/19 15:29	CI	 Load TIF	
7	18/12/19 15:29	Driving License	 Load TIF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CT119022440/R1SF3S2

Date: 04/03/2020

REFERENCE

Insured/Claimant: ACTINIUM ENGINEERING PTE LTD Policy No: DMCVSN3054161900
Date of Loss: 17/12/2019 Nature of Claim: OD Claim No: SNM19D206047C01

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: YQ1085M
Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M) Engine No: 4P10D74589
Reg. Date: 16/07/2019 (Man. Year: 2019) Chassis No: FEB21EA30197
Colour: White Odometer: 36109 km
Engine Capacity: 2998 cc
Market Value/New Car Price: S\$77,000.00
Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15 Rear Tyre Size: 195/85 R15 (D)
Front Left Side: Dunlop 7 mm Rear Left Side: Dunlop 7/7 mm
Front Right Side: Dunlop 7 mm Rear Right Side: Dunlop 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,774.01	25,988.74	6,785.27	20.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,020.00	8,585.00	2,435.00	22.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,794.01	34,573.74	9,220.27	21.05
- Excess (S\$)	450.00	450.00	0.00	0.00
(S\$)	43,344.01	34,123.74	9,220.27	21.27
+ GST 7.00/7.00% (S\$)	3,034.08	2,388.66	645.42	21.27
Nett Amount (S\$)	46,378.09	36,512.40	9,865.69	21.27

INSPECTION

Date of Assignment: 23/12/2019
Date Inspected: 23/12/2019 Inspected At: Blk K, Pandan Loop Industrial Estate, #01-12
Singapore 128219
Estimated Period of Repair: 12.0 days Repairer: Goldbell Engineering Pte Ltd

Adjuster: MOHD RASUL

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 04 Mar 2020)

Parts: N/A MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for YQ1085M)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS, WINDSHIELD	Cracked	1,131.37 F	*1,131.37 F
2	1		*WEATHERSTRIP, WINDSHIELD	Necessary	486.78 F	*486.78 F
3	1		*GARNISH, FR PANEL	Cracked	373.08 F	*373.08 F
4	1		*PANEL ASSY, FR	Bent	2,367.22 F	*2,367.22 F
5	1		*RAIL ASSY, WINDSHIELD	Bent	1,439.87 F	*1,439.87 F
6	1		*MARK, FUSO	Necessary	150.59 F	*150.59 F
7	1		*MARK, 3-DIA	Necessary	80.22 F	*80.22 F
8	1		*EMBLEM, CANTER	Missing	76.22 F	*76.22 F
9	1		*GRILLE, FRONT	Missing	719.33 F	*719.33 F
10	8		*GRILLE CLIP	Necessary	49.52 F	*49.52 F
11	2		*PAD, RADIATOR GRILLE BRACKET	Necessary	22.30 F	*22.30 F
12	1		*BRKT, RADIATOR GRILLE - CTR	Bent	25.52 F	*25.52 F
13	1		*PANEL, CAB FR CORNER - LH	Cracked	492.41 F	*492.41 F
14	1		*PANEL, CAB FR CORNER - RH	Serviceable	492.41 F	*- F
15	1		*CAP, MIRROR COVER (FLAP)	Missing	28.83 F	*28.83 F
16	1		*COVER, RR VIEW MIRROR STAY (ROUND)	Missing	13.42 F	*13.42 F
17	1		*MIRROR, UNDER VIEW	Cut	55.22 F	*55.22 F
18	1		*BUMPER, FR	Buckled	948.37 F	*948.37 F
19	1		*STAY, FR BUMPER - LH	Bent	190.69 F	*190.69 F
20	1		*STAY, FR BUMPER - RH	Serviceable	190.69 F	*- F
21	1		*BRKT, FR BUMPER, RH	Serviceable	158.92 F	*- F
22	1		*BRKT, FR BUMPER, LH	Bent	158.92 F	*158.92 F
23	1		*COVER, FR BUMPER - LH	Torn	332.06 F	*332.06 F
24	1		*COVER, FR BUMPER - RH	Serviceable	332.06 F	*- F
25	1		*HORN, ELECTRIC HIGH	Cut	144.72 F	*144.72 F
26	1		*COVER, HORN	Bent	32.11 F	*32.11 F
27	1		*PIPE ASSY, HEATER WATER	Bent	71.67 F	*71.67 F
28	1		*C FUSO LLC 4L	Necessary	62.00 F	*62.00 F
29	2		*CLAMP, HEATER WATER (TOP)	Serviceable	14.64 F	*- F
30	1		*AIR INTAKE BOX, HEATER UNIT	Cracked	845.66 F	*845.66 F
31	1		*HEATER UNIT	Cracked	2,384.46 F	*2,384.46 F
32	1		*BRACKET, CAB FR MOUNTING CROSSMEMBER, RH	Bent	800.08 F	*800.08 F
33	1		*C/MBR ASSY, FR.FLOOR (CENTER)	Bent	462.67 F	*462.67 F
34	1		*BRKT, CAB HINGE (LH)	Bent	896.98 F	*896.98 F
35	1		*LEVER, ANCHOR (OUTER MOST) CAP	Bent	243.00 F	*243.00 F
36	1		*BAR, TORSION	Bent	583.15 F	*583.15 F
37	1		*CUSHION, CAB FR (MOUNTING)	Necessary	216.12 F	*216.12 F
38	1		*BUSHING, CAB FR MOUNTING YELLOW	Necessary	17.92 F	*17.92 F
39	1		*CONNECTOR (BRAKE JOINT 3)	Serviceable	206.69 F	*- F
40	1		*PIPE ASSY, BRAKE	Serviceable	240.18 F	*- F
41	1		*HEADLAMP ASSY - LH	Broken	470.69 F	*470.69 F
42	1		*BEZEL, HEADLAMP, LWR	Missing	14.14 F	*14.14 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
43	2		*RIVET, SCREW (BEZEL HEADLAMP)	Necessary	5.10 F	*5.10 F
44	1		*LAMP ASSY, TURN SIGNAL, FR - LH	Broken	197.31 F	*197.31 F
45	1		*GARNISH, HEADLAMP - LH	Broken	216.22 F	*216.22 F
46	1		*HEADLAMP ASSY - RH	Broken	470.69 F	*470.69 F
47	1		*LAMP ASSY, TURN SIGNAL, FR - RH	Serviceable	192.83 F	*- F
48	1		*CROSSMEMBER, CHASSIS FRAME (A)	Bent	1,153.62 F	*1,153.62 F
49	1		*LINK, W/SHLD WIPER	Serviceable	614.32 F	*- F
50	1		*TANK, W/SHLD WASHER	Serviceable	155.74 F	*- F
51	6		*CLIP, INSTRUMENT PANEL UNDER TRIM	Necessary	20.52 F	*20.52 F
52	1		*PILLAR, FR - LH LOWER	Bent	1,315.31 F	*1,315.31 F
53	1		*PANEL ASSY, FR DR 02TD DOM	Buckled	1,944.56 F	*1,944.56 F
54	1		*LATCH, F/DOOR POWER	Serviceable	652.21 F	*- F
55	1		*REGULATOR ASSY, F/DR PWR WD	Serviceable	1,279.57 F	*- F
56	1		*TRIM ASSY, FR DOOR LWR LH	Serviceable	403.25 F	*- F
57	1		*DECAL, BLUETEC	Necessary	41.12 F	*41.12 F
58	1		*SCUFF PLATE, FR LH	Cracked	101.46 F	*101.46 F
59	1		*FENDER, SIDE, FR UPR - LH (DOOR)	Deformed	64.93 F	*64.93 F
60	1		*HOSE, A/C PIPING, NO.2	Bent	474.84 F	*474.84 F
61	1		*HOSE, A/C PIPING, NO.3 (SMALL)	Bent	444.43 F	*444.43 F
62	1		*CONDENSER A/C REFRIGERANT	Bent	650.00 F	*650.00 F
63	1		*REAR BRACKET, A/C CONDENSER	Bent	805.52 F	*805.52 F
64	1		*MOTOR, A/C CONDENSER FAN	Shorted	433.28 F	*433.28 F
65	1		*RECEIVER ASSY	Serviceable	288.15 F	*- F
66	2		*FRONT BRACKET, A/C CONDENSER X	Bent	71.68 F	*71.68 F
67	1		*FENDER, FR FLOOR SIDE - LH (TOP OF AC CONDENSER)	Bent	304.96 F	*304.96 F
68	1		*STEP, FR SIDE - LH (BLACK)	Broken	285.00 F	*285.00 F
69	1		*GARNISH, AIR OUTLET	Serviceable	47.23 F	*- F
70	1		*RESERVOIR, P/S OIL	Serviceable	541.44 F	*- F
71	1		*TANK, RADIATOR SURGE	Serviceable	176.31 F	*- F
72	1		*BRKT, W/WPR MOTOR	Serviceable	110.33 F	*- F
73	1		*MOTOR, W/SHLD WIPER	Serviceable	643.30 F	*- F
74	1		*IU BRACKET	Necessary	20.00 FS	*20.00 FS
75	1		*NUMBER PLATE	Bent	25.00 FS	*25.00 FS
76	1		*BRAKE FLUID	Not Necessary	45.00 FS	*- FS
77	1		*STEP FENDER, FR FLOOR SIDE - LH	Bent	328.61 F	*328.61 F
78	1		*PANEL, SHIELD FR 04TD EXP W	Bent	227.27 F	*227.27 F

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	32,774.01	25,988.74
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	New	4,800.00	4,200.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK.	New	200.00	180.00
3	TO PUTTY, CLEAN SPRAY PAINT AND POLISH, ETC.	New	2,100.00	1,575.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR.	New	200.00	180.00
5	TO TRANSFER / REMOVE / INSTALL DOOR LOCK MECHANISM, WINDOW REGULATOR, WINDOW GLASS, DOOR TRIM TO NEW DOOR UNIT.	New	300.00	250.00
6	TO REMOVE AND REFIX FRONT DASHBOARD.	New	700.00	600.00
7	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION.	New	700.00	600.00
8	TOP UP AIRCON GAS.	New	120.00	100.00
9	TO REMOVE, REFIX AND REALIGN FRONT CABIN.	New	600.00	450.00
10	TO REMOVE & REFIX POWER STEERING TANK ASSY / COOLANT SPARE TANK / BRAKE SYSTEM, TO CHECK FUNCTION.	New	700.00	0.00
11	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	New	600.00	450.00
Gross Labour Cost (S\$)			11,020.00	8,585.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >