

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road, #16-00 Springleaf Tower
Singapore 079909

Our File No: CS/CTI19022440/R1SF3S2**Date:** 04/03/2020**REFERENCE**

Insured/Claimant: ACTINIUM ENGINEERING PTE LTD Policy No: DMCVSN3054161900

Date of Loss: 17/12/2019

Nature of Claim: OD

Claim No: SNM19D206047C01

DESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **YQ1085M**

Make & Model: MITSUBISHI CANTER, 3.0 D FEB21 (M)

Engine No: 4P10D74589

Reg. Date: 16/07/2019 (Man. Year: 2019)

Chassis No: FEB21EA30197

Colour: White

Odometer: 36109 km

Engine Capacity: 2998 cc

Market Value/New Car Price: S\$77,000.00

Sum Insured (S\$): **Market Value/New Car Price****CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition: Fair Steering (Serviceable):

Yes Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/85 R15

Rear Tyre Size: 195/85 R15 (D)

Front Left Side: Dunlop 7 mm

Rear Left Side: Dunlop 7/7 mm

Front Right Side: Dunlop 7 mm

Rear Right Side: Dunlop 7/7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	32,774.01	25,988.74	6,785.27	20.70
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,020.00	8,585.00	2,435.00	22.10
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	43,794.01	34,573.74	9,220.27	21.05
- Excess (S\$)	450.00	450.00	0.00	0.00
(S\$)	43,344.01	34,123.74	9,220.27	21.27
+ GST 7.00/7.00% (S\$)	3,034.08	2,388.66	645.42	21.27
Nett Amount (S\$)	46,378.09	36,512.40	9,865.69	21.27

INSPECTION

Date of Assignment: 23/12/2019

Date Inspected: 23/12/2019 Inspected At:

8 Tuas Ave 18 SINGAPORE 638892

Repairer: Goldbell Engineering Pte Ltd

Estimated Period of Repair: 12.0 days

Adjuster: MOHD RASUL**Manager:** Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 04 Mar 2020)	
Parts:	N/A	MITSUBISHI CANTER 3.0 D FEB21 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for YQ1085M)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*GLASS, WINDSHIELD	Cracked	1,131.37 F	*1,131.37 F
2	1		*WEATHERSTRIP, WINDSHIELD	Necessary	486.78 F	*486.78 F
3	1		*GARNISH, FR PANEL	Cracked	373.08 F	*373.08 F
4	1		*PANEL ASSY, FR	Bent	2,367.22 F	*2,367.22 F
5	1		*RAIL ASSY, WINDSHIELD	Bent	1,439.87 F	*1,439.87 F
6	1		*MARK, FUSO	Necessary	150.59 F	*150.59 F
7	1		*MARK, 3-DIA	Necessary	80.22 F	*80.22 F
8	1		*EMBLEM, CANTER	Missing	76.22 F	*76.22 F
9	1		*GRILLE, FRONT	Missing	719.33 F	*719.33 F
10	8		*GRILLE CLIP	Necessary	49.52 F	*49.52 F
11	2		*PAD, RADIATOR GRILLE BRACKET	Necessary	22.30 F	*22.30 F
12	1		*BRKT, RADIATOR GRILLE - CTR	Bent	25.52 F	*25.52 F
13	1		*PANEL, CAB FR CORNER - LH	Cracked	492.41 F	*492.41 F
14	1		*PANEL, CAB FR CORNER - RH	Serviceable	492.41 F	*- F
15	1		*CAP, MIRROR COVER (FLAP)	Missing	28.83 F	*28.83 F
16	1		*COVER, RR VIEW MIRROR STAY (ROUND)	Missing	13.42 F	*13.42 F
17	1		*MIRROR, UNDER VIEW	Cut	55.22 F	*55.22 F
18	1		*BUMPER, FR	Buckled	948.37 F	*948.37 F
19	1		*STAY, FR BUMPER - LH	Bent	190.69 F	*190.69 F
20	1		*STAY, FR BUMPER - RH	Serviceable	190.69 F	*- F
21	1		*BRKT, FR BUMPER, RH	Serviceable	158.92 F	*- F
22	1		*BRKT, FR BUMPER, LH	Bent	158.92 F	*158.92 F
23	1		*COVER, FR BUMPER - LH	Torn	332.06 F	*332.06 F
24	1		*COVER, FR BUMPER - RH	Serviceable	332.06 F	*- F
25	1		*HORN, ELECTRIC HIGH	Cut	144.72 F	*144.72 F
26	1		*COVER, HORN	Bent	32.11 F	*32.11 F
27	1		*PIPE ASSY, HEATER WATER	Bent	71.67 F	*71.67 F
28	1		*C FUSO LLC 4L	Necessary	62.00 F	*62.00 F
29	2		*CLAMP, HEATER WATER (TOP)	Serviceable	14.64 F	*- F
30	1		*AIR INTAKE BOX, HEATER UNIT	Cracked	845.66 F	*845.66 F
31	1		*HEATER UNIT	Cracked	2,384.46 F	*2,384.46 F
32	1		*BRACKET, CAB FR MOUNTING CROSSMEMBER, RH	Bent	800.08 F	*800.08 F
33	1		*C/MBR ASSY, FR.FLOOR (CENTER)	Bent	462.67 F	*462.67 F
34	1		*BRKT, CAB HINGE (LH)	Bent	896.98 F	*896.98 F
35	1		*LEVER, ANCHOR (OUTER MOST) CAP	Bent	243.00 F	*243.00 F
36	1		*BAR, TORSION	Bent	583.15 F	*583.15 F
37	1		*CUSHION, CAB FR (MOUNTING)	Necessary	216.12 F	*216.12 F
38	1		*BUSHING, CAB FR MOUNTING YELLOW	Necessary	17.92 F	*17.92 F
39	1		*CONNECTOR (BRAKE JOINT 3)	Serviceable	206.69 F	*- F
40	1		*PIPE ASSY, BRAKE	Serviceable	240.18 F	*- F
41	1		*HEADLAMP ASSY - LH	Broken	470.69 F	*470.69 F
42	1		*BEZEL, HEADLAMP, LWR	Missing	14.14 F	*14.14 F
43	2		*RIVET, SCREW (BEZEL HEADLAMP)	Necessary	5.10 F	*5.10 F
44	1		*LAMP ASSY, TURN SIGNAL, FR - LH	Broken	197.31 F	*197.31 F
45	1		*GARNISH, HEADLAMP - LH	Broken	216.22 F	*216.22 F
46	1		*HEADLAMP ASSY - RH	Broken	470.69 F	*470.69 F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
47	1		*LAMP ASSY, TURN SIGNAL, FR - RH	Serviceable	192.83 F	*- F
48	1		*CROSSMEMBER, CHASSIS FRAME (A)	Bent	1,153.62 F	*1,153.62 F
49	1		*LINK, W/SHLD WIPER	Serviceable	614.32 F	*- F
50	1		*TANK, W/SHLD WASHER	Serviceable	155.74 F	*- F
51	6		*CLIP, INSTRUMENT PANEL UNDER TRIM	Necessary	20.52 F	*20.52 F
52	1		*PILLAR, FR - LH LOWER	Bent	1,315.31 F	*1,315.31 F
53	1		*PANEL ASSY, FR DR 02TD DOM	Buckled	1,944.56 F	*1,944.56 F
54	1		*LATCH,F/DOOR POWER	Serviceable	652.21 F	*- F
55	1		*REGULATOR ASSY, F/DR PWR WD	Serviceable	1,279.57 F	*- F
56	1		*TRIM ASSY, FR DOOR LWR LH	Serviceable	403.25 F	*- F
57	1		*DECAL, BLUETEC	Necessary	41.12 F	*41.12 F
58	1		*SCUFF PLATE, FR LH	Cracked	101.46 F	*101.46 F
59	1		*FENDER, SIDE, FR UPR - LH (DOOR)	Deformed	64.93 F	*64.93 F
60	1		*HOSE, A/C PIPING, NO.2	Bent	474.84 F	*474.84 F
61	1		*HOSE, A/C PIPING, NO.3 (SMALL)	Bent	444.43 F	*444.43 F
62	1		*CONDENSER A/C REFRIGERANT	Bent	650.00 F	*650.00 F
63	1		*REAR BRACKET, A/C CONDENSER	Bent	805.52 F	*805.52 F
64	1		*MOTOR, A/C CONDENSER FAN	Shorted	433.28 F	*433.28 F
65	1		*RECEIVER ASSY	Serviceable	288.15 F	*- F
66	2		*FRONT BRACKET, A/C CONDENSER X	Bent	71.68 F	*71.68 F
67	1		*FENDER, FR FLOOR SIDE - LH (TOP OF AC CONDENSER)	Bent	304.96 F	*304.96 F
68	1		*STEP, FR SIDE - LH (BLACK)	Broken	285.00 F	*285.00 F
69	1		*GARNISH, AIR OUTLET	Serviceable	47.23 F	*- F
70	1		*RESERVOIR, P/S OIL	Serviceable	541.44 F	*- F
71	1		*TANK, RADIATOR SURGE	Serviceable	176.31 F	*- F
72	1		*BRKT, W/WPR MOTOR	Serviceable	110.33 F	*- F
73	1		*MOTOR, W/SHLD WIPER	Serviceable	643.30 F	*- F
74	1		*IU BRACKET	Necessary	20.00 FS	*20.00 FS
75	1		*NUMBER PLATE	Bent	25.00 FS	*25.00 FS
76	1		*BRAKE FLUID	Not Necessary	45.00 FS	*- FS
77	1		*STEP FENDER, FR FLOOR SIDE - LH	Bent	328.61 F	*328.61 F
78	1		*PANEL, SHIELD FR 04TD EXP W	Bent	227.27 F	*227.27 F

F=Franchise part. S=SpcNett.

Total Parts (S\$) 32,774.01 25,988.74

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	New	4,800.00	4,200.00
2	TO CHECK FOR AND RECTIFY WIRING FAULTS, TO CONDUCT DIAGNOSTICS CHECK.	New	200.00	180.00
3	TO PUTTY, CLEAN SPRAY PAINT AND POLISH, ETC.	New	2,100.00	1,575.00
4	TO REMOVE AND REFIX FRONT WINDSCREEN TO ASSIST REPAIR.	New	200.00	180.00
5	TO TRANSFER / REMOVE / INSTALL DOOR LOCK MECHANISM, WINDOW REGULATOR, WINDOW GLASS, DOOR TRIM TO NEW DOOR UNIT.	New	300.00	250.00
6	TO REMOVE AND REFIX FRONT DASHBOARD.	New	700.00	600.00
7	TO REMOVE AND REFIX AIRCON SYSTEM. TO CHECK FUNCTION.	New	700.00	600.00
8	TOP UP AIRCON GAS.	New	120.00	100.00
9	TO REMOVE, REFIX AND REALIGN FRONT CABIN.	New	600.00	450.00
10	TO REMOVE & REFIX POWER STEERING TANK ASSY / COOLANT SPARE TANK / BRAKE SYSTEM, TO CHECK FUNCTION.	New	700.00	0.00
11	TO REMOVE AND REFIX DAMAGED PARTS, CUT, WELD, PANEL BEAT, STRAIGHTEN & REALIGN, ETC.	New	600.00	450.00
Gross Labour Cost (\$)			11,020.00	8,585.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >