LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd. From: LKK Auto Consultants Pte Ltd

3 Anson Road

51 Ubi Ave 1 #01-25 #16-00 Springleaf Tower Paya Ubi Industrial Park Singapore 079909 Singapore 408933

Attn: Irene Tay Hui Ping Date: 18 Feb 2020

Preliminary Advice

Vehicle No : YQ1085M **Accident Date** : 17/12/2019

Make : MITSUBISHI CANTER Policy No. : DMCVSN3054161900

: 23/12/2019 **Excess** : S\$450.00 **Assignment Date** Date of Inspection Est. Duration of Repair : 23/12/2019 : 12 days

Inspection At : Goldbell Engineering Pte Ltd (Pandan)

Blk K, Pandan Loop Industrial Estate, #01-12

Singapore 128219

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	43,794.01 (inclusive supp)
Revised Amount	:S\$	34,573.74 (inclusive supp)
Check Items (Estimated)	:S\$	0.00

Total :S\$ 34,573.74

Lump Sum Repair :S\$

Total Loss Consideration

New for Old Value :S\$

Pre-Accident Value :S\$ 77,000.00 COE / PARF Rebate 22,137.00 :S\$

Salvage Value :S\$

Margin for Repair :S\$ 54,863.00

Remarks

(X)	The vehicle is repairable at our adjusted amoun	ા. We have also confirmed	l excess and policy coverage.
	Kindly let us have your authorisation.		

- The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- Other comments: Supplementary amount is \$ 1,005.88. (X)