

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Irene Tay Hui Ping

Date: 24 Dec 2019

Preliminary Advice

Vehicle No	: YQ1085M	Accident Date	: 17/12/2019
Make	: MITSUBISHI CANTER	Policy No.	: DMCVSN3054161900
Assignment Date	: 23/12/2019	Excess	: S\$450.00
Date of Inspection	: 23/12/2019	Est. Duration of Repair	: 12 days
Inspection At	: GOLDBELL ENGINEERING PTE LTD 8 TUAS AVE 18 SINGAPORE 638892		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	42,638.13
Revised Amount	:S\$	27,481.62
Check Items (Estimated)	:S\$	11,406.94
Total	:S\$	38,888.56

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	77,000.00
COE / PARF Rebate	:S\$	22,137.00
Salvage Value	:S\$	
Margin for Repair	:S\$	54,863.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- () Other comments :