

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG19022444/ADS3Q2

Date: 25/06/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100462911-02

Claimant
Vehicle No : SLH9079E **Insured Vehicle No :** SLC242K

Date of Loss: 28/11/2019 Nature of Claim: TP Claim No: 0795440189SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLH9079E		
Make & Model:	MERCEDES-BENZ E200 (R17), 2.0 (A)	Engine No:	27186030325151
Reg. Date:	09/01/2012 (Man. Year: 2011)	Chassis No:	WDD2120482A519753
Colour:	Blue	Odometer:	72251 km
Engine Capacity:	1796 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	265/35 R18	Rear Tyre Size:	265/35 R18
Front Left Side:	Goodyear 6 mm	Rear Left Side:	Goodyear 6 mm
Front Right Side:	Goodyear 6 mm	Rear Right Side:	Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,804.40	5,377.50	6,426.90	54.44
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,840.00	1,620.00	1,220.00	42.96
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	14,644.40	6,997.50	7,646.90	52.22
Approved Total (Overridden) (\$\$)		5,600.00		
Nett Amount (\$\$)	14,644.40	5,600.00	9,044.40	61.76
+ Car Rental (7.0 x S\$140.00/day) (\$\$)		980.00		
+ Doc/Search Fee (\$\$)		7.45		
Nett Liability (\$\$)		6,587.45		

INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 17/12/2019 Inspected At: Zero Gravity (Kaki Bukit)
2 Kaki Bukit Ave 2, #01-25 Kaki Bukit
Autohub
Singapore 417921

Estimated Period of Repair: 5.0 days

Adjuster: ADRIAN LING

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	1,640.00 FL	*1,314.00 FL
2	1		*REAR BUMPER LIP	Deformed	520.00 FL	*325.00 FL
3	2		*REAR BUMPER LIP BRACKET	Not Necessary	54.00 FL	*- FL
4	1		*SET BUMPER BEAM SCREW /INNER CLIPS	Necessary	120.00 FL	*30.00 FL
5	1		*BUMPER CAP	Not Necessary	62.00 FL	*- FL
6	1		*REAR BUMPER CHROME MOULDING (CENTER)	Necessary	182.00 FL	*182.00 FL
7	2		*REAR BUMPER CHROME MOULDING (SIDE)	Necessary	276.00 FL	*276.00 FL
8	1		*BUMPER BRACKET (L/H)	Cracked	73.00 FL	*73.00 FL
9	1		*BUMPER BRACKET (R/H)	Not Necessary	73.00 FL	*- FL
10	1		*REAR BUMPER TOP RETAINER	Cracked	48.00 FL	*48.00 FL
11	1		*BUMPER REINFORCEMENT	Bent	413.00 FL	*413.00 FL
12	2		*GARNISH (EXHAUST)	Not Necessary	272.00 FL	*- FL
13	1		*EXHAUST TAIL PIPE	Not Necessary	320.00 FL	*- FL
14	1		*REAR END PANEL	Repair	1,300.00 FL	*- FL
15	1		*REAR END PANEL GARNISH	Not Necessary	150.00 FL	*- FL
16	1		*REAR BOOT	Buckled	3,100.00 FL	*1,753.00 FL
17	1		*REAR BOOT CHROME STRIP	Not Necessary	135.00 FL	*- FL
18	1		*REAR BOOT OUTER HANDLE	Not Necessary	265.00 FL	*- FL
19	1		*REAR BOOT INNER TRIM BOARD	Not Necessary	325.00 FL	*- FL
20	8		*REAR BOOT INNER TRIM BOARD CLIPS	Not Necessary	64.00 FL	*- FL
21	1		*REAR BOOT WEATHERSTRIP	Not Necessary	185.00 FL	*- FL
22	1		*REAR BOOT INNER LOCK	Damaged	1,175.00 FL	*295.00 FL
23	1		*LOGO	Necessary	57.00 FL	*57.00 FL
24	1		*EMBLEM C&C	Necessary	90.00 FL	*90.00 FL
25	1		*EMBLEM E200	Necessary	86.00 FL	*86.00 FL
26	1		*EMBLEM 7G TRONIC	Necessary	95.00 FL	*95.00 FL
27	1		*LAMP (L/H/R)	Cracked	725.00 FL	*652.00 FL
28	1		*LAMP (REAR) (BOOT L/H)	Not Necessary	525.00 FL	*- FL
29	1		*REVERSE SENSOR	Damaged	286.00 FL	*286.00 FL
30	1		*REVERSE CAMERA	Not Necessary	450.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	13,066.00	5,975.00
- List Item Discount on L Items 10.00/10.00% (\$)	1,261.60	597.50
Total Parts (\$)	11,804.40	5,377.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEAT & REPAIR REAR DAMAGE	New	1,000.00	600.00
2	TO PUTTY AND RESPRAY AFFECTED PORTION	New	900.00	700.00
3	TO PROVIDE UNDER TURFCOAT	New	180.00	50.00
4	TO TRANSFER REAR BOOT FITTING	New	180.00	80.00
5	TO CHECK WIRIG SYSTEM & ENSURE FUNCTION OF COMPONENT	New	80.00	30.00
6	TO REMOVE REVERSE SENSOR /CAMERA	New	250.00	100.00
7	TO REMOVE AND REFIT COMPONENTS /FACILITATE REPAIR	New	250.00	60.00
Gross Labour Cost (\$\$)			2,840.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >