

## LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

**Our File No:** CC4/AIG19022447/QBS3Q2

**Date:** 03/11/2020

### REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100505046

**Claimant**  
**Vehicle No :** SLN8931U **Insured Vehicle No :** SLM3385J

Date of Loss: 14/12/2019 Nature of Claim: TP Claim No: 0556161612SG

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLN8931U		
Make & Model:	TOYOTA PRIUS, 1.5 HYBRID (A)	Engine No:	2ZRS049244
Reg. Date:	22/05/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FUX03559052
Colour:	Silver	Odometer:	151784 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Firenza 5 mm	Rear Left Side:	Firenza 5 mm
Front Right Side:	Firenza 5 mm	Rear Right Side:	Firenza 5 mm

*The above values represent the remaining tyre treads depth*

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,122.60	4,145.52	977.08	19.07
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,900.00	1,300.00	40.63
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>8,322.60</b>	<b>6,045.52</b>	<b>2,277.08</b>	<b>27.36</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>4,800.00</b>		
<b>(\$\$)</b>	8,322.60	4,800.00	3,522.60	42.33
<b>+ GST 7.00/7.00% (\$\$)</b>	582.58	336.00	246.58	42.33
<b>Nett Amount (\$\$)</b>	<b>8,905.18</b>	<b>5,136.00</b>	<b>3,769.18</b>	<b>42.33</b>
<b>+ Loss of Use (8.0 x S\$80.00/day) (\$\$)</b>		640.00		
<b>+ Doc/Search Fee (\$\$)</b>		2.00		
<b>Nett Liability (\$\$)</b>		<b>5,778.00</b>		
<b>Global Sum Settlement (\$\$)</b>		<b>5,600.00</b>		

### INSPECTION

Date of Assignment: 17/12/2019

Date Inspected: 17/12/2019 Inspected At:

Lion City Rentals Pte Ltd  
1090 LOWER DELTA ROAD #05-12  
Singapore 169201

Estimated Period of Repair: 6.0 days

---

**Adjuster:** OI SUN PIN**Manager:** CHUA ZHEN LI

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BACK DOOR	Dented	922.50 FL	*922.50 FL
2	1		*REAR BACK DOOR CENTRE GARNISH COVER	Cracked	850.00 FL	*850.00 FL
3	1		*REAR BACK DOOR TOYOTA EMBLEM	Necessary	45.80 FL	*45.80 FL
4	1		*REAR BACK DOOR HYBRID EMBLEM	Necessary	52.30 FL	*52.30 FL
5	1		*REAR BACK DOOR PIRUS EMBLEM	Necessary	45.80 FL	*45.80 FL
6	1		*REAR BACK DOOR LOCK	Jammed	447.40 FL	*447.40 FL
7	1		*REAR BACK DOOR LOCK CATCH	Serviceable	24.60 FL	*- FL
8	1		*REAR BACK DOOR WEATHERSTRIP	Crumpled	356.80 FL	*356.80 FL
9	1		*REAR BUMPER	Crumpled	423.90 FL	*423.90 FL
10	1		*REAR BUMPER CENTER PAD	Necessary	552.30 FL	*552.30 FL
11	1		*REAR BUMPER LH RETAINER	Broken	112.70 FL	*112.70 FL
12	1		*REAR BUMPER REINFORCEMENT	Bent	318.80 FL	*318.80 FL
13	1		*REAR BUMPER UNDERSIDE LH COVER	Serviceable	133.60 FL	*- FL
14	1		*REAR BUMPER LOWER COVER	Serviceable	303.90 FL	*- FL
15	1		*REAR BUMPER LH SIDE EXTENSION FILLER	Cut	148.40 FL	*148.40 FL
16	1		*REAR BUMPER RH TOW COVER	Serviceable	35.90 FL	*- FL
17	1		*REAR END PANEL	Dented	356.80 FL	*356.80 FL
18	1		*REAR END PANEL TOP GARNISH	Deformed	105.30 FL	*105.30 FL
19	1		*R/L COMBINATION LAMP	Serviceable	433.70 FL	*- FL
20	1		*R/L LAMP LEN AND BODY	Cracked	481.90 FL	*481.90 FL
21	1		*R/L FENDER AIR VENT	Serviceable	64.40 FL	*- FL
22	1		*SET BUMPER AND END PANEL CLIPS	Necessary	200.00 FS	*30.00 FS
23	1		*SET REVERSE SENSOR	Shorted	260.00 FS	*200.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>6,676.80</b>	<b>5,450.70</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	1,554.20	1,305.18
<b>Total Parts (\$\$)</b>	<b>5,122.60</b>	<b>4,145.52</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Labour Items</u></b>				
1	TO LABOUR CHARGE FOR REMOVING REAR BACK DOOR ,REAR END PANEL ,SPARE TYRE PANEL ,REAR BUMPER AND REAR BUMPER REINFORCEMENT OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,200.00	900.00
2	TO RESPRAY REAR BUMPER ,REAR BACK DOOR ,CENTER GARNISH ,REAR BUMPER ,END PANEL ,SPARE TYRE PANEL ,R/L SIDE FILLER	New	1,200.00	600.00
3	TRANSFER DOOR MECHANISM TO FACILITATE REPAIRS AND REPLACEMENT OF PARTS ,REMOVE WINDSCREEN	New	200.00	200.00
4	TO CONDUCT STANDARD OF OPEARTING PROCEDURES POST SCAN TEST AS AREQUIREMENTS FOR HYBRID CARS UPON COMPLETION OF COLLISION REPAIRS }	New	300.00	200.00
5	TO DEACTIVATE AND ACTIVATE HIGH VOLTAGE HYBRID BATTERY AS A REQUIREMENT FOR SAFETY PRECAUTIONS }	New	300.00	0.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,200.00</b>	<b>1,900.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >