

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022449/GBA3Q2

Date: 10/04/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No:

Claimant Vehicle No : GBB2141D

Insured Vehicle No : SFX8778P

Date of Loss: 14/12/2019

Nature of Claim: TP Claim No: 3876026157SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: GBB2141D

Make & Model: TOYOTA HIACE, 3.0 D DX (M)

Engine No: 1KD1817316

Reg. Date: 29/09/2008 (Man. Year: 2008)

Chassis No: KDH2010023495

Colour: Silver

Odometer: 525426 km

Engine Capacity: 2982 cc

Market Value/New Car Price: N/A

Sum Insured (\$\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195 R15

Rear Tyre Size: 195 R15

Front Left Side: VANMAX 6 mm

Rear Left Side: VANMAX 6 mm

Front Right Side: VANMAX 6 mm

Rear Right Side: VANMAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	8,907.10	1,437.81	7,469.29	83.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,360.00	650.00	1,710.00	72.46
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	11,267.10	2,087.81	9,179.29	81.47
Approved Total (Overridden) (\$\$)		1,650.00		
(\$\$)	11,267.10	1,650.00	9,617.10	85.36
+ GST 7.00/7.00% (\$\$)	788.70	115.50	673.20	85.36
Nett Amount (\$\$)	12,055.80	1,765.50	10,290.30	85.36
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 19/12/2019 Inspected At:

 Bodyfix (HQ)
 10 Ang Mo Kio Industrial Park 2, #04-06, AMK
 Autopoint
 Singapore 568047

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT DOOR (RH)	Buckled	1,811.90 F	*950.50 FL
2	2		*FRONT DOOR HINGES	Bent (1 PCS ONLY)	185.20 F	*92.60 FL
3	1		*FRONT DOOR GLASS (RH)	Not Necessary	360.00 F	*- FL
4	1		*DOOR GLASS MOULDING FRONT	Not Necessary	165.00 F	*- FL
5	1		*POWER WINDOW MOTOR (FRONT RH)	Not Necessary	1,281.60 F	*- FL
6	1		*POWER WINDOW REGULATOR FRONT RH	Not Necessary	345.00 F	*- FL
7	1		*FRONT DOOR OUTER HANDLE (RH)	Not Necessary	145.00 F	*- FL
8	1		*SIDE MIRROR (RH)	Not Necessary	750.00 F	*- FL
9	1		*HEAD LAMP (RH)	Cut	2,539.10 F	*422.78 FL
10	1		*FRONT BUMPER	Cut	468.70 F	*391.20 FL
11	10		*FRONT BUMPER CLIPS	Necessary	57.00 F	*40.00 FL
12	2		*FRONT BUMPER SIDE RETAINER	Not Necessary	273.60 F	*- FL
13	1		*FRONT BUMPER LOWER GRILLE	Not Necessary	156.30 F	*- FL
14	1		*FRONT CORNER PANEL (RH)	Not Necessary	268.70 F	*- FL
15	1		*RH-FRT DOOR STICKER	Cut	100.00 FS	*15.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	8,907.10	1,912.08
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	474.27
Total Parts (\$\$)	8,907.10	1,437.81

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	RUST-PROOFING ON THE ACCIDENT AFFECTED PORTIONS	New	60.00	0.00
2	LABOUR TO REPLACE ABOVE PARTS PANEL BEAT ,REPAIR & REALIGN DAMAGE PARTS	New	1,200.00	400.00
3	SPRAY PAINT RH FRONT DOOR ,FRONT BUMPER ,RH CORNER PANEL & OTHER AFFECTED AREAS	New	1,100.00	250.00
Gross Labour Cost (S\$)			2,360.00	650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >