Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022451/QES3Q2

Date: 03/08/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant SLK5863T Insured Vehicle No: SDR988H

Vehicle No: SLK38031 Insured vehicle No: SDK388H

Date of Loss: 12/12/2019 Nature of Claim: TP Claim No: 0669562954SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLK5863T

 Make & Model:
 HONDA VEZEL, 1.5 HYBRID (A)
 Engine No:
 LEB5915830

 Reg. Date:
 20/01/2017 (Man. Year: 2016)
 Chassis No:
 RU31215821

 Colour:
 Blue
 Odometer:
 148732 km

Engine Capacity: 1496 cc Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R16 Rear Tyre Size: 215/60 R16
Front Left Side: Rovelo 5 mm Rear Left Side: Rovelo 5 mm
Front Right Side: Rovelo 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,692.00	690.00	6,002.00	89.69
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,250.00	450.00	1,800.00	80.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	8,942.00	1,140.00	7,802.00	87.25
Approved Total (Overridden) (S\$)		900.00		
(S\$)	8,942.00	900.00	8,042.00	89.94
+ GST 7.00/7.00% (S\$)	625.94	63.00	562.94	89.94
Nett Amount (S\$)	9,567.94	963.00	8,604.94	89.94
+ Loss of Use (3.0 x S\$60.00/day) (S\$) + Doc/Search Fee (S\$)		180.00		_
		2.00		
Net	t Liability (S\$)	1,145.00		

INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 20/12/2019 Inspected At: 60 JALAN LAM HUAT# 04-35/36

CARROS CENTRE, 737869

SINGAPORE.

Repairer:Lion City Rentals Pte Ltd

Estimated Period of Repair: 2.0 days

Adjuster Report Page 2 of 4

Adjuster: OI SUN PIN Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*F/L HEADLAMP	Serviceable	2,100.00 FL	*- FL
2	1		*F/L HEADLAMP TOP BRACKET	Serviceable	210.00 FL	*- FL
3	1		*F/L HEADLAMP LOWER BRACKET	Serviceable	210.00 FL	*- FL
4	1		*F/R HEADLAMP	Serviceable	2,100.00 FL	*- FL
5	1		*F/R HEADLAMP TOP BRACKET	Serviceable	210.00 FL	*- FL
6	1		*F/R HEADLAMP LOWER BRACKET	Serviceable	Serviceable 210.00 FL	
7	1		*FRONT BUMPER	Dented	955.00 FL	*825.00 FL
8	1		*FRONT BUMPER REINFORCEMENT	Serviceable	680.00 FL	*- FL
9	1		*FRONT COMPLETE RADIATOR GRILLE ASSY	Serviceable	1,590.00 FL	*- FL
10	1		*SET FRONT BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
F=Fra	nchise	part. S=Spcl	Nett. L=ListItemDisc List Item Discount on L Items 2	Sub Total (S\$)	8,345.00 1,653.00	855.00 165.00
			1,055.00	105.00		
				Total Parts (S\$)	6,692.00	690.00
			Report was unsubmitted during this	print-out.		

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount		
Lab	our Items					
1	TO CHECK WIRIGN SYSTEM	New	100.00	0.00		
2	TO RESPRAY FRONT BUMPER ,SUPPORT PANEL AND FRONT BONNET	New	900.00	200.00		
3	TO LABOUR CHARGE FOR REMOVING FRONT BUMPER AND SUPPORT PANEL OUT TO FACILITATE REPAIRS AND REPLACEMENT OF DAMAGED PARTS	New	1,250.00	250.00		
	Gross Labour Cost (S\$)		2,250.00	450.00		
	Report was unsubmitted during this print-out.					

< END OF ESTIMATES >