

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG19022453/AEA3Q2

Date: 17/04/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No:

Claimant
Vehicle No : GBJ2273P **Insured Vehicle No :** SLN6862Z

Date of Loss: 16/12/2019 **Nature of Claim:** TP **Claim No:** 4938848399SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBJ2273P		
Make & Model:	TOYOTA HIACE, 3.0 D (M)	Engine No:	1GD8343262
Reg. Date:	14/02/2019 (Man. Year: 2018)	Chassis No:	GDH2012003331
Colour:	White	Odometer:	34001 km
Engine Capacity:	2754 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/80 R15	Rear Tyre Size:	195/80 R15
Front Left Side:	Dunlop 6 mm	Rear Left Side:	Dunlop 6 mm
Front Right Side:	Dunlop 6 mm	Rear Right Side:	Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,998.75	4,665.25	9,333.50	66.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	4,850.00	1,990.00	2,860.00	58.97
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,848.75	6,655.25	12,193.50	64.69
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	18,848.75	5,300.00	13,548.75	71.88
+ GST 7.00/7.00% (S\$)	1,319.41	371.00	948.41	71.88
Nett Amount (S\$)	20,168.16	5,671.00	14,497.16	71.88
+ Loss of Use (6.0 x S\$90.00/day) (S\$)		540.00		
+ Doc/Search Fee (S\$)		36.45		
Nett Liability (S\$)		6,247.45		
Global Sum Settlement (S\$)		6,240.00		

INSPECTION

Date of Assignment: 18/12/2019

Date Inspected: 23/12/2019 Inspected At:

Vision Autowork Pte Ltd (HQ)
8 KAKI BUKIT AVE 4,, #08-09
PREMIER @ KAKI BUKIT
Singapore 415875

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*TAILGATE	Dented	2,054.00 FL	*2,054.00 FL
2	2		*TAILGATE STOPPER	Not Necessary	50.00 FL	*- FL
3	2		*TAILGATE DAMPER	Not Necessary	116.00 FL	*- FL
4	1		*TAILGATE OUTER MOULDING	Not Necessary	464.00 FL	*- FL
5	1		*TAILGATE LOGO	Necessary	80.00 FL	*80.00 FL
6	1		*TAILGATE LOCK MOTOR	Not Necessary	545.00 FL	*- FL
7	1		*TAILGATE WEATHERSTRIP	Cut	410.00 FL	*283.00 FL
8	1		*TAILGATE WEATHERSTRIP PROTECTOR	Bent	485.00 FL	*263.00 FL
9	1		*TAILGATE INNER LOCK	Damaged	285.00 FL	*285.00 FL
10	1		*TAILGATE LOWER LOCK	Not Necessary	45.00 FL	*- FL
11	1		*TAILGATE INNER TRIM	Not Necessary	286.00 FL	*- FL
12	2		*TAIL LAMP	Cut (RH Only)	760.00 FL	*380.00 FL
13	2		*TAILLAMP LOWER GARNISH	Repair	372.00 FL	*- FL
14	2		*TAILLAMP LOWER GARNISH RETAINER	Not Necessary	130.00 FL	*- FL
15	1		*REAR BUMPER	Deformed	479.00 FL	*479.00 FL
16	1		*REAR STEP PANEL	Bent	386.00 FL	*386.00 FL
17	2		*REAR BUMPER SIDE RETAINER	Necessary	110.00 FL	*110.00 FL
18	1		*REAR END PANEL (INNER)	Repair	871.00 FL	*- FL
19	1		*REAR END PANEL (OUTER)	Dented	647.00 FL	*647.00 FL
20	1		*REAR FLOOR PANEL	Not Necessary	1,960.00 FL	*- FL
21	1		*REAR FLOOR MATT	Not Necessary	1,050.00 FL	*- FL
22	1		*REAR SPARE TYRE HOLDER BRACKET	Not Necessary	380.00 FL	*- FL
23	1		*REAR SPARE TYRE HOLDER BOLT	Not Necessary	60.00 FL	*- FL
24	1		*REAR NUMBER PLATE	Bent	50.00 FS	*30.00 FS
25	1		*REAR BUMPER SLIP (SET)	Necessary	80.00 FS	*30.00 FS
26	1		*REAR STEP PANEL SEALANT	Not Necessary	150.00 FS	*- FS
27	1		*TAIL LAMP SLIP (SET)	Necessary	40.00 FS	*10.00 FS
28	1		*TAILLAMP LOWER GARNISH CLIP (SET)	Not Necessary	60.00 FS	*- FS
29	1		*TAILGATE SEALANT	Not Necessary	150.00 FS	*- FS
30	1		*TAILGATE OUTER MOULDING CLIP (SET)	Not Necessary	50.00 FS	*- FS
31	1		*TAILGATE INNER TRIM CLIP (SET)	Not Necessary	50.00 FS	*- FS
32	1		*TAILGATE STICKER 70KM/H	Necessary	40.00 FS	*15.00 FS
33	1		*TAILGATE STICKER 80/90	Necessary	60.00 FS	*25.00 FS
34	1		*TAILGATE STICKER BUDAK JURONG	Necessary	80.00 FS	*20.00 FS
35	1		*TAILGATE COMPANY STICKER	Necessary	1,200.00 FS	*450.00 FS
36	1		*TAILGATE STICKER TRUCKWERKZE (INNER)	Necessary	80.00 FS	*20.00 FS
37	1		*TAILGATE WINDSCREEN SEALANT	Necessary	80.00 FS	*40.00 FS
38	1		*TAILGATE WINDSCREEN INNER SEAL	Necessary	60.00 FS	*40.00 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
39	1		*REAR END PANEL (INNER) SEALANT	Not Necessary	150.00 FS	*- FS
40	1		*REAR END PANEL (OUTER) SEALANT	Necessary	150.00 FS	*60.00 FS
41	1		*REAR FLOOR PANEL SEALANT	Not Necessary	150.00 FS	*- FS
42	1		*REAR FLOOR TOP BOARD (WOODEN)(SPECIAL TYPE)	Not Necessary	850.00 FS	*- FS
43	1		*REAR FLOOR CARPET (SPECIAL TYPE)	Not Necessary	680.00 FS	*- FS
44	1		*REVERSE CAMERA	Not Necessary	550.00 FS	*- FS
45	1		*REVERSE SENSOR	Damaged	220.00 FS	*200.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (\$\$)					17,005.00	5,907.00
- List Item Discount on L Items 25.00/25.00% (\$\$)					3,006.25	1,241.75
Total Parts (\$\$)					13,998.75	4,665.25

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING AND REPLACE PARTS	New	1,800.00	800.00
2	SPRAY PAINTING TO AFFECTED AREA	New	1,800.00	800.00
3	WIRING, BULB CHECKING	New	180.00	30.00
4	TRANSFER TAILGATE MECHAISM	New	80.00	80.00
5	CONDUCT WATER LEAKAGE TEST	New	120.00	0.00
6	REAR CHASSIS ALIGNMENT	New	250.00	0.00
7	REMOVE AND REFIX REAR REVERSE SENSOR	New	80.00	50.00
8	REMOVE AND REFIX REAR REVERSE CAMERA	New	80.00	50.00
9	REMOVE AND REFIX VIDEO RECORDER	New	80.00	60.00
10	REMOVE AND REFIX REAR REVERSE CAMERA	New	80.00	0.00
11	REMOVE AND REFIX FUEL TANK	New	0.00	0.00
12	REMOVE AND REFIX REAR WINDSCREEN	New	120.00	120.00
13	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	New	180.00	0.00
Gross Labour Cost (\$\$)			4,850.00	1,990.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >