

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III19022458/APS3Q2

Date: 09/11/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : GBA1197E	Insured Vehicle No :	SHC8952P
Date of Loss: 10/12/2019	Nature of Claim: TP	Claim No: MCT19120382

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBA1197E		
Make & Model:	TOYOTA HIACE, 2.0 (M)	Engine No:	1KD1577352
Reg. Date:	23/02/2007 (Man. Year: 2007)	Chassis No:	JTFHT02P900002146
Colour:	Silver	Odometer:	545143 km
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195 R15C	Rear Tyre Size:	195 R15C
Front Left Side:	Compasal 6 mm	Rear Left Side:	Firestone 6 mm
Front Right Side:	Compasal 6 mm	Rear Right Side:	Firestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,620.75	1,860.50	2,760.25	59.74
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,340.00	1,190.00	1,150.00	49.15
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,960.75	3,050.50	3,910.25	56.18
Approved Total (Overridden) (S\$)		2,400.00		
(S\$)	6,960.75	2,400.00	4,560.75	65.52
+ GST 7.00/7.00% (S\$)	487.25	168.00	319.25	65.52
Nett Amount (S\$)	7,448.00	2,568.00	4,880.00	65.52
+ Car Rental (4.0 x S\$120.00/day + 7.00% GST) (S\$)		513.60		
+ Doc/Search Fee (S\$)		29.00		
Nett Liability (S\$)		3,110.60		
Global Sum Settlement (S\$)		3,100.00		

INSPECTION

Date of Assignment:	18/12/2019	
Date Inspected:	03/01/2020 Inspected At:	N-51 Automotive Pte Ltd (HQ) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB Singapore 417921

Estimated Period of Repair: 4.0 days

Adjuster: ADRIAN LING

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 07 Jun 2020)	
Parts:	N/A	TOYOTA HIACE 2.0 (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBA1197E)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Deformed	396.00 FL	*396.00 FL
2	4		*REAR BUMPER LOWER BRACKET	Not Necessary	192.00 FL	*- FL
3	1		*REAR BUMPER SIDE RETAINER L/R	N/S Necessary	94.00 FL	*47.00 FL
4	1		*REAR END PANEL (OUTER)	Repair	743.00 FL	*- FL
5	1		*REAR LH FENDER	Dented	1,850.00 FL	*1,452.00 FL
6	1		*REAR LH FENDER AIR VENT	Deformed	97.00 FL	*97.00 FL
7	1		*REAR LH FENDER INNER PANEL	Repair	977.00 FL	*- FL
8	2		*REAR LH FENDER INNER VERTICAL BRACKET	Not Necessary	158.00 FL	*- FL
9	1		*REAR LH TAILLAMP	Cut	265.00 FL	*265.00 FL
10	1		*REAR LH TAILLAMP INNER PANEL	Repair	525.00 FL	*- FL
11	1		*REAR LH TAILLAMP LOWER GARNISH	Cracked	157.00 FL	*157.00 FL
12	1		*REAR LH TAILLAMP LOWER GARNISH RETAINER	Not Necessary	53.00 FL	*- FL
13	1		*REAR TAILGATE LOGO EMBLEM	Not Necessary	63.00 FL	*- FL
14	1		*REAR TAILGATE WEATHERSTRIP	Not Necessary	391.00 FL	*- FL
15	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
16	1		*SET REAR LH TAILLAMP CLIPS	Necessary	25.00 FS	*10.00 FS
17	1		*SET REAR LH TAILLAMP LOWER GARNISH CLIPS	Necessary	20.00 FS	*10.00 FS
18	1		*REAR TAILGATE 70KM STICKER	Not Necessary	25.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	6,111.00	2,464.00
- List Item Discount on L Items 25.00/25.00% (\$\$)	1,490.25	603.50
Total Parts (\$\$)	4,620.75	1,860.50

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE,REINSTALL ELECTRICAL WIRING HARNESS ,CHECK LIGHTING AND REWIRE FOR PARKING SENSOR	New	80.00	80.00
2	TO REMOVE,REINSTALL ROOF TOP TRIM UPHOLSTERY CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR)	New	140.00	50.00
3	TO RE-SPRAY PAINTING ON THE CHARGE BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
4	TO PROVIDE LABOUR ,WORKMANSHIP TO CHARGE THE ABOVE DAMAGED BODYPARTS ,REPAIR ,RECONSTRUCT AND REALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	New	1,000.00	500.00
5	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL	New	120.00	60.00
Gross Labour Cost (\$\$)			2,340.00	1,190.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >