

CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE



209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

Co Reg No : 199405410K

ESTIMATE

GST Reg No : MR-8500111-X

	Invoice Name & Address	d on the second	Owner Name & Vehicle Info
*,	LIM KOK KHENG	Cust No/Name	LCV11056/LIM KOK KHENG
		Reg No/Reg Date	SMP1393X*ECB1/ 05/09/201
٠,	49 SWISS VIEW	Date In/Mileage	/ 0
$\hat{z}_{\mathbf{c}_{\xi}}$	ANNO LOCATE ACCOUNTS	Chassis No	KNAF5416MK5050393
-	SINGAPORE 288055	Engine No	G4FGKH745313
٠	Contact No	Make/Model	KIA/CERATO 1.6 A GT LINE H171
		Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

count No Terms Date/Time Printed CSE Operator		WIP No		
LCV11056 CRDVCH 16/12/2019/ 10:18 BLC 442 / CocoLu		63534		
Description of Goods / Services	Qty L	Init Price	Disc%	Amount
; PNT88000				1100.00
RENEW REAR BUMPER, REPAIR BOOTLID				60.00
I PNT88000 REMOVE & INSTALL PARKING SENSOR				00.00
PNT98000				1260.00
SPRAY PAINT FOR REAR BUMNPER, BOOTLID				
© 90000001			ŀ	30.00
CHECK WIRING & ELECTRICAL SYSTEM 10028901				200.00
* TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST				200.00
	r i		1	
SUNDRY GIFTESO SO	17/2			40.00
USING HI-SCAN PRO TEST SUNDRY C&C LOGO T SUNDRY				20.00
Sundry	Marine Ma			20.00
SUNDRY				360.00
PARKING SENSOR				500.00
COVER-RR BUMPER COVER-RR BUMPER LWR	1.00 1.00	688.00 197.00		688.00 197.00
OVER-RR BUMPER FOG LAMP, RH	1.00		00.00	19.00
LAMP ASSY-SIDE T/SIGNAL,RH	1.00	181.00		181.00
BRACKET-ASSY RR BPR SIDE UPR,R	1.00		00.00	31.00
EMBLEM-GT LINE	1.00		00.00	45.00
LAMP ASSY-REAR COMB INSIDE,RH	1.00	608.00 675.00		608.00
EMME NOOT-KEAK COMP OOTSIDE,KU	1.00	0/5.00	00.00	675.00
			1	
No.				
**Constitute 0table.				
Confirm & accepted by				
; **	-à -a	Ne		5,514.00
as a second of the second of t	7% GST on	5514.	00	385.98
	Tot	al Payab	l e	5,899.98
Authorized signatory and company stamp		•		-
alidity of this estimate is 14 days from date of quote. This is a computer generated				•

alidity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Stimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include my additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered fter work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a eposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or heque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.