Adjuster Report Page 1 of 4

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD19022465/APA3Q2

Date: 13/01/2021

REFERENCE

Handling Insurer: FWD Singapore Pte. Ltd. Policy No: PNPV2019-00006462

Claimant Vehicle No:

SLE9395H Insured Vehicle No: SLZ4465L

ΤP Date of Loss: Nature of Claim: 18/12/2019 Claim No: 1201900040684

DESCRIPTION & IDENTIFICATION OF VEHICLE

SLE9395H Reg No:

Make & Model: HONDA CIVIC, 1.8 (A) Engine No: R18A13042693 Reg. Date: 16/03/2009 (Man. Year: 2008) Chassis No: JHMFD16808S219871 Odometer: 131956 km

Colour: Silver

Engine Capacity: Market Value/New Car

N/A

Price:

Sum Insured (S\$): Market Value/New Car Price

1799 cc

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Yes Footbrake (Serviceable): Steering (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16 Front Left Side: Rear Left Side: Bridgestone 6 mm Bridgestone 6 mm Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		6,152.12	2,730.16	3,421.96	55.62
Miscellaneous Items		0.00	0.00	0.00	
Labour		2,740.00	1,850.00	890.00	32.48
Paintwork Labour		0.00	0.00	0.00	
Towing		0.00	0.00	0.00	
Calculated Gross To	tal (S\$)	8,892.12	4,580.16	4,311.96	48.49
Approved Total (Overridde	en) (S\$)		3,600.00		
	(S\$)	8,892.12	3,600.00	5,292.12	59.51
+ GST 7.00/7.00	0% (S\$)	622.45	252.00	370.45	59.51
Nett Amou	unt (S\$)	9,514.57	3,852.00	5,662.57	59.51
+ Car Rental (6.0 x S\$100.	.00/day + 7.	00% GST) (S\$)	642.00		
	+ Doc/S	earch Fee (S\$)	7.45		
	+ Ot	her Costs (S\$)	100.00		
	Ne	tt Liability (S\$)	4,601.45		

INSPECTION

Date of Assignment: 19/12/2019

Date Inspected: 19/12/2019 Inspected At: Twincar Automotive Pte Ltd - Kaki

Bukit (HQ)

2 KAKI BÜKIT AVENUE 2, #01-17

KAKI BUKIT AUTOHUB Singapore 417921

Adjuster Report Page 2 of 4

Estimated Period of Repair: 6.0 days

Adjuster: ADRIAN LING Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Nov 2020)

Parts: 143 HONDA CIVIC 1.8 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SLE9395H)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page

numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No	. Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Dented	610.70 FL	*610.70 FL
2	1		*REAR BOOTLID CIVIC EMBLEM	Necessary	29.00 FL	*29.00 FL
3	1		*REAR BOOTLID LOGO EMBLEM	Necessary	76.90 FL	*76.90 FL
4	2		*REAR BOOTLID HINGES L/R	Not Necessary	97.20 FL	*- FL
5	2		*REAR BOOTLID INNER RUBBER STOPPER L/R	Not Necessary	21.00 FL	*- FL
6	1		*REAR BOOTLID INNER TRIM BOARD	Not Necessary	331.00 FL	*- FL
7	1		*REAR BOOTLID MECHANISM LOCK	Damaged	194.50 FL	*194.50 FL
8	2		*REAR BOOTLID REFLECTOR BLACK GASKET L/R	Not Necessary	29.80 FL	*- FL
9	2		*REAR BOOTLID REFLECTOR L/R	Not Necessary	366.00 FL	*- FL
10	1		*REAR BOOTLID WEATHER STRIP	Cut	97.20 FL	*97.20 FL
11	2		*REAR BUMPER SIDE RETANER L/R	Necessary	29.20 FL	*29.20 FL
12	1		*REAR END PANEL	Dented	989.00 FL	*308.00 FL
13	1		*REAR END PANEL INNER TOP GARNISH	Deformed	159.00 FL	*159.00 FL
14	1		*REAR EXHAUST GASKET	Not Necessary	31.60 FL	*- FL
15	2		*REAR EXHAUST RUBBER MOUNTING	Not Necessary	30.00 FL	*- FL
16	1		*REAR EXHAUST SILENCER BOX	Not Necessary	535.00 FL	*- FL
17	2		*REAR FENDER INNER TRIM BOARD L/R	Not Necessary	598.60 FL	*- FL
18	2		*REAR TAILLAMP INNER RUBBER GASKET L/R	Necessary	30.00 FL	*30.00 FL
19	2		*REAR TAILLAMP L/R	Cracked	617.40 FL	*617.40 FL
20	2		*REAR TAILLAMP LOWER BRACKET L/R	Bent	27.80 FL	*27.80 FL
21	1		*SPARE TYRE PANEL TOP COVER	Deformed	308.00 FL	*308.00 FL
22	1		*SET REAR BOOTLID INNER TRIM BOARD CLIPS	Not Necessary	80.00 FS	*- FS
23	1		*REAR BOOTLID NUMBER PLATE	Not Necessary	25.00 FS	*-FS
24	1		*REAR BOOTLID NUMBER PLATE HOLDER	Not Necessary	•	
25	1		*REAR BUMPER	Deformed	1,200.00 FS	*480.00 FS
26	1		*SET REAR BUMPER CLIPS	Necessary	80.00 FS	*30.00 FS
27	1		*SET REAR BUMPER REVERSE SENSOR	Damaged	350.00 FS	*200.00 FS
28	1		*SET REAR END PANEL INNER TOP GARNISH CLIPS	•	50.00 FS	*10.00 FS
29	2		*SET REAR FENDER INNER TRIM BOARD CLIPS L/R	Not Necessary	100.00 FS	*- FS
30	2		*SET REAR TAILLAMP CLIPS L/R	Necessary	50.00 FS	
F=Fra	anchise	part. S=Sp	cNett. L=ListItemDisc.			
				Sub Total (S\$)	7,193.90	3,227.70

 Sub Total (S\$)
 7,193.90
 3,227.70

 - List Item Discount on L Items 20.00/20.00% (S\$)
 1,041.78
 497.54

Condition

Total Parts (S\$) 6,152.12 2,730.16

Report was unsubmitted during this print-out.

Adjuster Report Page 4 of 4

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

OUTER HANDLE REFLECTOR 2 TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS New 100.00 7 CHECK LIGHTING AND REWIRE FOR PARKING SENSOR 3 TO REMOVE, REINSTALL ROOF TOP TRIM New 140.00 6 UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR) 4 TO RE-SPRAY PAINTING ON THE CHANGE New 1,200.00 80 BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT 5 TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT 6 TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE New 1,000.00 80 ABOVE DAMAGED BODYPARTS, REPAIR, RE-	No	Particulars	Lab.Type	Repairer's	Amount
OUTER HANDLE REFLECTOR 2 TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS New 100.00 7 CHECK LIGHTING AND REWIRE FOR PARKING SENSOR 3 TO REMOVE, REINSTALL ROOF TOP TRIM New 140.00 6 UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR) 4 TO RE-SPRAY PAINTING ON THE CHANGE New 1,200.00 80 BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT 5 TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT 6 TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE New 1,000.00 80 ABOVE DAMAGED BODYPARTS, REPAIR, RE-	Lab	pour Items			
CHECK LIGHTING AND REWIRE FOR PARKING SENSOR 3 TO REMOVE, REINSTALL ROOF TOP TRIM New 140.00 6 UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM LINER CARPET (TO FR) 4 TO RE-SPRAY PAINTING ON THE CHANGE New 1,200.00 80 BODYPARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT 5 TO REMOVE AND CHANGE EXHAUST SILENCER BOX WITH PIPE, RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT 6 TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE New 1,000.00 80 ABOVE DAMAGED BODYPARTS, REPAIR, RE-	1		New	80.00	60.00
UPHOLSTERY ,CUSHION SEAT ,TRIM GARNISH ,TRIM LINER CARPET (TO FR) 4 TO RE-SPRAY PAINTING ON THE CHANGE New 1,200.00 80 BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT 5 TO REMOVE AND CHANGE EXHAUST SILENCER BOX New 100.00 WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT 6 TO PROVIDE LABOUR ,WORKMANSHIP TO CHANGE THE New 1,000.00 80 ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-	2		New	100.00	70.00
BODYPARTS ,REPAIR PORTION ,AND WHERE CONSISTENT TO THE ACCIDENT 5 TO REMOVE AND CHANGE EXHAUST SILENCER BOX New 100.00 WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT 6 TO PROVIDE LABOUR ,WORKMANSHIP TO CHANGE THE New 1,000.00 80 ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-	3	UPHOLSTERY, CUSHION SEAT, TRIM GARNISH, TRIM	New	140.00	60.00
WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT TO THE ACCIDENT 6 TO PROVIDE LABOUR ,WORKMANSHIP TO CHANGE THE New 1,000.00 80 ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-	4	BODYPARTS ,REPAIR PORTION ,AND WHERE	New	1,200.00	800.00
ABOVE DAMAGED BODYPARTS ,REPAIR ,RE-	5	WITH PIPE ,RE-ALIGN WHERE NECESSARY CONSISTENT		100.00	0.00
ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	6	ABOVE DAMAGED BODYPARTS ,REPAIR ,RE- CONSTRUCT AND RE-ALIGN BODY STRUCTURE BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE	New	1,000.00	800.00
7 TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND New 120.00 6 REPLACED PANEL	7		New	120.00	60.00
Gross Labour Cost (S\$) 2,740.00 1,85		Gross Labour Cost (S\$)		2,740.00	1,850.00
Report was unsubmitted during this print-out.		Report was unsubmitted durin	g this print-out.		

< END OF ESTIMATES >