



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 1927X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	LHS FRONT FENDER (CONSISTENT)	BENT	980.00	558.00
1	LHS FRONT FENDER WHEEL ARCH GARNISH (CONSISTENT)	SCRATCHED	283.00	220.00
1	LHS FRONT FENDER INNER SPLASH SHIELD (CONSISTENT)	SERVICEABLE	267.00	-
1	LHS FRONT FENDER HYBRID EMBLEM PLATE (CONSISTENT)	NECESSARY	112.00	68.00
1	FRONT BUMPER (CONSISTENT)	CRACKED	1,428.00	850.00
1	FRONT BUMPER FOG LAMP COVER LHS (CONSISTENT)	SERVICEABLE	244.00	-
1	FRONT BUMPER FOG LAMP LHS (CONSISTENT)	SERVICEABLE	428.00	-
1	FRONT BUMPER LOWER SKIRT LHS (CONSISTENT)	SCRATCHED	780.00	400.00
2	FRONT BUMPER SIDE RETAINERS (CONSISTENT)	N/S NECESSARY	142.00	71.00
1	LHS HEADLAMP (CONSISTENT)	SCRATCHED	1,280.00	1,280.00
1	LHS HEADLAMP LOWER BRACKET (CONSISTENT)	CRUMPLED	248.00	70.00
1	LHS FRONT SHOCK ABSORBER (CONSISTENT)	SERVICEABLE	592.00	-
1	LHS FRONT SHOCK ABSORBER COIL SPRING (CONSISTENT)	SERVICEABLE	209.00	-
1	LHS FRONT LOWER ARM (CONSISTENT)	SERVICEABLE	488.00	-
1	LHS FRONT TIE ROD (CONSISTENT)	SERVICEABLE	278.00	-
1	LHS FRONT KNUCKLE ARM (CONSISTENT)	SERVICEABLE	498.00	-
1	LHS FRONT WHEEL BEARING (CONSISTENT)	CRUMPLED	279.00	181.00
	LESS 20% DISCOUNT		-1,707.20	-739.60
			6,828.80	2,958.40
<b><u>SPECIAL NETT ITEMS</u></b>				
1	SET LHS FRONT FENDER INNER SHIELD CLIPS (SN) (CONSISTENT)	NECESSARY	50.00	20.00
1	SET FRONT BUMPER CLIPS (SN)(CONSISTENT)	NECESSARY	60.00	25.00
1	SET FRONT FENDER WHEEL ARCH LH CLIPS (SN) (CONSISTENT)	NECESSARY	60.00	20.00
1	LHS FRONT SPORTS RIM (SN)(CONSISTENT)	SCRATCHED	980.00	450.00
			1,150.00	515.00



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b>LABOUR</b>			
	TO REMOVE THE AFFECTED PARTS & FITTINGS TO COMMENCE REPAIRS;REPLACE DAMAGED PARTS AND COMPONENTS.		1,000.00	500.00
	TO SUPPLY PAINT MATERIALS,EXPANDLE ITEMS & PUTTY,RESPRAY PAINT ON PARTS REPLACED.		600.00	600.00
	TO CHECK WIRING AND FOCUS HEADLAMP BEAM.		150.00	30.00
	TO REMOVE AND REPLACE LHS FRONT UNDERCARRIAGE PARTS (SUSPENSION SYSTEM).		300.00	80.00
	TO CARRY OUT ANTI RUST TREATMENT ON AFFECTED AREAS.		150.00	30.00
	TO CONDUCT FULL COMPUTERISED WHEEL ALIGNMENT TEST.		120.00	60.00
			2,320.00	1,300.00
	<b>GRAND TOTAL</b>		<b>10,298.80</b>	<b>4,773.40</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>3,750.00</b>

Report Ref No. CC4/ASM19022472/Hps3q2

LEE HOCK ANN

Asst. Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.