



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS FIRST CAPITAL INSURANCE LTD

Ref : CC4/FCI19022484/Uha3q2

36 ROBINSON ROAD
#16-01 CITY HOUSESINGAPORE 068877

Date : 08-05-2020



Code : FCI2

1. Policy Particulars :- THIRD PARTY CLAIM

| | | | |
|---------------------|----------------|-----------------------|------------|
| Insured Veh. | SHB 4980P | Veh. Inspected | SJY 6361T |
| Policy No. | D-18088937MFSH | Coverage (\$) | 0.00 |
| Claim No. | D19007901MFSH | Excess (\$) | 0.00 |
| Assign From | RACHEL WU | Assign Date | 06/01/2020 |

2. Vehicle Particulars & Condition

| | | | |
|-------------------------|-------------------|---------------------|------------|
| Make & Model | TOYOTA WISH (A) | c.c | 1987 |
| Engine No. | HIDDEN | Year of Reg. | 2010 |
| Chassis No. | JTDGJ20W305003246 | Colour | BROWN |
| Odometer | 27752 | Steering | IN ORDER |
| Brakes | IN ORDER | Modification | SPORTS RIM |
| General | GOOD | | |

3. Conditions of Tyres

| | | | |
|-----------------------|-------------|-------------|----------------|
| | Size | Make | Balance |
| R/H Front Tyre | 195/65 R15 | MICHELIN | 6 mm |
| L/H Front Tyre | 195/65 R15 | MICHELIN | 6 mm |
| R/H Rear Tyre | 195/65 R15 | MICHELIN | 6 mm |
| L/H Rear Tyre | 195/65 R15 | MICHELIN | 6 mm |

4. Description of Damages

| |
|--|
| THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS. |
|--|

5. General Information

| | | | |
|-----------------------|--|------------------------|------------|
| Accident Date | 13/12/2019 | Inspection Date | 06/01/2020 |
| Survey held at | PROGRESSIVE CAR CARE PTE LTD BLK 3022A UBI ROAD 1 #01-45/46, SINGAPORE 048716 | | |

5a. Remarks

| |
|--|
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |
|--|

5b. Estimate Days of Repair

| | |
|-------------------------------------|-----------------------|
| ESTIMATED NORMAL PERIOD FOR REPAIR: | 5 Working Days |
|-------------------------------------|-----------------------|