



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLD 319T

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	TAILGATE	BENT	1,050.00	1,050.00
1	REAR BUMPER	DEFORMED	518.60	518.60
1	FRONT BONNET	BENT	892.35	892.35
1	FRONT GRILLE BASE	CRACKED	268.90	268.90
1	OUTER GARNISH	NOT NECESSARY	203.40	-
2	CHROME @\$45.60	NOT NECESSARY	91.20	-
1	FRONT BUMPER	DEFORMED	459.80	459.80
1	FRONT HONDA EMBLEM	NECESSARY	95.50	95.50
1	REAR HONDA EMBLEM	NOT NECESSARY	95.50	-
1	VEZEL EMBLEM	NECESSARY	55.50	55.50
1	HEAD LAMP BRACKET LHS (ADDITIONAL)	CRACKED	49.00	49.00
1	HEAD LAMP BRACKET RHS (ADDITIONAL)	CRACKED	49.00	49.00
1	CENTER LOCK COVER BRACKET (ADDITIONAL)	CRACKED	119.56	119.56
1	REAR BUZZER (ADDITIONAL)	CRACKED	120.12	120.12
1	REAR TOOL KIT HOLDER FORM-BLACK (ADDITIONAL)	DEFORMED	294.97	294.97
1	END PANEL (ADDITIONAL)	BENT	535.47	535.47
			4,898.87	4,508.77
<b><u>SPECIAL NETT ITEMS</u></b>				
1	REVERSE SENSOR ASSY (SN)	DISTORTED	280.00	220.00
1	FRONT NUMBER PLATE (SN)	CRACKED	25.00	25.00
1	SEALANT (SN)	NECESSARY	40.00	40.00
1	SUNDRIES (SN)	NECESSARY	100.00	30.00
			445.00	315.00
<b><u>LABOUR</u></b>				
	TO CARRY OUT PANEL BEAT TO STRAIGHTERN CRAMBLED PANELS IN SPARE TYRE COMPARTMENT. (ADDITIONAL).		800.00	400.00
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC. (ADDITIONAL).		400.00	400.00
	TO APPLY SEALANT ONTO SPARE TYRE COMPARTMENT (NPA).(ADDITIONAL).		-	-



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY,CLEAN,SPRAY PAINT AND POLISH,ETC.		680.00	600.00
	TO REMOVE AND REFIX DAMAGED PARTS,CUT,WELD,PANEL BEAT,STRAIGHTEN & REALIGN,ETC.		880.00	800.00
	TO REMOVE AND REFIX FRONT WINDSCREEN PLUS GUM.		180.00	120.00
			2,940.00	2,320.00
<b>GRAND TOTAL</b>			<b>8,283.87</b>	<b>7,143.77</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>5,700.00</b>

Report Ref No. CC4/FCI19022486/R1ha3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.