

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 6289P

DATE : 16.12.2019

MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

PCI

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt <i>turn</i>			\$ 1,890.50
	Bumper Reinforcement, Frt <i>bt</i>			\$ 1,158.00
	Bumper Bracket, Frt/LH <i>bt</i>			\$ 95.00
	Bumper Frame, Frt/Centre <i>HH</i>			\$ 389.00
	Bumper Frame, Frt/LH <i>broken</i>			\$ 75.00
	Bumper Sponge, Frt/Centre <i>broken</i>			\$ 285.00
	Bumper Sponge, Frt/LH <i>turn</i>			\$ 250.00
	Bumper Sponge Extension, Frt/LH/RH <i>HH</i>			\$ 105.00
	Bumper Grille, Frt/Centre <i>HH</i>			\$ 290.50
	Bumper Grille, Frt/LH <i>HH</i>			\$ 240.50
	Bumper Inner Clip, Frt <i>Nec</i>			\$ 22.00
	Daylight (LH) <i>HH</i>			\$ 498.00
	Daylight Chrome Cover (LH) <i>HH</i>			\$ 250.00
	Head Lamp Assy (LH/RH) <i>HH broken / mostly crack</i>	\$	2,380.00	\$ 4,760.00
	Head Lamp Bracket (LH) <i>Dented</i>			\$ 300.00
	Radiator Top Panel, Frt <i>Dented</i>			\$ 330.50
	Head Lamp Panel (LH) <i>Dented</i>			\$ 480.00
	Radiator Grille <i>broken</i>			\$ 1,220.00
	Radiator Grille Star Logo <i>Nec</i>			\$ 170.00
	Radiator Grille Adjuster Bracket <i>broken</i>			\$ 685.70
	Bonnet Assy <i>Dented</i>			\$ 2,850.60
	Bonnet Mercedes Star Logo <i>bt</i>			\$ 112.00
	Bonnet Hinge (LH) <i>HH</i>			\$ 285.50
	Bonnet Shock Absorber <i>HH</i>			\$ 295.40
	Bonnet Insulator <i>HH</i>			\$ 235.40
	Bonnet Centre Lock <i>bt</i>			\$ 95.00
	Bonnet Lock, Top <i>HH</i>			\$ 94.00
	Bonnet Lock Lower (2 pcs) <i>Dented</i>	\$	92.00	\$ 184.00
	Bonnet Lock Brace Panel <i>bt</i>			\$ 64.80
	Bonnet Air Inlet Grille <i>broken</i>			\$ 269.25
	Fender, Frt/LH <i>turn</i>			\$ 996.08
	Fender Splashshield, Frt/LH (Front) <i>Scratch / turn / dented</i>			\$ 257.00
	Fender Splashshield, Frt/LH (Rear) <i>HH</i>			\$ 263.00
	Horn (Woofer) (LH) <i>HH</i>			\$ 228.00
	Radiator Assy <i>bt</i>			\$ 1,345.00
	Radiator Fan Blower Assy <i>Crack / Dented</i>			\$ 1,385.40
	Radiator Shroud <i>Crack</i>			\$ 1,225.60
	Radiator Air Baffle, Top <i>broken</i>			\$ 80.00
	Radiator Air Baffle, Lower <i>HH</i>			\$ 125.90
	Radiator Mounting Lower <i>HH</i>			\$ 8.00
	Radiator Mounting Top-2 pcs <i>HH</i>	\$	19.00	\$ 38.00
	Aircon Condenser <i>bt</i>			\$ 1,235.80
	Aircon Discharge Hose/Pipe <i>bt</i>			\$ 372.55
	Turbo Charger Air Cooler <i>mostly broken</i>			\$ 1,053.80
	Turbo Charger Cooler Hose, LH <i>HH</i>			\$ 156.80
	Turbo Charger Cooler Hose, Top <i>HH</i>			\$ 92.50

SHB 6289P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	P/Steering Cooling Pipe <i>1st</i>			\$ 556.80	✓
	ABS Hydraulic Brake Pump <i>Carrotte replaced</i>			\$ 4,980.00	✓ X
	SUB TOTAL			\$ 32,380.88	
	LESS 10%			\$ 3,238.09	
	DISCOUNTED TOTAL			\$ 29,142.79	
	Head Lamp Bulb <i>NH</i>			\$ 25.00	Nett X
	Labour Charge				
	Panel Beating			\$ 1,200.00	1000/-
	Spray Painting Charge			\$ 900.00	700/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charges			\$ 50.00	NH
	Tuff Kote			\$ 50.00	30/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	Re-set and Diagnosis			\$ 550.00	320/-
	TOTAL LABOUR			\$ 2,950.00	
	Boot Lid <i>1st</i>			\$ 2,470.00	✓
	Boot Lid Lamp (LH/RH) <i>1st mainly crack</i>	\$	655.00	\$ 1,310.00	✓
	Boot Lid Rubber <i>SVC</i>			\$ 170.00	X
	Boot Lid Moulding <i>NH</i>			\$ 110.00	X
	Boot Lid Lock <i>NH</i>			\$ 275.00	X
	Boot Lid Lock Lower Catch <i>NH</i>			\$ 35.00	X
	Boot Lid Lock Sticker <i>NH</i>			\$ 90.00	X
	Boot Lid 'E220' Emblem <i>NH</i>			\$ 54.30	✓
	Boot Lid Star Logo <i>NH</i>			\$ 45.00	✓
	Boot Lid 'CDI' Emblem <i>NH</i>			\$ 54.30	✓
	Rear Bumper <i>distorted</i>			\$ 1,510.00	✓
	Rear Bumper Reinforcement <i>1st</i>			\$ 1,150.00	✓
	Rear Bumper Bracket Lower (LH/RH) <i>NH</i>	\$	135.00	\$ 270.00	X
	Rear Bumper Bracket Top (LH/RH) <i>NH</i>	\$	125.00	\$ 250.00	X
	Rear Bumper Retainer Mounting (LH/RH) <i>NH</i>	\$	115.00	\$ 230.00	X
	Taillamp (LH/RH) <i>1st mainly crack</i>	\$	1,280.00	\$ 2,560.00	✓
	Rear Panel End <i>2 Distorted</i>			\$ 1,380.00	✓
	Rear Panel Inner Garnish <i>NH</i>			\$ 240.00	X
	Rear Panel Inner Garnish Clip (10pcs) <i>NH</i>			\$ 40.00	X
	Spare Tyre Panel <i>broken Distorted</i>			\$ 1,280.00	✓
	Spare Wheel Lower Garnish <i>NH</i>			\$ 361.20	X
	Spare Tyre Panel Cushion Cover <i>NH</i>			\$ 365.00	X
	Rear Exhaust Pipe Insulator <i>NH</i>			\$ 46.00	X
	Rear Exhaust Silencer <i>2 1st</i>			\$ 1,890.00	✓
	Rear Exhaust '8' Shape Ring (1pc only) <i>NH</i>			\$ 16.00	X
	Rear Exhaust Mounting <i>NH</i>			\$ 21.85	X
	SUB TOTAL			\$ 16,223.65	
	LESS 10%			\$ 1,622.37	
	DISCOUNTED TOTAL			\$ 14,601.29	

SHB 6289P

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper Sensor <i>DM</i>			\$ 388.00	Nett ✓
	Labour Charge				
	Panel Beating			\$ 1,500.00	700/-
	Spray Painting Charge			\$ 1,200.00	600/-
	Wiring Charge			\$ 50.00	30/-
	Tuff Kote			\$ 50.00	20/-
	Remove/Refix Reverse Sensor			\$ 120.00	40/-
	Remove/Refix Exhaust Pipe			\$ 150.00	60/-
	TOTAL LABOUR			\$ 3,070.00	
	ESTIMATE TOTAL			\$ 50,177.08	
19/12/2019 @ 1000m Not Antimal 2/Smw 12 days. <i>J nyan</i> 2KK Auto <i>Provide BV</i>					
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

CHUNNI MOTOR WORK PTE LTD**REPAIR ESTIMATE***

VEHICLE NO : SHB 6289P (Supplementary)


DATE : 19.12.2019

MAKE :

TEL : 6542 5119

MODEL : MERCEDES

FAX : 6542 6039

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	ABS Hydraulic Brake Pump <i>check</i>			\$ 8,400.00
	Front Bumper Reinforcement Absorber, LH <i>1st</i>			\$ 295.00
	Bonnet Lock Lower Sensor, LH <i>dislodged / Dam</i>			\$ 285.50
	Power Steering Pump Assy <i>broken</i>			\$ 1,950.00
	Power Steering Oil - 2 Bottle <i>HN</i>		\$ 68.00	\$ 136.00
	Fan Belt <i>torn</i>			\$ 188.00
	Head Lamp Panel "L" Bracket (LH) <i>1st</i>			\$ 128.00
	Head Lamp Panel "S" Bracket (LH) <i>1st</i>			\$ 138.00
	Radiator Hose, LH <i>defunct / torn</i>			\$ 368.00
	Wiper Spare Tank <i>defunct / torn</i>			\$ 288.00
	Rear Bumper Lower Cover <i>defunct</i>			\$ 325.00
	Spare Tyre Lock Nut Wheel <i>broken</i>			\$ 108.00
	Bonnet Stopper Spring <i>Dam / dislodged</i>		\$ 385.00	\$ 770.00
	Radiator Mounting Top Clip <i>new</i>		\$ 15.00	\$ 30.00
SUB TOTAL				\$ 13,409.50
LESS 10%				\$ 1,340.95
DISCOUNTED TOTAL				\$ 12,068.55
 <i>2kk Auto</i> 				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				